

ZZZ ■ These assemblies must be clean and free from flux and all contaminants. Use of no clean flux is not acceptable.

ZZ3 ■ These assemblies must comply with workmanship standards IPC-A-610 Class 2., unless otherwise specified.



COMPONENTS MARKED 'DNP' SHOULD NOT BE POPULATED. ASSEMBLY VARIANT: 001

PCB VIEWED FROM TOP SIDE	BOARD #: PWR612	REV: A	SUN REV	: Not In VersionControl
IGNORE -> Top Overlay				
PLOT NAME = Top Assembly Drawing	GENERATED : 2/7/20	014 2:19:18	PM	TEXAS INSTRUMENTS



COMPONENTS MARKED 'DNP' SHOULD NOT BE POPULATED. ASSEMBLY VARIANT: 001

PCB VIEWED FROM BOTTOM SIDE	BOARD #: PWR612	REV: A	SVN REV: Not In VersionControl	
	Bottom Overlay <- JACONDI			
PLOT NAME = Bottom Assembly Drawing	GENERATED : 2/7/20	014 2:19:20	PM	TEXAS INSTRUMENTS