



To-Do List (PlanckOff)

- ☒ Setup Github repo for the project
- ☒ Ask for the creds for new email
- ☒ Start Vercel and Supabase instance
- ☒ Making things modular in the current project, make the folder structure better and super modular
- ☒ Make Components Modular, lot of components have more than 800-900 lines of code which is not good.
- ☒ Start with Authentication Flow, Hard coded Admin creds and from hard coded creds (email id will be of planckoff and password I will set) admin can set
- ☒ Introduce Roles in the application
- ☒ Then setup Protected routes
- ☐ The button which you can see on the top which is Metric and Imperial is for the Unit system which we have to follow for that particular project.



- ☐ After Deleting the project it should go in trash and will stay there for 15 Days.
CRON Job (we need to set)
- ☐ Three button on the project screen, one is to view only Wall Assembly, another is for Takeoff Schedule, and another one is for viewing both. **(Can we do it or not)**
- ☐ We need to make the “import button” work in Material Database we need to compare the downloaded excel to the real excel, and we have to upload the real sheet in which we have the data.
- ☐ Assembly Code → Wall Type No/Wall Type (something near to wall type).

ASSEMBLY CODE

W4

- ☐ in “#” column we have to keep the Sr. No. which is as it is.
 - ☐ In the “Sect” Column we have to map the data from the database. we need to look in the sheet, the section which matches with the database we have to print that section.
- eg: it should print 092216 when “Metal Studs (...)” appears.

	A	B	C	D	E	F	G	metal	5 of 53	^	v	:	x	
1	code	section	matCostCode	laborCostCode	type	manufacturer	description							PriceU
2	LAB-GEN-01	01 00 00	LABOR	GEN	Labor	Role	Project Foreman / Superintendent	85	1 HR					1/24/2
3	LAB-GEN-02	01 00 00	LABOR	GEN	Labor	Role	Journeyman Carpenter (Framing/Drywall)	65	1 HR					1/24/2
4	LAB-GEN-03	01 00 00	LABOR	GEN	Labor	Role	Drywall Finisher / Taper	62	1 HR					1/24/2
5	LAB-GEN-04	01 00 00	LABOR	GEN	Labor	Role	Apprentice / General Laborer	45	1 HR					1/24/2
6	LAB-FRM-STD	09 22 16	LABOR	FRM	Labor	Framing	Install Metal Studs (Walls < 12ft)	1.1	1 SF					1/24/2
7	LAB-FRM-HIGH	09 22 16	LABOR	FRM	Labor	Framing	Install Metal Studs (High 12ft-20ft)	1.65	1 SF					1/24/2
8	LAB-FRM-XHI	09 22 16	LABOR	FRM	Labor	Framing	Install Metal Studs (Extr. High > 20ft)	2.25	1 SF					1/24/2
9	LAB-FRM-TRK	09 22 16	LABOR	FRM	Labor	Framing	Install Track (Top & Bottom)	0.65	1 LF					1/24/2
10	LAB-FRM-CEIL	09 22 16	LABOR	FRM	Labor	Framing	Ceiling Joist Framing (Hard Lid)	1.85	1 SF					1/24/2

- ☐ Keywords which I need to feed AI to fetch the description from the pdf: GYPSUM WALLBOARD, POLY VAPOUR BARRIER, INSULATION, METAL STUDS, GYPSUM SHEATHING, CROSS BRACING,

☐ Now coming to Code Column, it should also match from the db (in website) column sheet which is named as “code”.

☐ Now comes the Hgt column, for that we have to upload excel on the other side which is “OST Sheet” in that we have to check for the “Assembly Code” now for example P1 we have to check for the various height which we have that is for P1 we have 15, 10, 9.7 now we have to show each height individually in different assembly something like P1@10, then in next line we have to show P1@15...

☐ We have to do sum of LF (Linear Feet) for example look in the excel sheet in P1 we have 9.7 repeated multiple times we have to do the sum of wall length/ceiling area so for 9.7 it would be 1717 and it should be shown here. 📌 here in the image we are showing all three together but it should not be like that.

Global Parameters		
Wall @ 10'	264 LF	2640 SF
Wall @ 15'	68 LF	1020 SF
Wall @ 9.7'	1717 LF	16655 SF

☐ Next comes up the OC by default we have to keep it 16 inch. it might be in mm in the pdf. Now for P1 look in the pdf it is already mentioned the OC, we have to scan that and print in the assembly.

☐ Now comes the Layering for that we will get the data from the pdf itself, if the wall is of Two Layers then we have to print 2, if it is not mentioned then you have to print 1.

☐ Now comes Wst% which is Wastage% that we have to set by default 5% but it should be editable.

☐ Now comes the Qty. formulas Dhruv Bhai is going to give me we have to use that.

☐ LF → Imperial, M → Metric Unit System **(NOTE)**.

☐ If I select Imperial from the top then while uploading the assembly the UOM Column should get imperial units, and if Metric then it should show the units of metrics in the dropdown.

☐ Now comes the Formula Basis that Dhruv Bhai will share me.

☐ Now comes Unit Mat. (Unit Material Price) in that it should go in the db from the website match the code and get the Cost from it, there it might have been mentioned like 450/1000 LF we have to convert it to 1 Feet or Sq. Feet and show in the column

How would I know in which unit I need to get it.

☐ While uploading to the database we have Plus Button in that we have to make sure that in the code column we have one coding standard which everything needs to follow.

☐ One button to upload both files, will that work ?