Product recall report

Acme Forgings (Acme Forgings Private Limited), Gat 121, Chakan Industrial Area, Pune 410501, GSTIN 27ABCDE1234F1Z5

Recall reference	RCL-2026-00007	Status	OPEN
Recall date	2026-10-28	Generated	31 Oct 2026, 12:00 IST

Reason for recall

Hairline cracks were found in drive shafts from these batches during a customer's incoming inspection. Metallurgy points to incorrect heat treatment on furnace 3.

Action required

Stop using the affected units at once. Quarantine remaining stock, and tell us how many units you hold.
Do not scrap anything: we will arrange collection within five working days.

Quantities

3	200	110	90
Customers affected	Dispatched	Returned	Outstanding

Affected products and batches

Product code	Product	Batch	Batch status
DS-40	Drive Shaft 40mm	PB-2026-00031	RELEASED

Customers

Customer	Contact	Status	Attempts	Acknowledged	Dispatched	Returned	Outstanding
Partial Returns Limited (CUST-1000)	Asha Rao, +91 98200 11000 quality.manager@customer0.example.com Plot 1, MIDC Bhosari, Pune 411026	Return in progress Meera Iyer	2		100	30	70
Fully Returned Limited (CUST-1001)	Asha Rao, +91 98200 11001 quality.manager@customer1.example.com Plot 2, MIDC Bhosari, Pune 411026	Resolved Meera Iyer	3	2026-10-28	80	80	0

Customer	Contact	Status	Attempts	Acknowledged	Dispatched	Returned	Outstanding
Vanished Traders (CUST-1002) Exception: Company has ceased trading, confirmed by the Registrar of Companies. Agreed with the Plant Manager.	Asha Rao, +91 98200 11002 quality.manager@customer2.example.com Plot 3, MIDC Bhosari, Pune 411026	Unreachable Meera Iyer	4		20	0	20

Dispatch references

Dispatch	Customer	Dispatched on	Shipped on	Quantity	Returned	Outstanding
DSP-2026-1000	Partial Returns Limited	2026-10-19	2026-10-20	100	30	70
DSP-2026-1001	Fully Returned Limited	2026-10-19	2026-10-20	80	80	0
DSP-2026-1002	Vanished Traders	2026-10-19	2026-10-20	20	0	20

Affected serial numbers (200)

DS40-2026-000000, DS40-2026-000001, DS40-2026-000002, DS40-2026-000003, DS40-2026-000004, DS40-2026-000005, DS40-2026-000006, DS40-2026-000007, DS40-2026-000008, DS40-2026-000009, DS40-2026-000010, DS40-2026-000011, DS40-2026-000012, DS40-2026-000013, DS40-2026-000014, DS40-2026-000015, DS40-2026-000016, DS40-2026-000017, DS40-2026-000018, DS40-2026-000019, DS40-2026-000020, DS40-2026-000021, DS40-2026-000022, DS40-2026-000023, DS40-2026-000024, DS40-2026-000025, DS40-2026-000026, DS40-2026-000027, DS40-2026-000028, DS40-2026-000029, DS40-2026-000030, DS40-2026-000031, DS40-2026-000032, DS40-2026-000033, DS40-2026-000034, DS40-2026-000035, DS40-2026-000036, DS40-2026-000037, DS40-2026-000038, DS40-2026-000039, DS40-2026-000040, DS40-2026-000041, DS40-2026-000042, DS40-2026-000043, DS40-2026-000044, DS40-2026-000045, DS40-2026-000046, DS40-2026-000047, DS40-2026-000048, DS40-2026-000049, DS40-2026-000050, DS40-2026-000051, DS40-2026-000052, DS40-2026-000053, DS40-2026-000054, DS40-2026-000055, DS40-2026-000056, DS40-2026-000057, DS40-2026-000058, DS40-2026-000059, DS40-2026-000060, DS40-2026-000061, DS40-2026-000062, DS40-2026-000063, DS40-2026-000064, DS40-2026-000065, DS40-2026-000066, DS40-2026-000067, DS40-2026-000068, DS40-2026-000069, DS40-2026-000070, DS40-2026-000071, DS40-2026-000072, DS40-2026-000073, DS40-2026-000074, DS40-2026-000075, DS40-2026-000076, DS40-2026-000077, DS40-2026-000078, DS40-2026-000079, DS40-2026-000080, DS40-2026-000081, DS40-2026-000082, DS40-2026-000083, DS40-2026-000084, DS40-2026-000085, DS40-2026-000086, DS40-2026-000087, DS40-2026-000088, DS40-2026-000089, DS40-2026-000090, DS40-2026-000091, DS40-2026-000092, DS40-2026-000093, DS40-2026-000094, DS40-2026-000095, DS40-2026-000096, DS40-2026-000097, DS40-2026-000098, DS40-2026-000099, DS40-2026-000100, DS40-2026-000101, DS40-2026-000102, DS40-2026-000103, DS40-2026-000104, DS40-2026-000105, DS40-2026-000106, DS40-2026-000107, DS40-2026-000108, DS40-2026-000109, DS40-2026-000110, DS40-2026-000111, DS40-2026-000112, DS40-2026-000113, DS40-2026-000114, DS40-2026-000115, DS40-2026-000116, DS40-2026-000117, DS40-2026-000118, DS40-2026-000119, DS40-2026-000120, DS40-2026-000121, DS40-2026-000122, DS40-2026-000123, DS40-2026-000124, DS40-2026-000125, DS40-2026-000126, DS40-2026-000127, DS40-2026-000128, DS40-2026-000129, DS40-2026-000130, DS40-2026-000131, DS40-2026-000132, DS40-2026-000133, DS40-2026-000134, DS40-2026-000135, DS40-2026-000136, DS40-2026-000137, DS40-2026-000138, DS40-2026-000139, DS40-2026-000140, DS40-2026-000141, DS40-2026-000142, DS40-2026-000143, DS40-2026-000144, DS40-2026-000145, DS40-2026-000146, DS40-2026-000147, DS40-2026-000148, DS40-2026-000149, DS40-2026-000150, DS40-2026-000151, DS40-2026-000152, DS40-2026-000153, DS40-2026-000154, DS40-2026-000155, DS40-2026-000156, DS40-2026-000157, DS40-2026-000158, DS40-2026-000159, DS40-2026-000160, DS40-2026-000161, DS40-2026-000162, DS40-2026-000163, DS40-2026-000164, DS40-2026-000165, DS40-2026-000166, DS40-2026-000167, DS40-2026-000168, DS40-2026-000169, DS40-2026-000170, DS40-2026-000171, DS40-2026-000172, DS40-2026-000173, DS40-2026-000174, DS40-2026-000175, DS40-2026-000176, DS40-2026-000177, DS40-2026-000178, DS40-2026-000179, DS40-2026-000180, DS40-2026-000181, DS40-2026-000182, DS40-2026-000183, DS40-2026-000184, DS40-2026-000185, DS40-2026-000186, DS40-2026-000187, DS40-2026-000188, DS40-2026-000189, DS40-2026-000190, DS40-2026-000191, DS40-2026-000192, DS40-2026-000193, DS40-2026-000194, DS40-2026-000195, DS40-2026-000196, DS40-2026-000197, DS40-2026-000198, DS40-2026-000199

Inspection history

Inspection	Type	Batch	Status	Result	Disposition
INS-2026-00412	FQC	PB-2026-00031	COMPLETED	PASS	ACCEPT

Contact history

When	Customer	Kind	Outcome	Response	Recorded by
2026-10-21	Fully Returned Limited	Email	No reply		Meera Iyer
2026-10-22	Fully Returned Limited	Phone	Failed		Meera Iyer
2026-10-23	Fully Returned Limited	WhatsApp	Reached	Will return all 80 units	Meera Iyer
2026-10-24	Vanished Traders	Phone	Failed	Number disconnected	Meera Iyer