

Hari Om ERP Stock Lifecycle, Timestamp Count and QR Traceability Guide

Client-ready user guide for opening stock, inward QC, QR labels, scan issue, non-blocking job-card QC, customer rejection, rework/scrap, monthly stock count, year-end carry-forward, reports and traceability.

Prepared for	Amigo / Hari Om production and stores users
Prepared on	28 June 2026
System area	Inventory, Quality, Production Job Cards, Reports, Stock Control
Purpose	Explain exactly how to use the finished workflow without technical language

Executive Summary

The system now covers the complete stock lifecycle from first opening stock to inward material, QC approval, QR label tracking, scan-based production issue, job-card stage QC, finished-goods inward, dispatch, customer rejection, rework/scrap closure, stock count, stock adjustment, monthly reporting and year-end carry-forward.

The newest release adds timestamp-based stock counts. If the physical count was taken yesterday evening but entered today, the book stock can be calculated exactly at yesterday evening, then saved with the real count-taken time. This prevents later receipts/issues from corrupting the count.

Opening stock is now a one-time initialization per plant. After go-live, opening for the next month/year should come from certified carry-forward, and corrections should go through dated adjustment vouchers.

1. Full Stock Lifecycle

1. Opening Enter first opening stock once at go-live.	2. Inward Receive raw material, reels, parchment, adhesive or FG return.	3. QC Gate QC approves before item can be issued/used.	4. QR Label Print batch/reel label and attach to material.
1. Issue Scan label and issue to production/job card.	2. Job Card QC Record QC after each stage without blocking normal flow.	3. FG/Dispatch FG inward and dispatch remain traceable.	4. Reject/Count Handle customer rejection, count, variance and carry-forward.

This lifecycle keeps the physical material identity, ledger movement, QC result, job card and final customer outcome connected. A user can start with a QR label, a batch number, a reel number, a job card, a dispatch, or a customer rejection and follow the trail backward or forward.

TUBEOS WORKSPACE
Inventory

Search pages, flows, SUPPLY CHAIN INVENTORY Guide OWNER ALL VISIBLE PLANTS Logout

STORES RECEIPT / DIRECT GRN
Raw Material Inward
Post bulk adhesive, parchment, packing, and non-reel material receipts with vendor id, batch/rate, location, and mandatory incoming QC hold.

PURCHASE FLOW **REEL INWARD**

STEP 1
Purchase reference
PO/GRN number stays on the ledger external reference.

STEP 2
Receipt posting
Vendor id, cost, and location are mandatory for a priced batch.

STEP 3
Incoming QC
Every receipt stays on QC hold until inspection passes.

STEP 4
Stock use
Only QC-approved batches become available to production issue.

Select RM item Batch no optional Qty Select vendor Inward rate Incoming QC hold

Select location PO / GRN reference **Post inward**

This receipt will enter stock as **QC_HOLD**. Release/inspection is visible from the quality desk before production issue.

1 Inward material identity

QC status gates issue/use

Marked inward screen: material identity, QC gate and label point.

2. One-Time Opening Stock

Use opening stock only once per plant when the system goes live. This creates the first book stock for existing material. Once any opening load exists for that plant, manual opening is blocked to avoid double-posting stock.

When	What user does	System result
First go-live day	Open Inventory > Stock Control > Opening Load. Select item, quantity, batch/reel, unit cost and post.	Stock ledger receives opening transaction and stock becomes available subject to status.
Next month/year	Do not manually enter opening again. Certify closing stock, generate carry-forward, then post opening from carry-forward.	Opening is tied to the prior certified close and avoids double entry.
Correction needed	Use Adjustment Voucher with reason and effective time.	A dated correction is recorded in the audit trail.

Example: On 1 July, opening stock is entered for Plant A. On 31 July, users count and certify July closing stock. On 1 August, August opening is created through carry-forward, not manual opening.

The screenshot shows the 'Marked Stock Control' interface. At the top, there's a navigation bar with 'Inventory' and 'Stock Control' tabs. The main header reads 'Opening stock, closing certification, and formal year carry-forward'. Below this, there's a 'Period and count timing controls' section with a date range of '2024-01-01 to 2024-06-30' and a 'Physical count close' section with a bar chart showing stock levels. The 'Material stock ledger' table lists various materials with their current and previous stock levels. The 'Manual stock correction' section includes an 'Adjustment voucher and audit trail' button. The 'Missing transferability policy' section lists materials with their respective policies.

Marked Stock Control screen: certification, opening load, adjustment voucher and audit trail.

3. Timestamp-Based Stock Count

This is the most important stock count change. The system separates two times:

Field	Meaning	Why it matters
Stock as of	The exact book-stock snapshot time.	The statement ignores receipts/issues after this time.
Count taken	The time the physical team actually counted the material.	The count proof shows when the floor quantity was checked.
Posting time	When the user enters/saves the count in ERP.	Can be later; it does not change the count snapshot.

Detailed example: The team physically counts stock on 27 June 2026 at 6:30 PM. The office enters it on 28 June 2026 at 11:00 AM. In Stock Control, select period 1 June to 30 June, set Stock as of = 27/06/2026 18:30 and Count taken = 27/06/2026 18:30. Draft the certification. The system creates count lines using book stock exactly at 6:30 PM on 27 June. Any inward or issue posted after 6:30 PM is excluded from that count session.

Step	User action	What to check
1	Open Inventory > Stock Control.	Select the correct plant, not All Plants.
2	Set From/To dates and Stock as of timestamp.	Timestamp must fall inside the selected period.
3	Set Count taken timestamp.	Use the actual floor count time.
4	Click Draft certification for period.	Count sheet lines appear from book stock at that timestamp.
5	Enter physical quantity, bin/location, counted by, checked by and proof notes.	Use recount flag where needed.
6	Certify.	Certification becomes the official monthly/year-end proof.
7	Post variance if required.	Variance voucher uses the stock-as-of time for audit accuracy.

4. Inward QC Before Use or Issue

Material can be received first, but production should only use/issue approved material. Items under QC hold or blocked status remain visible for tracking but should not be treated as free usable stock.

Material	QC parameters requested by client	Use rule
Adhesive	Viscosity, Temperature, Solid Content, Color, PH	Approve QC before issue to production.
Parchment	Color Bleeding, GSM, BF	Approve QC before issue to production.
Paper/Reels	Reel number, GSM, BS, BF, Caliper, Bulk, Ply Bond, RCT, COBB, Moisture	Track by reel; scan reel QR at issue.
Finished goods return	Rework possible, defect/reason, department, evidence	Keep under hold until disposition.

The QC/specification lists are kept as editable master-style check parameters, so the team can add, remove or rename dropdown options without redesigning the flow.

Reel Inward (Barcode Assisted)
Confirm vendor id, rate, weight, location, and incoming QC hold. The system generates the reel code.

Inward Entry

REEL CODE: [System generated after posting] INWARD DATE: 28/06/2026

PAPER ITEM: [Select raw paper] INWARD WEIGHT (KG): [] INWARD RATE / KG: []

VENDOR: [Select vendor] LOCATION: [Select location] RECEIPT STOCK STATUS: [Incoming QC hold]

GSM: [] BF: []

[Post Reel Inward]

Recent Reels

Code	Status	Current kg	Vendor	Location	Inward date
REEL-00A1-260525-1961	IN_STOCK	455.00	RM Seed Supplier	-	2026-05-25
REEL-00B2-260525-1560	IN_STOCK	455.00	RM Seed Supplier	-	2026-05-25
REEL-00A1-260525-3FF9	IN_STOCK	455.00	RM Seed Supplier	-	2026-05-25
REEL-00A1-260525-9D2D	IN_STOCK	455.00	RM Seed Supplier	-	2026-05-25
REEL-00B2-260525-0656	IN_STOCK	455.00	RM Seed Supplier	-	2026-05-25
REEL-00A1-260525-EF61	IN_STOCK	455.00	RM Seed Supplier	-	2026-05-25
REEL-00A1-260525-DE06	IN_STOCK	455.00	RM Seed Supplier	-	2026-05-25
REEL-00B2-260525-1A5E	IN_STOCK	455.00	RM Seed Supplier	-	2026-05-25
REEL-00A1-260525-7131	IN_STOCK	455.00	RM Seed Supplier	-	2026-05-25
REEL-00A1-260525-6326	IN_STOCK	455.00	RM Seed Supplier	-	2026-05-25
REEL-00B2-260525-1FFC	IN_STOCK	455.00	RM Seed Supplier	-	2026-05-25
REEL-00A1-260525-C737	IN_STOCK	455.00	RM Seed Supplier	-	2026-05-25
REEL-00A1-260523-26CD	IN_STOCK	455.00	RM Seed Supplier	-	2026-05-23
REEL-00B2-260523-3147	IN_STOCK	455.00	RM Seed Supplier	-	2026-05-23
REEL-00A1-260523-9D08	IN_STOCK	455.00	RM Seed Supplier	-	2026-05-23

Marked reel inward screen: reel identity, QC/stock status and label point.

5. QR Labels and Scan Issue

Labels are generated for stock identities. Bulk materials use batch labels. Reel-tracked paper uses reel labels. Operators can scan labels instead of typing long IDs.

Label type	Printed/attached to	Used for
Batch QR	Bulk inward material lot, e.g. adhesive/parchment/non-reel item	Selecting the correct batch during production issue.
Reel QR	Physical paper reel	Selecting the exact reel during reel issue to winder.
FG/batch reference	Finished goods batch/return where available	Customer rejection and traceability.

Production issue example: A store operator opens Inventory > Production Issue. The operator scans the batch QR into "Scan batch QR or enter batch no". The system resolves the material and batch, then the operator selects the job card, enters quantity and posts the issue. The ledger records Store Out and WIP In against the same batch and job card.

Reel issue example: A reel has a QR label. The operator opens Inventory > Reels > Issue, scans the reel QR, selects the winder machine, enters issued weight and keeps "Log issue scan event" checked. The reel movement remains linked to the reel, machine, shift and consumed/remaining weight.

6. Non-Blocking QC in Job Cards

The client wanted QC data after every production step, but not as a hard stop for every routine entry. The system supports this as non-blocking trace data: production can continue, while the QC values, remarks, signatures, hold/reject quantities and reasons stay linked to the job card and stage.

Job-card stage	Typical QC data captured	Trace use later
Slitting/Winder	Operator, machine, input, output, reject, hold, reason, QC sign	Trace winding/slitting defects and department responsibility.
Oven	Output, scrap/reject, temperature/process remarks, QC sign	Trace heating/process issues.
Process/Packing	Final output, reject quantity, hold, reason, QC/packing sign	Trace customer rejection to final handling.
Print/Document	QC fields and signatures appear on job-card print view	Client/audit proof without blocking daily production.

If a serious QC issue is found, the user should mark hold/reject or create the appropriate rejection/disposition. Routine QC values are recorded for traceability and reports.

7. Customer Rejection, Rework and Scrap

1. Inward rejection Customer rejected FG quantity is received back under hold.	2. Trace cause Link to FG batch, job card, stage QC and department.	3. Decide action Rework, reheat, segregate, accept, block or scrap.	4. Close Save cost, proof and closure status.
--	---	---	---

Disposition	When to use	Stock result
Rework	Material can be repaired/reprocessed and returned as usable FG.	Rework output can be inwarded again as FG with reference.
Reheat	Material needs heating/reprocessing before use.	Trace action stays with rejection; resulting output is inwarded/updated as applicable.
Segregate	Good/bad quantity can be separated.	Acceptable quantity can be released; bad quantity can remain blocked or scrap.
Accept	Customer return is accepted after inspection.	Stock can be released where appropriate.
Block	Decision pending or material should not be used.	Stock remains blocked/hold.
Scrap	Material is not repairable.	Scrap closure posts a negative stock adjustment voucher and removes live stock.

Example: Customer rejects 1,000 tubes from batch FG-2406-18. User opens Quality, records customer rejection, root cause department Winder, owner QC, corrective action and proof. If 700 tubes are reworkable, use Rework and inward the repaired output with reference. If 300 tubes are not repairable, close those as Scrap so stock is removed through a posted adjustment voucher.

Marked quality screen: returned FG hold, disposition and scrap stock adjustment.

8. Monthly Close and Year-End

Close activity	Monthly flow	Year-end flow
Physical count	Count material for the month-end timestamp.	Count material for year-end timestamp.
Certification	Draft, fill physical counts, certify.	Same process; mark fiscal year label.
Variance	Post variance voucher if book and physical differ.	Post variance before carry-forward.
Reconciliation	Approve monthly reconciliation only after stock certificate is ready.	Use approved year-end close as proof.
Opening next period	Carry-forward creates next period opening where needed.	Carry-forward creates next financial year opening.

The important rule is that month/year close should be certification-led. The physical count and stock certification come before final reconciliation approval, so reports and opening stock are based on controlled data.

9. Reports and Trace Usage

User question	Where to go	How to use it
What is current stock?	Inventory > Balances / Stock Control	Review closing quantity, hold/block status and count coverage.
Why did stock change?	Inventory > Ledger	Filter by item, batch/reel, date period and transaction type.
Which batch/reel went to production?	Inventory > Production Issue or Reel Issue plus Ledger	Scan/search QR identity and follow issue to job card.
Why did monthly consumption vary?	Production > Reconciliation	Compare theoretical, actual, ledger issued and notes. Drill to ledger.
What was counted at month-end?	Inventory > Stock Control > Certifications	Open certification, see stock-as-of, count-taken, physical count, variance and proof.
What stock adjustments were posted?	Inventory > Stock Control > Adjustment Vouchers	Review reason, effective time, approval note and posted voucher.
Why was customer rejected material scrapped?	Quality > Customer Rejections	Open rejection, review root cause, department, disposition, proof and scrap voucher.

Trace example: Customer complaint says "notch issue". Start from Quality customer rejection, open linked FG/job card, inspect stage QC data such as notch width/patti/direction, check material issue ledger for paper/reel/batch used, and review whether closure was rework or scrap.

10. Operator Quick Guides

A. Post a stock count taken earlier

Step	Action
1	Go to Inventory > Stock Control and select the plant.
2	Set period From/To.
3	Set Stock as of to the exact count snapshot time.
4	Set Count taken to when the floor actually counted.
5	Draft certification, enter physical counts, save, certify.
6	Post variance voucher only if needed.

B. Issue material by QR scan

Step	Batch material	Reel material
1	Inventory > Production Issue.	Inventory > Reels > Issue.
2	Scan batch QR or enter batch no.	Scan reel QR or enter reel code.
3	Select job card and quantity.	Select winder machine, shift and issued weight.
4	Post issue to WIP.	Create reel issue with scan event checked.

C. Handle customer rejection

Step	Action
1	Inward the returned/rejected quantity as customer rejection/FG return.
2	Open Quality customer rejection and fill root cause department, owner department, corrective action and due date.
3	Choose disposition: rework, reheat, segregate, accept, block or scrap.
4	For rework, inward recovered FG with reference after repair.
5	For scrap, close as scrap so the stock adjustment voucher removes quantity.

11. Release Verification Summary

The following checks were completed on the current system before this report was generated. This page is written in user language so it can be shared without code details.

Area checked	Result
Web application verification	Passed: screen lint, route/spec checks, unit checks, type check and production build.
Inventory service checks	Passed: stock truth and stock-control contracts, including timestamp fields.
Production reconciliation checks	Passed: monthly reconciliation safeguards.
BFF route contracts	Passed: web/API route contract tests.
Runtime smoke	Passed: login, timestamp stock statement, certification timestamp fields, adjustment effective time, reel QR label payload.
Browser screenshot refresh	Not refreshed in this run because local Chrome launch required blocked desktop permission; existing marked screenshots are included for navigation context.

Client handover note: users should attach QR labels immediately after inward, keep QC approval updated before floor issue, and use dated adjustment vouchers instead of changing historical stock directly.