PPL - FLIGHT

Page: 11

BALI INTERNATIONAL FLIGHT ACADEMY

Revision 8

Effective: Jun. 2021

Mission 11

CIRCUITS 5 / CROSS CHECK

STUDENT: BRILYAN	DATE 1: 17 /07 /2023	DATE 2:
INSTRUCTOR: CAPT. RIZKA	A/C REG: RON	A/C REG:
A/C TYPE: C-172	DURATION: 01:00	DURATION:

R-	4 10 0 110 1 0 -	1	2 COMMENTS:
-	A/C Certificate & Documents	2	
R-	A/C Manual	1	- TOO SLOW TO DO CONNECTION
R-	Use of checklist	2	TOO SLOW TO DO PROCEDURES
R-	Pre-flight Inspections	S	- TOO SLOW TO GO PROCESSES
R-	Operations of the Systems	5	NOT INITIATIVE
R-	Equipment Checks	3	
R-	Engine Starting	S	NOT COPY ATC WISTENCTON.
R-	Radio Communications	2	
R-	Taxiing and Taxi Checks	12	TRAFFIC AWARENESS WAS PODE
R-	Before Take-off Checks	S	ADJUSTMENT ON TRANING TO FINAL
R-	Normal Take-off and Climb	9	ADJUSTMENT ON THOUSE
R-	Engine Failure Before Take-off	玉	WAS POOR.
R-	Engine Failure After Take-off (EFATO)	Σ	NOT MULTITASKING
R-	Engine Failure on Downwind/Glide Approach	2	NOT DOING LEVELING Off
R-	Collision Avoidance/Traffic Awareness	3/2	NOT DOING FLAME.
R-	Traffic Pattern Procedures	59	NOT AWARE WITH BUNWAY WE EVERY
R-	Normal Approach	<u>Gry</u>	46.
R-		Sign	- ab
R-	Go-Around (GA) Procedures From Landing Flare	I	UNGOTBLE ON FWAL
	- Clean Configuration / Flap 10°, 20°, 30°	2	TOO HIGH ON FWAL & NOT COMMECTION
R-	Flapless Approach	I	- PASSIVE TO DO CONRECTION.
R-		É	ON FINAL NO IDEA WHAT TO DO
R-	Bad Landing Recovery Technique	11	- ON THE TO THE WITH
	- Bouncing / Balked Landing	20	$\neg \omega$
	- Ballooning Floating	59	
R-	After Landing Procedures	ς	
R-	Parking and Securing	2	

COMPLETION STANDARDS:

- Must perform all the listed manoeuvres including emergencies safely and with minimum instructor assistance.
- b. Maintain tolerances for Altitude \pm 100 ft., Heading \pm 10 $^{\circ}$ and airspeed +10/-5 kts.

SYLLABUS TIMES:

Total	Dual	Solo	IF	X/C	X/C Solo	Ldas
11:25	1:00					6
11:25	1:00					4

Student Signature

Instructor Signature

