CPL - FLIGHT

Page: 40

BALI INTERNATIONAL FLIGHT ACADEMY

Revision 5

Effective: Jun. 2021

Mission 40

CPL MANEUVERS - SUPERVISED PIC

| STUDENT: AFMON | DATE 1: 1/12/2021 | DATE 2: |
|--------------------------|-------------------|-----------|
| INSTRUCTOR: CAST EAR RYO | A/C REG: PLZROS | A/C REG: |
| A/C TYPE: C(22 | DURATION: /230 | DURATION: |

| | EXERCISES | 1 | 2 | COMMENTS: |
|----|-----------------------------------|-----|---|-----------|
| R- | Pre-Flight Inspection | S | | |
| R- | Required Documents Inspection | 1 | | 216 |
| R- | Checklist Usage | | П | Complete |
| R- | Short Field Take-Off | | | |
| R- | Departure to Training Area | | | |
| | | | | |
| R- | Pre-Manoeuvre Checks | | | |
| R- | Power Off Clean Stall - Full | | | |
| R- | Power Off Clean Stall - Incipient | | | |
| R- | Power Off Dirty Stall – Full | | | |
| R- | Power Off Dirty Stall – Incipient | | | la III |
| R- | Power On Clean Stall - Incipient | | | fil. |
| R- | Power On Dirty Stall – Incipient | | | a " |
| R- | Steep Turns | 1 | | - N |
| R- | Slow Flight | | | |
| | | | | 2 |
| R- | Alternator Failure | | | |
| R- | Engine Fire in Flight / PFL | | | |
| R- | Engine Failure After Take-Off | | | = |
| R- | Flapless Landing | | | |
| R- | Short Field Landing | | | |
| R- | Low Level Circuits | C | | |
| | | | | |
| | 9 | - 8 | | ş |
| | | | | |
| | 572 | | | φ. |
| | | | | |
| | | | | |
| | | | | 8 |
| | | | | |
| | | - | | |
| | | - | | |
| | * | - | | |
| | | | | 19 |

COMPLETION STANDARDS:

Able to maintain altitude ± 50 ft., heading ± 10°, airspeed ± 5 kts. and bank angle ± 5° for all exercises.

SYLLABUS TIMES:

| Total | Dual | PIC | X/C | IF | Ldgs | Night |
|-------|------|------|-----|----|------|-------|
| 72:50 | | 1:30 | | | 4 | |
| | | 1:30 | 1 I | | ک | |

