CPL - FLIGHT

Revision 5

Page: 48

BALI INTERNATIONAL FLIGHT ACADEMY

Effective: Jun. 2021

Mission 48

CPL MANEUVERS – SUPERVISED PIC

| STUDENT: AKMAL ANUGRAM P | DATE 1: 18/12/2021 | DATE 2: |
|--------------------------|--------------------|-----------|
| INSTRUCTOR: Capt. 12/0 | A/C REG: PIKROV | A/C REG: |
| A/C TYPE: C172 | DURATION: 1:30 | DURATION: |

| | EXERCISES | 1 | 2 | COMMENTS: |
|----|-----------------------------------|---------|---|--|
| R- | Pre-Flight Inspection | 5 | | |
| | Required Documents Inspection | T | | 12 |
| | Checklist Usage | | | # <u>=</u> |
| | Short Field Take-Off | | | Corplete |
| R- | Departure to Training Area | 7 | | Corplete |
| | - | | | |
| R- | Pre-Manoeuvre Checks | | | |
| | Power Off Clean Stall - Full | | | |
| R- | Power Off Clean Stall - Incipient | | | 66. |
| R- | Power Off Dirty Stall - Full | | | |
| R- | Power Off Dirty Stall – Incipient | | | |
| R- | Power On Clean Stall - Incipient | П | | |
| R- | Power On Dirty Stall – Incipient | П | | |
| R- | Steep Turns | | | A CONTRACTOR OF THE PROPERTY O |
| R- | Slow Flight | | | |
| | | | | # · · · · · · · · · · · · · · · · · · · |
| R- | Alternator Failure | | | |
| R- | Engine Fire in Flight / PFL | | | |
| R- | Engine Failure After Take-Off | | | |
| | Flapless Landing | | | |
| R- | Short Field Landing | | | |
| R- | Low Level Circuits | 0 | | 1 4 |
| | | \perp | | |
| | | | | |
| | × | | | \$ gr = 10 a a a a a a a a a a a a a a a a a a |
| | W | | | |
| | • | | | |
| | | | | |
| | (Section 1) | | | 9 11 |
| | | | | |
| | - X | | | · 1 |
| | | | | |
| | | | | |
| | | | | |

COMPLETION STANDARDS:

Able to maintain altitude ± 50 ft., heading ± 10°, airspeed ± 5 kts. and bank angle ± 5° for all exercises.

SYLLABUS TIMES:

| Total | Dual | PIC | X/C | IF | Ldgs | Night |
|-------|------|------|-----|----|------|-------|
| 84:00 | | 1:30 | | | 4 | |
| | | (:)0 | - | | 2 | |

