CPL - FLIGHT



Revision 4

Page: 34

BALI INTERNATIONAL FLIGHT ACADEMY

Effective: May. 2019

Mission 34

CPL MANEUVERS

| STUDENT: M. Hariah Raihan | DATE 1: 25 FLb 2021 | DATE 2: |
|---------------------------|---------------------|-----------|
| INSTRUCTOR: Lapt. 1 Qbal | A/C REG: PK-ROR | A/C REG: |
| A/C TYPE: LI72 | DURATION: 01:00 | DURATION: |

| | Exercises | 1 | 2 | COMMENTS: |
|----|-----------------------------------|-------------|----|---------------------------------------|
| R- | Pre-Flight Inspection | S | | |
| | Required Documents Inspection | 3 | | |
| R- | Checklist Usage | 3 | | (|
| R- | Short Field Take-Off | 3 | | miscrotory. |
| R- | Departure to Training Area | S | | Satisfactory. |
| | | | | |
| R- | Pre-Manoeuvre Checks | 3 | | |
| | Power Off Clean Stall – Full | S | | |
| R- | Power Off Clean Stall – Incipient | 8 | | |
| | Power Off Dirty Stall – Full | 5 | | · · · · · · · · · · · · · · · · · · · |
| | Power Off Dirty Stall – Incipient | 8 8 | | |
| | Power On Clean Stall – Incipient | S | | |
| R- | Power On Dirty Stall – Incipient | | | |
| R- | | S | | |
| R- | Slow Flight | 9 | | |
| | ** | | | 9.9 |
| R- | | S S S | | , |
| | Engine Fire in Flight / PFL | ٤ | | |
| | Engine Failure After Take-Off | ع | | |
| | Flapless Landing | 9 | | |
| | Short Field Landing | 5 | | |
| R- | Low Level Circuits | S | | |
| | , | | | |
| | | | _ | * * * |
| | | | | |
| | | _ | _ | |
| | | _ | 1 | |
| | | | - | |
| | | | _ | |
| - | | _ | 2. | y 20 |
| | | | - | |
| - | | | | , , , |
| - | | | | |
| | | | | |

COMPLETION STANDARDS:

a. Able to maintain altitude \pm 50 ft., heading \pm 10°, airspeed \pm 5 kts. and bank angle \pm 5° for all exercises.

SYLLABUS TIMES:

| Total | Dual | PIC | X/C | IF | Ldgs | Night |
|-------|------|-----|-----|----|------|-------|
| 65:00 | 1:00 | | | | 4 | |
| | 1:00 | | | | | |

Student Signature M. Hariah

Instructor Signature