CPL - FLIGHT

Page: 34

BALI INTERNATIONAL FLIGHT ACADEMY

Revision 5

Effective: Jun. 2021

Mission 34

CPL MANEUVERS

STUDENT: Munammad , Irsyatdudin	DATE 1: 13 / 11 /2021	DATE 2:
INSTRUCTOR: Capt Dav &	A/C REG: PK-ROS	A/C REG:
A/C TYPE: COCCAO 172	DURATION: 01:00	DURATION:

EXERCISES		1 2		COMMENTS:			
R-	Pre-Flight Inspection	3		A Company of the Comp			
R-	Required Documents Inspection	7		e Steep tupn was ok			
R-	Checklist Usage	5		· POWER OFF STALL WAS DR			
R-	Short Field Take-Off	5					
R-	Departure to Training Area	5		and the state of t			
				o power on stall was ok			
R-	Pre-Manoeuvre Checks	(
R-	Power Off Clean Stall - Full	. 5	÷	o slowflight or			
R-	Power Off Clean Stall - Incipient	5					
R-	Power Off Dirty Stall – Full	1					
R-	Power Off Dirty Stall – Incipient	5		· PFL: - TOO HIGH ON LOWICEY			
R-	Power On Clean Stall - Incipient	5					
R-	Power On Dirty Stall - Incipient	5		- TOO HIGH ON BASE			
	Steep Turns	5					
R-	Slow Flight	5					
R-	Alternator Failure	1		OVERALL SETTS=ACTORY			
R-	Engine Fire in Flight / PFL	5		OVERSEC SKITSFACTORY			
R-	Engine Failure After Take-Off	5					
R-	Flapless Landing	3					
R-	Short Field Landing)					
R-	Low Level Circuits)					
	,	-	1				
				*			
				PRE BRITISH 10MING			
				PORT SE TEMPLS			

COMPLETION STANDARDS:

Able to maintain altitude \pm 50 ft., heading \pm 10°, airspeed \pm 5 kts. and bank angle \pm 5° for all exercises.

SYLLABUS TIMES:

Total	Dual	PIC	X/C	IF	Ldgs	Night
65:00	1:00				4	*
	01:00				1	

Student Signature.



Instructor Signature ...