Revision 8

Page: 11

BALI INTERNATIONAL FLIGHT ACADEMY

Effective: Jun. 2021

Mission 11

CIRCUITS 5 / CROSS CHECK

STUDENT: FARLY ARCLAPS DUASS	DATE 1: 13/07/2003	DATE 2:
INSTRUCTOR: CAPT. MECHA	A/C REG: Ph-ROZ	A/C REG:
A/C TYPE: CIT?	DURATION: 0:00	DURATION:

R-	1 (0 0 110)		2	COMMENTS:
-	A/C Certificate & Documents	S		-TAKE OF NOT USING VISUAL PEFERENCE
R-	A/C Manual	S		
R-	Use of checklist	S		- CLIMB NOT MAINTAW P/W HDG.
R-	Pre-flight Inspections	ç		- NOT AWAME W/ SPEED AFTER USING
R-	Operations of the Systems	1		FLAP.
R-	Equipment Checks	5		120711
R-	Engine Starting	5		- MAINTAW ALTITUDE WAS OK AT YOMIN
R-	Radio Communications	S		- TOO SWW/LATE TO DO BUMPISH CHECK
R-	Taxiing and Taxi Checks	5	Γ	AND CONTACT NOWER.
R-	Before Take-off Checks	S		
R-	Normal Take-off and Climb	50		AT PIRST CAMPING TENDENCY FLAT &
R-	Engine Failure Before Take-off	5		TOO LOW FOR LEVEL of.
R-	Engine Failure After Take-off (EFATO)	S		- LATE CONRECTION WHEN HIGH ON APPROP
R-	Engine Failure on Downwind/Glide Approach	S		consine stees of my white travial
R-	Collision Avoidance/Traffic Awareness	1		FINAL.
R-	Traffic Pattern Procedures	2		SPEED SS-60 KMg on final 2/3 Times
R-	Normal Approach	C		
R-	Normal Landing	?		UP WIND - CRUSSWIND SPEED BO-25 END
R-	Go-Around (GA) Procedures From Landing Flare	Ī		4rd cansink was very smooth of safe.
	 Clean Configuration / Flap 10°, 20°, 30° 	1		PLOULING POWER TO IDLE WAS ROUGH.
R-	Flapless Approach	5		over su wix minon misomut,
R-		3		,
R-	Bad Landing Recovery Technique	1		STUDENT GOOD TO GO KEED MUSICA.
	 Bouncing / Balked Landing 	1		
	 Ballooning Floating 			
	After Landing Procedures	2		
R-	Parking and Securing	S		

COMPLETION STANDARDS:

- a. Must perform all the listed manoeuvres including emergencies safely and with minimum instructor assistance.
- b. Maintain tolerances for Altitude \pm 100 ft., Heading \pm 10° and airspeed +10/-5 kts.

SYLLABUS TIMES:

Total	Dual	Solo	IF.	X/C	X/C Solo	Ldas
11:25	1:00					6
	01:00	,	,			G

Student Signature

Instructor Signature ...