CPL - FLIGHT

Revision 5

Page: 48

BALI INTERNATIONAL FLIGHT ACADEMY

Effective: Jun. 2021

Mission 48

CPL MANEUVERS - SUPERVISED PIC

| STUDENT: FOURZ RIZNY-R | DATE 1: 21-12-2021 | DATE 2: | |
|------------------------|--------------------|-----------|--|
| INSTRUCTOR: CZPŁ-EH'K | A/C REG: PK-ROS | A/C REG: | |
| A/C TYPE: C-172 | DURATION: 1:30 | DURATION: | |

| | EXERCISES | 1 | 2 | COMMENTS: |
|-----|-----------------------------------|---------|---|---------------------------------|
| R- | Pre-Flight Inspection | 5 | | 8 8 8 |
| R- | Required Documents Inspection | 5 | | M 0 |
| R- | | 5 | | Mission Complete |
| R- | Short Field Take-Off | 5 | | 1 |
| R- | Departure to Training Area | S | | Mission Complete Overall was ox |
| | | 19 | | o all was ok |
| R- | Pre-Manoeuvre Checks | 5 | | * |
| R- | Power Off Clean Stall - Full | 5 | | |
| R- | Power Off Clean Stall - Incipient | 5 | | Čis: |
| R- | Power Off Dirty Stall - Full | 5 | | |
| R- | Power Off Dirty Stall – Incipient | 5 | | |
| R- | Power On Clean Stall – Incipient | 5 | | |
| R- | Power On Dirty Stall – Incipient | 5 | | |
| R- | Steep Turns | 5 | | " |
| R- | Slow Flight | 5 | | |
| | | | | |
| R- | Alternator Failure | 5 | | |
| R- | Engine Fire in Flight / PFL | 5 | * | . 6 |
| R- | Engine Failure After Take-Off | 5 | | |
| R- | Flapless Landing | 5 | | |
| R- | Short Field Landing | 5 | | |
| R- | Low Level Circuits | 5 | _ | |
| 1.5 | | | | |
| | | | | 2 |
| | | | | .93 |
| | <i>Ib</i> | | | |
| | | | Ш | |
| | | | | |
| | | | | П |
| | | | Ш | |
| | | | | |
| | | \perp | | |
| | | \perp | Щ | * 2 |
| | Ti . | | | |

COMPLETION STANDARDS:

a. Able to maintain altitude \pm 50 ft., heading \pm 10°, airspeed \pm 5 kts. and bank angle \pm 5° for all exercises.

SYLLABUS TIMES:

| Total | Dual | PIC | X/C | IF | Ldgs | Night |
|-------|------|------|-----|----|------|-------|
| 84:00 | | 1:30 | | | 4 | |
| | | 1:30 | | | u | |

Student Signature

..... Instructor Signature ...