Revision 5

CPL - FLIGHT

Page: 40

Effective: Jun. 2021

BALI INTERNATIONAL FLIGHT ACADEMY

04 noissiM

CPL MANEUVERS - SUPERVISED PIC

A/C TYPE: C-13	Z:1 :NOITARUD	:иотаяиО
INSTRUCTOR: במסף . להתנים	A/C REG: Pu-roy	A/C REG:
STUDENT: Darry (Midda	12 - 2-51 : 1314	:S ETAC

	_	-		
	_	-		
		1	Low Level Circuits	-N
		5	Short Field Landing	- H
		5	Flapless Landing	-H
		5	Engine Failure After Take-Off	B-
	_	5	Engine Fire in Flight / PFL	-N
		2	Alternator Failure	- N
POSTFLICHT BRIEF = IS MINS	7			
	-	7	Slow Flight	-Y
	_	7	Steep Turns	- B-
· PREFLICHT BRIEF = 15 PIM		5	Power On Dirty Stall - Incipient	- B-
	_	1	Power On Clean Stall - Incipient	B-
	_	2	Power Off Dirty Stall - Incipient	B-
VECESSARY	_	7	Power Off Dirty Stall - Full	B-
		1	Power Off Clean Stall – Incipient	-B
11 Name of the Mark of the Mar	_	2	Power Off Clean Stall - Full	-H
- PFL RUNMAY 32 & 14. SLICHTLY ADD FUDDER 1F	_	7	Pre-Manoeuvre Checks	- B-
	+	-	eyeed2 earlies each ead	a
- ALL MREA & CIRCUIT WERE SAFE		5	Departure to Training Area	-Y
202	_	r	Short Field Take-Off	-H
		7	Checklist Usage	-N
		5	Required Documents Inspection	-B
MADE - SINCARAJA - WADE		5	Pre-Flight Inspection	-H
20 M. ((ALM 2001) - 30 M.M		3	Pre-Figure Inspection	

COMPLETION STANDARDS:

exercises. Able to maintain altitude \pm 50 ft., heading \pm 10°, airspeed \pm 5 kts. and bank angle \pm 5° for all

SYLLABUS TIMES:

	5					
	Þ			1:30		72:50
thgiN	грдг	비	X/C	PIC	[end]	Total





