CPL - FLIGHT

337

Revision 5

Page: 34

BALI INTERNATIONAL FLIGHT ACADEMY

Effective: Jun. 2021

Mission 34

CPL MANEUVERS

STUDENT: Adition survey Dininglat	DATE 1: 20 - 01 - 2022	DATE 2:
INSTRUCTOR: CUPY 19 bal	A/C REG: PK - ROY	A/C REG:
A/C TYPE: C172	DURATION: 1,00	DURATION:

	EXERCISES	1	2	COMMENTS:
R-	Pre-Flight Inspection	5		
R-	Required Documents Inspection	3		
R-	Checklist Usage	5		
R-	Short Field Take-Off	5		Satistactory
R-	Departure to Training Area	5		3000.700000
		minis een y		10000
R-	Pre-Manoeuvre Checks	\$		•
R-	Power Off Clean Stall - Full	5		
R-	Power Off Clean Stall - Incipient	S		- Flories, Flore a batt
R-	Power Off Dirty Stall - Full	5		
R-	Power Off Dirty Stall - Incipient	2		
R-	Power On Clean Stall - Incipient	5		MOR.
R-	Power On Dirty Stall - Incipient	5		Account to the second s
R-	Steep Turns	Ş		
R-	Slow Flight	5		- hall wasters
				- stall mountain using
R-	Alternator Failure	Q		
R-	Engine Fire in Flight / PFL	Ş		r
R-	Engine Failure After Take-Off	S		(20) 21.
R-	Flapless Landing	5		September State September St
R-	Short Field Landing	5		
R-	Low Level Circuits	S	0110000	
	333333333333333333333333333333333333333			
				"
				3
				
			10000	6
	5 TT 10 5 00 00 00 00 00 00 00 00 00 00 00 00			
	T. W. Co.			

COMPLETION STANDARDS:

a. Able to maintain altitude ± 50 ft., heading ± 10°, airspeed ± 5 kts. and bank angle ± 5° for all exercises.

SYLLABUS TIMES:

Total	Dual	PIC	X/C	IF.	Ldgs	Night
65:00	1:00				4 0	
	1200				u//	1

Student Signature

Instructor Signature