Page: 26

BALI INTERNATIONAL FLIGHT ACADEMY

Revision 8

Effective: Jun. 2021

Mission 26 TRAINING AREA FAMILIARIZATION & PRACTICE FORCED LANDINGS

STUDENT: ALYAN	DATE 1: 205-08 - 2022	DATE 2:
INSTRUCTOR: CAPT. SUBLAN	A/C REG: PU-ROH	A/C REG:
	DURATION: 1:20	DURATION:
A/C TYPE: C 172	DORATION. 1100	

Exercises	1	2	COMMENTS:
R- Obtaining Weather Information	Ç		
R- NOTAMs	3		
R- Charts and Publications	5		
R- Maintenance Requirements	2		
R- AD's and Compliance	g		
R- Maintenance Records	5		
R- Aircraft Manual	9		
R- Aircraft Certificates and Documents	3	Г	
R- Use of checklist	5	Γ	
R- Pre-flight Inspections	S		
R- Equipment Checks	S		
R- Evacuation Procedures	S		
R- Procedures & Limitations	3	Γ	
R- Cockpit Management	S		
R- Radio Communications	3		
R- Short Field Take-off			
R- Short Field Landing			
R- Low Level Circuits			
R- VFR Departure Procedures	5		
R- Map Reading	5	floor	
R- Radio Communications Failure	S		-by fref
R- Lost Procedures	ς.	\pm	- by brief
R- Engine Failure Procedures (PFL)	3	Æ-	procedures male affinder (65 lys)
R- Slow Flight			Lafe to get to get the lately
R- Steep Turn	7	上	by brief broadures meed more in proved lafe to set to slide attitude (65 lifs) unsteady baule a unsteady sately
R- Stalls	15		
R- Collision Avoidance	S		C. D. W. pole L. onorein
R- VFR Arrival Procedures	9		fafe for 2nd polo trea expercio
R- After Landing Procedures	<u>8</u>		H Star
R- Parking and Securing	د	-	- (# OVY
R- Post Flight Procedures	+	+	Cape SUMHAN SETIAN ST. MM. / DGCA - 4077
	+	+	Capt Subtract Science of the control

COMPLETION STANDARDS:

Must be able to follow the published standard VFR Departure and Arrival procedures to and from

the training areas.

Must be able to demonstrate competency in a simulated forced landing using the correct

b. technique and whilst completing all the necessary drills.

SYLLABUS TIMES:

O , LL,						·
Total	Dual	Solo	TIF	X/C	X/C Solo	Ldgs
Total	1:20	5010		_	· -	2
26:25	1:20	_		-	-	3
17:10	1.00				A D	

Student Signature ...

Instructor Signature

apr. SUBKHAN SETIA.N, ST, MM. / DGCA - 4077