Initial tests

kernel7.img still not getting WIFI https://github.com/develone/Ultibo-Projects/tree/master/RIC-WIFI/tests/RPi3/0403-0201/022720

kernel7.img now gets WIFI on the Rpi3B+ compile with Lazarus IDE (Ultibo-Edition). kernel7.img now supports tftp

cat config.txt start_x=1 gpu_mem=128

diff bootcode.bin demofiles/bootcode.bin diff fixup4.dat demofiles/fixup4.dat diff fixup.dat demofiles/fixup.dat diff start4.elf demofiles/start4.elf diff start.elf demofiles/start.elf

Ultibo Core (Release: Beetroot Version: 2.1.125 Date: 25 August 2021)				
General	General			
Platform				
Memory	Release Name:	Beetroot		
Heap Blocks	Release Version:	2.1.125		
CPU	Release Date:	25 August 2021		
FPU				
GPU	Time (Local):	28-11-21 23:25:09		
RTL	Time (UTC):	28-11-21 23:25:09		
Clock				
Locale	Timezone:	UTC		
Threading				
Thread List	Daylight Start:	None		
Scheduler	Daylight Date:	N/A		
Devices				
Drivers	Standard Start:	None		
Handles	Standard Date:	N/A		
USB				
PCI	Temperature (SoC):	36.476 degrees Celcius		
MMC / SD / SDIO				
Network	Uptime:	0 days 00:01:31		
Storage				
Filesystem				
Disk Cache				
Keyboard				
Mouse				
Touch				

Ultibo Core (Release: Beetroot Version: 2.1.125 Date: 25 August 2021)				
General		Platform		
Platform				
Memory	Board Type:	BOARD_TYPE_RPI3B_PLUS		
Heap Blocks	Board Model:	0		
<u>CPU</u>	Board Serial:	0x000000008471DEDD		
<u>FPU</u>	Board Revision:	0x00A020D3		
<u>GPU</u>				
<u>RTL</u>	Chip Revision:	0x00000000		
Clock				
Locale	Firmware Revision:	0x5E4EB7C2 (1582217154)		
Threading				
Thread List	Machine Type:	MACHINE_TYPE_BCM2710		
Scheduler				
Devices	Memory Base:	0x00000000		
<u>Drivers</u>	Memory Size:	1073741824		
<u>Handles</u>				
<u>USB</u>	Page Size:	4096		
PCI	Large Page Size:	65536		
MMC / SD / SDIO				
Network	Section Size:	1048576		
Storage				
Filesystem	Power State			
Disk Cache	POWER_ID_MMC0:	POWER_STATE_ON		
Keyboard	POWER_ID_MMC1:	POWER_STATE_OFF		
Mouse	POWER_ID_MMC2:	POWER_STATE_OFF		
Touch	POWER_ID_MMC3:	POWER_STATE_OFF		

kernel7l.img now supports tftp

https://github.com/develone/Ultibo_Projects/tree/master/RIC-WIFI/tests/RPi3/0403-0201/112221

Using Ultibo member Paul's uTFTP.pas.

config.txt cmdline.txt

firmware

 $brcmfmac 43430 \hbox{-} sdio.bin \qquad brcmfmac 43455 \hbox{-} sdio.clm_blob$

brcmfmac43430-sdio.txt brcmfmac43436-sdio.bin brcmfmac43456-sdio.bin

brcmfmac43436-sdio.clm_blob brcmfmac43456-sdio.clm_blob

brcmfmac43436-sdio.txt brcmfmac43456-sdio.txt

brcmfmac43436s-sdio.bin LICENCE.broadcom_bcm43xx

brcmfmac43436s-sdio.txt Makefile

brcmfmac43455-sdio.bin

The folder firmware was copied from ultibowifi 3b1b3d8.

ls firmwar_for_ultibo/022720/ bootcode.bin fixup.dat fixup_x.dat start.elf start_x.elf