



Passport® Production Software EMV Feature Availability and M5/M7 CRIND EMV Kernel/FlexPay 6/ Software Reference Information

Related Equipment:

- Passport® Software V12 and Higher
- M5 CRIND Software (FlexPay II) (PCI2)
- M7 CRIND Software (FlexPay IV) (PCI4/PCI5)
- FlexPay 6 Software (PCI6)
- Wayne iXPay 1 Software
- Wayne iXPay 2 Software

Purpose:

This bulletin provides quick reference information that can be utilized when servicing, installing and/or performing an upgrade of Passport software and Gilbarco CRIND systems at locations utilizing EMV payment transactions.

The information provided will allow you to identify:

- When Passport EMV features were introduced by:
 - Specific Passport Version
 - Payment Network
 - Supported Indoor and Outdoor EMV Capabilities
- CRIND EMV Kernel Version Requirements by:
 - Passport Version
 - Payment Network
 - Dispenser Payment Terminal Type Support
 - M5 CRIND (FlexPay II) (PCI2)
 - M7 CRIND (FlexPay IV) (PCI4/PCI5)
 - FlexPay 6 (PCI6)
 - Wayne iX Pay Terminal
 - Wayne iX Pay 2
- CRIND EMV Contactless Hardware Requirements by:
 - Dispenser Payment Terminal Type Support
 - M5 CRIND (FlexPay II) UX410
 - M7 CRIND (FlexPay IV) UX400
 - Wayne iXPay 1 (Model C150 261EA02)
 - Wayne iXPay 1 (Model C150S_NP 2610FA02)
 - Wayne iXPay 2 (T7/T12 – C150S 2610A02 (PCI4)
 - Wayne iXPay 2 (T7/T12 – C150SE 2610A02 (PCI6)

IMPORTANT INFORMATION

The reference information provided in this document is current at the time of release and is not intended to replace any future notifications of Passport/CRIND software version and/or feature releases. Always refer to applicable MDE documentation for the installation, upgrade and/or serving of Gilbarco products.

IMPORTANT INFORMATION

This bulletin does not serve as authorization to perform any site visits or warranty service

	Indoor			Outdoor						
	MSD Contactless	EMV Inside Contact	EMV Inside Contactless	MSD Contactless		EMV Outdoor Contact		EMV Outdoor Contactless		FlexPay 6
				Gilbarco	Wayne	Gilbarco	Wayne	Gilbarco	Wayne	Invenco
BP										
BP		V11.02 H MP3				V20.02	V20.02	V21.03	V21.03	V24.04
Chevron										
Chevron	Yes	V11.02 C (Credit)	V12.02	Yes	Yes (Ovation)	V12.02	V12.03	V20.03	V22.01	V23.01
		V11.02 Q (Debit)								
Fiserv										
Exxon	Yes	V11.01 D	V11.02 J MP1	Yes	Yes (Ovation)	V11.02 J MP1	V20.02	V20.04	V22.01	V23.01
Sunoco	Yes	V11.01 D	V11.02 J MP1	Yes	Yes (Ovation)	11.04 B MP4	V20.02	V20.04	V21.03	V23.01
Valero	Yes	V11.01 D	V11.02 J MP1	Yes	Yes (Ovation)	V11.02 J MP1	V20.02	V20.04	V21.03	V24.01
Generic	Yes	V11.01 D	V11.02 J MP1	Yes	Yes (Ovation)	V11.02 J MP1	V20.02	V20.04	V21.03	V23.01
HPS Chicago										
Generic / Growmark	V12.02	V11.02 C	V20.04	V12.02	V12.02 (Ovation)	V20.01	V22.02	V22.02	V22.0 2	V23.01
NBS										
Irving	Yes	V11.02 K MP3	V20.04	Yes	Yes (Ovation)	V12.03	V23.01	V23.01	V23.01	V23.01
Cenex	Yes	V11.02 G MP1	V20.04	Yes	Yes (Ovation)	V11.04 B MP4	V21.03 MP27	V21.03 MP27	V21.03 MP27	V23.01
Generic	Yes	V11.02 G MP1	V20.04	Yes	Yes (Ovation)	V12.03	V23.01	V23.01	V23.01	V23.01
Shell										
Shell		V10.10D				V11.04 B MP11	V20.02	V22.02	22.02	V23.01
VAPS (HPS Dallas)										
P66	Yes	V11.01 D	V11.02 Q MP6	Yes	Yes (Ovation)	V11.02 Q MP6	V20.02	V21.03 MP24	V21.03 MP24	V23.01
Marathon	Yes	V11.01 D	V11.02 Q MP6	Yes	Yes (Ovation)	V11.02 Q MP6	V20.02	V21.03	V21.03	V23.01
Citgo	Yes	V11.01 D	V11.04 B MP12	Yes	Yes (Ovation)	V11.04 B MP12	V20.02	V21.03	V21.03	V23.01
Generic	Yes	V11.01 D	V11.02 Q MP6	Yes	Yes (Ovation)	V11.02 Q MP6	V20.02	V21.03	V21.03	V23.01
WorldPay										
Generic		V11.02 G MP1	V20.02			V12.02	V22.02	V21.03	V22.02	V23.01

	Not Available		Available		In progress		To Be Determined
--	---------------	--	-----------	--	-------------	--	------------------

Passport Version	Network	Brand	Production Maintenance Pack	M5 (FlexPay II) Software	M5 (FlexPay II) EMV Contact Kernel	M7 (FlexPay IV) Software	M7 (FlexPay IV) EMV Contact Kernel	GVR CRIND EMV Contactless Support	Passport Version	Wayne IXPay Software	Wayne IXPay EMV contact Kernel	Wayne EMV Contactless Support	
21.02	BP	BP	B	MP2	03.5.10	2.11	52.12.45	3.10	No	2.8.105.104 2.8.105.118	2.4.0.0	No	
	Chevron	Chevron	A	MP3		2.09	52.11.50	3.09	M5 / M7	2.8.105.104 2.8.105.118	2.4.0.0	No	
	Fiserv	Generic	B	MP4		2.09		3.09		2.8.105.104 2.8.105.118	2.4.0.0	No	
		ExxonMobil ^[0]											
	Sunoco	A	MP2	2.11		52.12.45	3.10	No	Not Supported	Not Supported	No		
	HPS-Chicago	Generic	B					MP4	3.09	No	Not Supported	Not Supported	No
	NBS	Cenex	B	MP4			2.09	52.12.45		3.10	No	Not Supported	Not Supported
		Generic											
		Irving											
	VAPS	CITGO	B	MP2		2.11	52.12.45	3.10	No	2.8.105.104 2.8.105.118	2.4.0.0	No	
		Generic	A	MP3									
		Marathon	B	MP2									
		Phillips 66											
	WorldPay	Generic	B	MP4		2.09		3.09	No	Not Supported	Not Supported	No	

^[0] ExxonMobil prefers their locations remain on V20.04 when possible and suggests that the installation of V21.02 is only performed when required, such as to support an EDH2c that is replacing an existing EDH1 and/or EDH2 with existing PX60 hardware or the installation of new PX68 systems with an EDH2c.

IMPORTANT M7 / WAYNE IX PAY VERSION INFORMATION

If multiple versions are listed, all versions of the software contain the necessary EMV Kernel required by the payment network. It is advised to always load the latest version of software associated with the current version of Passport POS software being loaded. (e.g. Fiserv Generic 23.01 for M7 must have 52.11.53)

Gilbarco Supported Devices for V21.03

Passport Version	Network	Brand	Production Maintenance Pack	M5 (FlexPay II) Software	M5 (FlexPay II) EMV Contact Kernel	M7 (FlexPay IV) Software	M7 (FlexPay IV) EMV Contact Kernel	GVR CRIND EMV Contactless Support
21.03	BP	BP	31	03.5.10 03.6.06 ^[3]	2.11	52.12.45 ^[4]	3.10	M5 / M7
	Chevron	Chevron	22	03.5.10 ^[1]	2.09	52.11.50 ^[2]	3.09	
	Fiserv	Generic	32					
		Valero	7					
		Sunoco	20					
	Shell	Shell	32	03.5.10 03.6.06 ^[3]	2.11	52.13.14 ^[4]	3.12	
	VAPS	Generic	34					
		CITGO	34					
		Marathon	34					
		Phillips 66	32					
	WorldPay	Generic	32		2.09		3.09	
	NBS	Cenex	28					

^[1] 03.5.10 Required for M5 EMV contactless support for Fiserv and Chevron brands

^[2] 52.11.50 Required for M7 EMV contactless support

^[3] 03.6.06 Required for M5 EMV contactless support

^[4] 52.12.45 Minimum Required for M7 EMV contactless support

IMPORTANT M7 / WAYNE IX PAY VERSION INFORMATION

If multiple versions are listed, all versions of the software contain the necessary EMV Kernel required by the payment network. It is advised to always load the latest version of software associated with the current version of Passport POS software being loaded. (e.g. Fiserv Generic 23.01 for M7 must have 52.11.53)

Wayne Supported Devices for V21.03

Passport Version	Network	Brand	Production Maintenance Pack	Wayne iXPay EMV Software	Wayne iXPay EMV contact Kernel	Wayne iXPay 1 EMV Contactless (Model C150 261EA02)	Wayne iXPay 1 EMV Contactless (Model C150S_NP 2610FA02)	Wayne EMV Contactless Support
21.03	BP	BP	31	2.8.105.118 2.8.204.31 ^[5]	2.4.0.0 2.7.0.0 ^[5]	21032xx ⁽⁷⁾	21070xx ⁽⁷⁾	Yes
	Chevron	Chevron	22	2.8.105.104 2.8.105.118	2.4.0.0	Not Supported	Not Supported	No
	Fiserv	Generic	32	2.8.105.118 2.8.204.36 ^[6]	2.4.0.0 2.7.0.0 ^[6]	21032xx ⁽⁷⁾	21070xx ⁽⁷⁾	Yes
		Valero	7					
		Sunoco	20					
	Shell	Shell	32	2.8.105.104 2.8.105.118	2.4.0.0	Not Supported	Not Supported	No
	VAPS	Generic	34	2.8.105.118 2.8.204.36 ^[6]	2.4.0.0 2.7.0.0 ^[6]	21032xx ⁽⁷⁾	21070xx ⁽⁷⁾	Yes
		CITGO	34					
		Marathon	34					
		Phillips 66	32					
	WorldPay	Generic	32	Not Supported	Not Supported	Not Supported	Not Supported	No
	NBS	Cenex	28	2.8.204.36 ^[6]	2.7.0.0 ^[6]	21032xx ⁽⁷⁾	21070xx ⁽⁷⁾	Yes

^[5] Wayne iXPay 2.8.204.31 is required for EMV contactless support

^[6] Wayne iXPay 2.8.204.36 is required for EMV contactless support

^[7] Required if EMV Contactless Hardware is present

IMPORTANT M7 / WAYNE IX PAY VERSION INFORMATION

If multiple versions are listed, all versions of the software contain the necessary EMV Kernel required by the payment network. It is advised to always load the latest version of software associated with the current version of Passport POS software being loaded. (e.g. Fiserv Generic 23.01 for M7 must have 52.11.53)

Gilbarco Supported Devices for V22.01

Passport Version	Network	Brand	Production Maintenance Pack	M5 (FlexPay II) Software	M5 (FlexPay II) EMV Contact Kernel	M7 (FlexPay IV) Software	M7 (FlexPay IV) EMV Contact Kernel	GVR CRIND EMV Contactless Support
22.01	Fiserv	Generic	20	3.5.10 ^[1]	2.09	52.11.53 ^[2]	3.09	M5/M7
		Valero	12					
		ExxonMobil	20					
	Chevron	Chevron	20					

^[1] 03.5.10 Required for M5 EMV contactless support for Fiserv and Chevron brands

^[2] 52.11.53 Required for M7 EMV contactless support

Wayne Supported Devices for V22.01

Passport Version	Network	Brand	Production Maintenance Pack	Wayne iXPay Software	Wayne iXPay EMV contact Kernel	Wayne iXPay 1 EMV Contactless (Model C150 261EA02)	Wayne iXPay 1 EMV Contactless (Model C150S_NP 2610FA02)	Wayne EMV Contactless Support
22.01	Fiserv	Generic	20	2.8.204.36 ^[6]	2.7.0.0 ^[6]	21032xx ^[7]	21070xx ^[7]	Yes
		Valero	12					
		ExxonMobil	20					
	Chevron	Chevron	20					

^[6] Wayne iXPay 2.8.204.36 is required for EMV contactless support

^[7] Required if EMV Contactless Hardware is present

IMPORTANT M7 / WAYNE IX PAY VERSION INFORMATION

If multiple versions are listed, all versions of the software contain the necessary EMV Kernel required by the payment network. It is advised to always load the latest version of software associated with the current version of Passport POS software being loaded. (e.g. Fiserv Generic 23.01 for M7 must have 52.11.53)

Gilbarco Supported Devices for V22.02

Passport Version	Network	Brand	Production Maintenance Pack	M5 (FlexPay II) Software	M5 (FlexPay II) EMV Contact Kernel	M7 (FlexPay IV) Software	M7 (FlexPay IV) EMV Contact Kernel	GVR CRIND EMV Contactless Support
22.02	Fiserv	Generic	19	3.5.10 ^[1]	2.09	52.11.53 ^[2]	3.09	M5/M7
		Sunoco	10					
	WorldPay	Generic	19	03.6.06 ^[3]	2.11	52.13.14 ^[4]	3.12	
	VAPS	Generic	15					
		CITGO	15					
		Marathon	15					
		Phillips 66	15					
	HPS-Chicago	Generic	16					
	BP	BP	19		3.09			
	Shell	Shell	14		3.09			
	NBS	Cenex	8	3.09				

^[1] 03.5.10 Required for M5 EMV contactless support for Fiserv and Chevron brands

^[2] 52.11.53 Required for M7 EMV contactless support

^[3] 03.6.06 Required for M5 EMV contactless support

^[4] 52.12.45 Minimum Required for M7 EMV contactless support

Wayne Supported Devices for V22.02

Passport Version	Network	Brand	Production Maintenance Pack	Wayne iXPAY Software	Wayne iXPAY EMV contact Kernel	Wayne iXPAY 1 EMV Contactless (Model C150 261EA02)	Wayne iXPAY 1 EMV Contactless (Model C150S_NP 2610FA02)	Wayne EMV Contactless Support
22.02	Fiserv	Generic	19	2.8.204.36 ^[6]	2.7.0.0 ^[6]	21032xx ^[7]	21070xx ^[7]	Yes
		Sunoco	10					
	WorldPay	Generic	19					
	VAPS	Generic	15					
		CITGO	15					
		Marathon	15					
		Phillips 66	15					
	HPS-Chicago	Generic	16					
	BP	BP	19	2.8.204.36	2.7.0.0 ^[6]	21032xx ^[7]	21070xx ^[7]	Yes
	Shell	Shell	14	2.8.203.9	2.7.0.0 ^[6]	21032xx ^[7]	21070xx ^[7]	Yes
	NBS	Cenex	8	2.8.204.36 ^[6]	2.7.0.0 ^[6]	21032xx ^[7]	21070xx ^[7]	Yes

^[6] Wayne iXPAY 2.8.204.36 is required for EMV contactless support

^[7] Required if EMV Contactless Hardware is present

Gilbarco Supported Devices for V23.01

Passport Version	Network	Brand	Production Maintenance Pack	M5 (FlexPay II) Software	M5 (FlexPay II) EMV Contact Kernel	M7 (FlexPay IV) Software	M7 (FlexPay IV) EMV Contact Kernel	GVR CRIND EMV Contactless Support	FlexPay 6 EMV Firmware Version	FlexPay 6 Kernel Version	FlexPay 6 EMV Adapter Version	FlexPay 6 EMV Configuration Version	FlexPay 6 A2-09 EMV Contact Kernel	FlexPay 6 A2-09 Firmware	
23.01	Chevron	Chevron	33	3.5.10 ^[1]	2.09	52.11.54 ^[2]	3.09	M5/M7/ FlexPay 6	3.2.2.32 ^[5]	01.02.0010 ^[5]	01.08.0143 ^[5]	01.08.0040 ^[5]	1.02.0010 ^[5]	5.4.9 ^[5]	
	Fiserv	Generic	36												
		Sunoco	19												
		Exxon	27												
	WorldPay	Generic	36	03.6.06 ^[3]	2.09	52.13.14 ^[4]	3.09				01.08.0132 ^[5]				
	NBS	Generic	27												
		Cenex	27												
	Shell	Shell	33												01.08.0143 ^[5]
	HPS-Chicago	Generic	32		2.11	52.13.14 ^[4]	3.12								
	VAPS	Generic	27												
		CITGO	27												
		Marathon	27												
		Phillips 66	33												

^[1] 03.5.10 Required for M5 EMV contactless support for Fiserv and Chevron brands
^[2] 52.11.53 Required for M7 EMV contactless support
^[3] 03.6.06 Required for M5 EMV contactless support
^[4] 52.12.45 Minimum Required for M7 EMV contactless support
^[5] Use recommended software from the FlexPay 6 Software Download link on GOLD under Technician Resources - Applies to the following devices A2-09/M1-15

Wayne Supported Devices for V23.01

Passport Version	Network	Brand	Production Maintenance Pack	Wayne iXPay 1 Software	Wayne iXPay 1 EMV contact Kernel	Wayne iXPay 1 EMV Contactless (Model C150 261EA02)	Wayne iXPay 1 EMV Contactless (Model C150S_NP 2610FA02)	Wayne EMV Contactless Support
23.01	Chevron	Chevron	33	2.8.204.36 ^[6]	2.7.0.0 ^[6]	21032xx ^[7]	21070xx ^[7]	Yes
	Fiserv	Generic	36					
		Sunoco	19					
		Exxon	27					
	WorldPay	Generic	36					
	NBS	Generic	27					
		Cenex	27					
	Shell	Shell	33	2.8.203.9				
	HPS-Chicago	Generic	32	2.8.204.36 ^[6]				
	VAPS	Generic	27					
		CITGO	27					
		Marathon	27					
		Phillips 66	33					

^[6] Wayne iXPay 2.8.204.36 is required for EMV contactless support

^[7] Required if EMV Contactless Hardware is present

Passport Version	Network	Brand	Production Maintenance Pack	Wayne iXPay 2 EMV Software	Wayne iXPay 2 EMV contact Kernel	Wayne iXPay 2 EMV Contactless (Model C150 261EA02)	Wayne iXPay 2 EMV Contactless (Model C150S_NP 2610FA02)	Anthem UI Software	Anthem EMV Software
23.01	Chevron	Chevron	33	3.1.201.132 ^[8]	2.7.0.0	21122xx	211224xx	1.22.0.929	3.1.212.1130
	Fiserv	Generic	36						
		Sunoco	19						
		Exxon	27						
	Worldpay	Generic	36						
	NBS	Generic	27						
		Cenex	27						
	Shell	Shell	33						
	HPS-Chicago	Generic	32						
	VAPS	Generic	27						
		CITGO	27						
		Marathon	27						
		Phillips 66	33						

^[8] For Wayne Dispensers, the version of software on this matrix is the minimum requirement, however any version higher than the one specified here and available for production on the Dover portal is approved to be used unless otherwise noted here.

Gilbarco Supported Devices for V23.02

Passport Version	Network	Brand	Production Maintenance Pack	M5 (FlexPay II) Software	M5 (FlexPay II) EMV Contact Kernel	M7 (FlexPay IV) Software	M7 (FlexPay IV) EMV Contact Kernel	GVR CRIND EMV Contactless Support	FlexPay 6 Firmware Version	FlexPay 6 Kernel Version	FlexPay 6 EMV Adapter Version	FlexPay 6 EMV Configuration Version	FlexPay 6 A2-09 EMV Contact Kernel	FlexPay 6 A2-09 Firmware
23.02	WorldPay	Generic	4	03.6.06 ^[3]	2.09	52.13.14 ^[4]	3.09	M5/M7/ FlexPay 6	3.2.32 ^[5]	01.02.0010 ^[5]	01.08.0143 ^[5]	01.08.0040 ^[5]	1.02.0010 ^[5]	5.4.9 ^[5]
	NBS	Generic	4		2.11		3.12				01.08.0132 ^[5]			
	HPS-Chicago	Generic	4								01.08.0143 ^[5]			

^[2] 52.11.53 Required for M7 EMV contactless support
^[3] 03.6.06 Required for M5 EMV contactless support
^[4] 52.12.45 Minimum Required for M7 EMV contactless support
^[5] Use recommended software from the FlexPay 6 Software Download link on GOLD under Technician Resources - Applies to the following devices A2-09/M1-15

Wayne Supported Devices for V23.02

Passport Version	Network	Brand	Production Maintenance Pack	Wayne iXPAY 1 Software	Wayne iXPAY 1 EMV contact Kernel	Wayne iXPAY 1 EMV Contactless (Model C150 261EA02)	Wayne iXPAY 1 EMV Contactless (Model C150S_NP 2610FA02)	Wayne EMV Contactless Support
23.02	WorldPay	Generic	4	2.8.204.36 ^[6]	2.7.0.0 ^[6]	21032xx ^[7]	21070xx ^[7]	Yes
	NBS	Generic	4					
	HPS-Chicago	Generic	4					

^[6] Wayne iXPAY 2.8.204.36 is required for EMV contactless support
^[7] Required if EMV Contactless Hardware is present

Passport Version	Network	Brand	Production Maintenance Pack	Wayne iXPAY 2 EMV Software	Wayne iXPAY 2 EMV contact Kernel	Wayne iXPAY 2 EMV Contactless (Model C150 261EA02)	Wayne iXPAY 2 EMV Contactless (Model C150S_NP 2610FA02)
23.02	WorldPay	Generic	4	3.1.201.132 ^[8]	2.7.0.0	21122xx	211224xx
	NBS	Generic	4				
	HPS-Chicago	Generic	4				

^[8] For Wayne Dispensers, the version of software on this matrix is the minimum requirement, however any version higher than the one specified here and available for production on the Dover portal is approved to be used unless otherwise noted here.

Gilbarco Supported Devices for V24.01

Passport Version	Network	Brand	Production Maintenance Pack	M5 (FlexPay II) Software	M5 (FlexPay II) EMV Contact Kernel	M7 (FlexPay IV) Software	M7 (FlexPay IV) EMV Contact Kernel	GVR CRIND EMV Contactless Support	FlexPay 6 Firmware Version	FlexPay 6 Kernel Version	FlexPay 6 EMV Adapter Version	FlexPay 6 EMV Configuration Version	FlexPay 6 A2-09 EMV Contact Kernel	FlexPay 6 A2-09 Firmware
24.01	Fiserv	Valero	10	03.5.10 ^[1]	2.09	52.11.53 ^[2]	3.09	M5/M7/ FlexPay 6	3.2.32 ^[5]	01.02.0010 ^[5]	01.08.0143 ^[5]	01.08.0040 ^[5]	1.02.0010 ^[5]	5.4.9 ^[5]
		Marathon	6	NOT SUPPORTED	NOT SUPPORTED	52.13.14 ^[4]	3.12	M7/FlexPay 6			01.08.0132 ^[5]			
	HPS-Chicago	Generic	7	03.6.06 ^[2]	2.11			M5/M7/ FlexPay 6			01.08.0143 ^[5]			
	Worldpay	Generic	11		2.09		3.09				01.08.0143 ^[5]			
	NBS	Cenex	11								01.08.0132 ^[5]			
		Generic	11											

^[1] 03.5.10 Required for M5 EMV contactless support for Fiserv and Chevron brands
^[2] 52.11.53 Required for M7 EMV contactless support
^[3] 03.6.06 Required for M5 EMV contactless support
^[4] 52.12.45 Minimum Required for M7 EMV contactless support
^[5] Use recommended software from the FlexPay 6 Software Download link on GOLD under Technician Resources - Applies to the following devices A2-09/M1-15

Wayne Supported Devices for V24.01

Passport Version	Network	Brand	Production Maintenance Pack	Wayne iXPAY 1 Software	Wayne iXPAY 1 EMV contact Kernel	Wayne iXPAY 1 EMV Contactless (Model C150 261EA02)	Wayne iXPAY 1 EMV Contactless (Model C150S_NP 2610FA02)	Wayne EMV Contactless Support
24.01	Fiserv	Valero	10	2.8.204.36 ^[6]	2.7.0.0 ^[6]	21032xx ^[7]	21070xx ^[7]	Yes
		Marathon	6					
	HPS-Chicago	Generic	7					
	Worldpay	Generic	11					
	NBS	Cenex	11					
		Generic	11					

^[6] Wayne iXPAY 2.8.204.36 is required for EMV contactless support
^[7] Required if EMV Contactless Hardware is present

Passport Version	Network	Brand	Production Maintenance Pack	Wayne iXPay 2 EMV Software	Wayne iXPay 2 EMV contact Kernel	Wayne iXPay 2 EMV Contactless (Model C150 261EA02)	Wayne iXPay 2 EMV Contactless (Model C150S_NP 2610FA02)	Anthem UI Software	Anthem EMV Software
24.01	Fiserv	Valero	10	3.1.205.530 ^[8]	2.7.0.0	21122xx	211224xx	1.22.0.929	3.1.212.1130
		Marathon	6						
	HPS-Chicago	Generic	7						
	Worldpay	Generic	11	3.1.201.132 ^[8]					
	NBS	Cenex	11						
		Generic	11						

Gilbarco Supported Devices for V24.04

Passport Version	Network	Brand	Production Maintenance Pack	M5 (FlexPay II) Software	M5 (FlexPay II) EMV Contact Kernel	M7 (FlexPay IV) Software	M7 (FlexPay IV) EMV Contact Kernel	VIPA Version	GVR CRIND EMV Contactless Support	FlexPay 6 Firmware Version	FlexPay 6 Kernel Version	FlexPay 6 EMV Adapter Version	FlexPay 6 EMV Configuration Version	FlexPay 6 A2-09 EMV Contact Kernel	FlexPay 6 A2-09 Firmware	
24.04	BP	BP	22	03.6.06 ^[3]	2.09	52.13.14 ^[4] (Driven by BP)	3.09	Driven by BP	M5/M7/ FlexPay 6	3.2.32 ^[5]	01.02.0010 ^[5]	01.08.0143 ^[5]	01.08.0040 ^[5]	1.02.0010 ^[5]	5.4.9 ^[5]	
	VAPS	Phillips 66	23	03.6.06 ^[3]	2.11	52.13.24 ^[4] (xx.14.04_US00_05)	3.12	6.8.2.25-13							6.8.2.32.12	3.2.32 ^[5]
		CITGO	22													5.4.9 ^[5]
		Generic	23													
	HPS-Chicago	Generic	23													
	Fiserv	Generic	23	03.5.10 ^[1]	2.09	52.14.07 ^[6] (xx.14.04_US00_07)	3.12									
		ExxonMobil	23													
		Marathon	22	NOT SUPPORTED	NOT SUPPORTED											
		Sunoco	21 w/QFs	03.5.10 ^[1]	2.09											
	Shell	Shell	22	03.6.06 ^[3]	2.09	52.13.14 ^[4] (Driven by Shell)	3.09	Driven by Shell								

^[1] 03.5.10 Required for M5 EMV contactless support for Fiserv and Chevron brands
^[2] 52.11.53 Required for M7 EMV contactless support
^[3] 03.6.06 Required for M5 EMV contactless support
^[4] 52.12.45 Minimum Required for M7 EMV contactless support
^[5] Use recommended software from the FlexPay 6 Software Download link on GOLD under Technician Resources - Applies to the following devices A2-09/M1-15
^[6] 52.14.07 Required for M7 removal of Plaintext Offline Pin – Visa/Mastercard Mandate

IMPORTANT M7 / WAYNE IX PAY VERSION INFORMATION

If multiple versions are listed, all versions of the software contain the necessary EMV Kernel required by the payment network. It is advised to always load the latest version of software associated with the current version of Passport POS software being loaded. (e.g. Fiserv Generic 23.01 for M7 must have 52.11.53)

Wayne Supported Devices for V24.04

Passport Version	Network	Brand	Production Maintenance Pack	Wayne iXPay 1 Software	Wayne iXPay 1 EMV contact Kernel	Wayne iXPay 1 EMV Contactless (Model C150 261EA02)	Wayne iXPay 1 EMV Contactless (Model C150S_NP 2610FA02)	Wayne EMV Contactless Support
24.04	BP	BP	22	2.8.215.6 ^[6]	2.7.0.0 ^[6]	21032xx ^[7]	21070xx ^[7]	Yes
	VAPS	Phillips 66	23					
		CITGO	22					
		Generic	23					
	HPS-Chicago	Generic	23					
	Fiserv	Generic	23					
		ExxonMobil	23					
		Marathon	22					
		Sunoco	21 w/QFs					
	Shell	Shell	22	NOT SUPPORTED	NOT SUPPORTED	NOT SUPPORTED	NOT SUPPORTED	N0

^[6] Wayne iXPay 2.8.204.36 is required for EMV contactless support

^[7] Required if EMV Contactless Hardware is present

Passport Version	Network	Brand	Production Maintenance Pack	Wayne iXPay 2 EMV Software	Wayne iXPay 2 EMV contact Kernel	Wayne iXPay 2 EMV Contactless (Model C150 261EA02)	Wayne iXPay 2 EMV Contactless (Model C150S_NP 2610FA02)	Anthem UI Software	Anthem EMV Software			
24.04	BP	BP	22	3.1.205.530 ^[8]	2.7.0.0	21122xx	211224xx	1.22.0.929 ^[8]	3.1.212.1130 ^[8]			
	VAPS	Phillips 66	23	3.1.215.1750 ^[8]					3.1.215.1750 ^[8]			
		CITGO	22									
		Generic	23									
	HPS-Chicago	Generic	23							Fiserv	Generic	23
	ExxonMobil	23										
	Marathon	22										
	Sunoco	21 w/QFs										
	Shell	Shell	22							NOT SUPPORTED	NOT SUPPORTED	NOT SUPPORTED

^[8] For Wayne Dispensers, the version of software on this matrix is the minimum requirement, however any version higher than the one specified here and available for production on the Dover portal is approved to be used unless otherwise noted here.

Gilbarco Supported Devices for V25.01

Passport Version	Network	Brand	Production Maintenance Pack	M5 (FlexPay II) Software	M5 (FlexPay II) EMV Contact Kernel	M7 (FlexPay IV) Software	M7 (FlexPay IV) EMV Contact Kernel	VIPA Version	GVR CRIND EMV Contactless Support	FlexPay 6 Firmware Version	FlexPay 6 Kernel Version	FlexPay 6 EMV Adapter Version	FlexPay 6 EMV Configuration Version	FlexPay 6 A2-09 EMV Contact Kernel	FlexPay 6 A2-09 Firmware
25.01	Worldpay	Generic	9	NOT SUPPORTED	NOT SUPPORTED	52.14.07 ^[6] (xx.13.10_US00_05)	3.09	6.8.2.25-13	M7/ FlexPay 6	3.2.32 ^[5]	01.02.0010 ^[5]	01.08.0143 ^[5]	01.08.0040 ^[5]	1.02.0010 ^[5]	5.4.9 ^[5]

^[1] 03.5.10 Required for M5 EMV contactless support for Fiserv and Chevron brands
^[2] 52.11.53 Required for M7 EMV contactless support
^[3] 03.6.06 Required for M5 EMV contactless support
^[4] 52.12.45 Minimum Required for M7 EMV contactless support
^[5] Use recommended software from the FlexPay 6 Software Download link on GOLD under Technician Resources - Applies to the following devices A2-09/M1-15
^[6] 52.14.07 Required for M7 removal of Plaintext Offline Pin – Visa/Mastercard Mandate

Wayne Supported Devices for V25.01

Passport Version	Network	Brand	Production Maintenance Pack	Wayne iXPAY 1 Software	Wayne iXPAY 1 EMV contact Kernel	Wayne iXPAY 1 EMV Contactless (Model C150 261EA02)	Wayne iXPAY 1 EMV Contactless (Model C150S_NP 2610FA02)	Wayne EMV Contactless Support
25.01	Worldpay	Generic	9	2.8.215.6 ^[6]	2.7.0.0 ^[6]	21032xx ^[7]	21070xx ^[7]	Yes

^[6] Wayne iXPAY 2.8.204.36 is required for EMV contactless support
^[7] Required if EMV Contactless Hardware is present

Passport Version	Network	Brand	Production Maintenance Pack	Wayne iXPAY 2 EMV Software	Wayne iXPAY 2 EMV contact Kernel	Wayne iXPAY 2 EMV Contactless (Model C150 261EA02)	Wayne iXPAY 2 EMV Contactless (Model C150S_NP 2610FA02)	Anthem UI Software	Anthem EMV Software
25.01	Worldpay	Generic	9	3.1.215.1750 ^[8]	2.7.0.0	21122xx	211224xx	1.22.0.929 ^[8]	3.1.215.1750 ^[8]

^[8] For Wayne Dispensers, the version of software on this matrix is the minimum requirement, however any version higher than the one specified here and available for production on the Dover portal is approved to be used unless otherwise noted here.