

To scale transformer max voltage increase R1 and R2.
EXAMPLES
36V ac : R1=150ohm 3W, R42=82ohm 2W

To scale the current add 1 power transistor and 2 resistors every 2A. Furthermore, the values of R12 and R23 must be proportionally decreased as well as appropriately modifying the firmware. L1 will also have to withstand the desired current.

EXAMPLES

5 final transistor (10A) R23=15k and R24=1500
2 final transistor (3A) R23=22k and R24=2700

