P. Lavanya 1665

Do If there is a faiture in leak test in battery!

-> We need to volise non-conformence and take correctiv action

- > For non-conformity, take actions and correct it and review the Effectiveness of the corrective action taken.
- -> To Stop the non-conformance:

9. Review & analyze the non-conformance document.

11. Verify weather the Same non-conformity exists before.

> In AS9100D, this clause comes under clause 10".
"Improvement".

(b) > First, raise a non-conformance Cfor the followe of the leak test).

-) Deal with consequence of the pan-confermance.

-> Take action to Eliminate the cause/failure.

- update any risks oppurtunties raised during planning and make changes to the OMS.

To raise a non-conformance, "quality control" (pc) is responsible.

Production. Design & Devolpment Cif there necessary), and quality departments are involved in this Non-conformance.

20 > Purchase department %/Stores is responsible for the counterfeit.

-> Stores need (Ao check the material cor) Product while receiving it from the supplier quality need to inspect the product in prior.

If the product/Material clossiff match the Specification given by the organisation. Beject the those material/Product.

-) When & counterfiel is found during the process, the

production team need to submit it to p.c. -> quality need to verify the product & reject the makerial.

(b) -> Purchase:

9. Should common reale with the supplier regarding material/products.

ii. After receiving of indent, need to verify whether the supplier can mouch the specification given by the organisoration.

-> quality Control:

i. The ac department need to inspect the invocand material as

per the Specifications / chavoings.

If the material is Accepted, Submit the materials to stoves with acceptance Sticker.

in. If rejected. Submit with Red Sticker

-> Stores:

9. Need the verify the inward material while receiving.

-> Production:

1. Need the Submit counterfest product to the p.c.

@ quarountine and reporting of defected counterfeit part.

-) Counterfeit part comes under clause 18.1.4- prevention of counterfiet parts".

-) To prevent counterflet parts;

1. Training the appropriate persons In the awareness Verification and test methodologies to detect counterfiet parts.

- (2
- 3 When a new Environmental regulation impacts the use of Specific Chemicals.
 - a Analysis and reportency of occured Events affecting
 - Safety.
 Communicating these Events with the training Persons.
 - 6 Customer communication:
 - -) Should provide information related to chemical.
 - Establishing Specific requirements for contingency actions.

 The organisation show hegotiate a mutually acceptable requirement with the customer.
 - The organisation Shall Ensure Hoort relevant documented information is amenaed, and the relevant persons are made a name of conduction, DSD and DC) of the changed requirements.
- De if the customer requirements cannot be met or comonly partially be met, the organisation shoul negotiate quantum acceptable requirement with the costomer.
 - The organisation show retain documented information, as applicable.
 - 1. On the results of the review.
 - (2. On any new requirements for products & Services.

3

The organisation can also consider as design and devolpment inputs other information such as benchmarking, External provider of feedback, internally generated data and in-service data.

The organisation shall divide the D&D Effort into distinct activities and, for Each activity, clefine the tasks, necresary resources, responsibilities, design content & inputs and outpots.

@ Clause 8.3.5 Design and devolpment outputs".

-> the organisation shall retain documented information on design and devolpment outputs". That can include.

1. Meet the Enplit requirement

/ a. Include Reference monitoring and measuring requirement.

3. Specify the characteristicts of products and Services.

(Fa) Communicating the different types of Supplier's, so Whoever the Specification's are mouching with our organisation's Specification.

Hyper of Supplier's, so who be described and order to that Supplier.

(8) CHOOSE THE CORRECT ANSWER

1. A 2. E 3. A/4. A