Name: M. BALARAMA MURTY.

frze-1

ID: 1641

1. a. Identity and Segregate the failed bettery and fix proper babeling Tag.

Investigate cause of failure

· guplement copyrective action i.e. Clarge of Design, Materials, process adjustments etc

Stop further production

After Corrective are implemented to re-perform the Leak Fest to vority Confliance.

Maintain documentation of Leak Text failures

Clause 8.7 - Control of NonConfirming outputs.

Clause 10:2 - work Contirmity and corrective action.

Clause & 5.1 - Control of production and Service Probation.

Clause 8.6 - beloase to product, and Services.

clause 6.1 - Actions to address, historadas opportunities.

- Reacise hisk Analysis and mitigation Stategies

Entere All Documentation its reviewed and Approved.

Conduct Internal Audit to Verify effectiveness.

Respublishe for Each Stop is - operator Canality Impector production guchorge.

Control ... page 2

- Effect of Counterfeit parts on production.
  - · production failure may coule malfunctions.

· Defective may compromise product integrity.

- gucreasing costs is Additional Tets, the work, the walls etc.
- penalties violations of Industry Standards.
- organisation Reputation danage, Lobe Looke of Cerstomers, grunt and credibility etc.

(2) Clause 8.1.4 - prevention of Counter ports

Requirements - using Approved Suppliers Authorised Distributors Dealors.

- Identifying and miligating hisks associated with Contra Counterfeet Ports.

- Training personnel on counterfeit & Itams abouteress.
- Reposting when detected.

· Responsible Departments and Roles: -

- purchase - procure ports only from Approved & Authorized & Manufacturer Cortified

Quality Sources.

Sources.

Performs verification &
Testing.

- Engineering Assist to find authorisity and other Solutions
- production Ensure Approved parts only are When Alsberry.

Contd ... (2)

The second secon and the second of the second o 7----The second second 

- Actions to betaleen on prevent counterfeit parts:
  Dead With AS 9100 Certified suppliery and Truston
  - · Conduct gegular incoming graspection, Festings. Ret.
  - Educate Conclorer persons on how to detect counterfeit
  - · naintain proper becords for parts traceability.
  - Lefort suspected counterfeit Components.
    - gutooms internal teams customers and
    - prepare boot cause Analysis and findout how these parts received.
- 4. Cerstoner Complaints about Thermal Bettery fairlevers.
  - helponsible Departments:
    - . Q. A. Start govestigation, Root Cause Analysis and corrective at action implementation.
- DED Analyse Design document performance issue.

  St. Production cross check process deviations defects.

  - · purchase check Supplies-related material detects.
  - . Marketing Communicate to Management, Cultoner.
  - Steps to Address the Complaints.
  - Acknowledge the Complaint

    Acknowledge the Complaint

    Lecord the issue in the NCL System.

    Communicate receipt of Complaint to the Customer.

Contd. 4

Ada di Selevino di -----

- corrective & preventive actions.
  - . Define corrective actions to fix the immediate issue
  - gomploment preventive measures to avoid recurpance
  - Volidate & Affectiveness through Re-Testing & Boccell Andits.
  - polements
    - · update se cooks, failure Avalysis Reports, well etc.
    - Ensure Complainte with AS91000 documentation geautyements.
    - Clause 8.7 Ensuring failed products are identified.
    - Clause 10.2 Addressing Customer Complaint through Corrective action procedles.
      - clude 8.2 It failure is due to Delign, Jerischidate Design document.
      - Clause & 4 Supplier Quality Control.
      - . NCh Failure Avadylis Report, Supplier Audit Necessary Documents! Reports, lisk Adselsment Reports, Test & guspection beforts, Castomer Comptaint Log Sheets etc

Conto ... (5)

e X "Take to see the see the see The state of the s ski ir sada parasan ir samar da sadaga s and the same of th to the following - 1 - 1 - 1

- Identifying the Alternative natorials,

- · Explore New Vendors and Consult materia related Scientists.
- · Ensure the alternative meets thermal mechanical and Chemical performance Specifications.
- · Evaluate past studies and Test date on possible replacements.
- Validation Stops.
  - . Ensure new notorial functions within existing bettery Deligns inthout mosor modifications.
  - · Validate, manifactortability before full deployment.

Communicate potential Delays.

- . Interm to customers as soon as possible about the nationaly Phaleout, Potential impacts
- To find and validate alternatives invite timelines.
- Engage with customers for concerns, additional reaccidentent in the validation process.

haraging lisks!

To talow strict Testing protocols for reliability, Thermal Stability, failure analysis etc. Identify multiple suppliers to prevent

Li Single Source dependency. Ensure new materials meets all Industry and Satte Standards

Contidu. 6

a stroping our all participation the state of broken or our re-- Arder - Karparet pp. t detail a bragade and are applicable and are a 

Name [ ID'. 1641

SECTION -21

AU A, BBC

ABCV