

acct@alltechfuel.com 850 Brookline Katy, Texas 77494

Invoice

Date	Invoice #
5/25/2021	21-2147 SV.

Bill To	
HITEC Power Protection	
Bradley Hill	
25707 Southwest Frwy	
Rosenberg, TX. 77471	
3	

Ship To	
ATT Spectrum 10101 Spectrum Drive Austin, TX. 78717	
	F 1

P.O. Number	Terms	Rep	Ship	Via	F.O.B.	Project
Bradley Hill	Due on receipt	TAM	5/4/2021	our equipm		ATT - 10101 Spectrum- A

Quantity	Item Code	Description		Price Each	Amount
1 4 304	Customer Charg Customer Charg Technician Travel Travel Time		TRUM G BELLY	38.72 11.11 95.00 0.85 65.00	38.72T 11.11T 380.00T 258.40 390.00T
nk you for t	he opportunity to be	of service	Subtotal		\$1,078.23

Thank you for the opportunity to be of service	Subtotal	\$1,078.23
	Sales Tax (8.25%)	\$67.64
	Payments/Credits	\$0.00
	Total	\$1,145.87
	Balance Due	\$1,145.87



TICKET #	SERVICE DATE	PRIORITY
Service Ticket #20009: Bradley Hill(Completed)	05/04/2021 10:00 AM	Normal

Subject: ATT SPECTRUM

TECHNICIAN: Shawn Hambalek Phone: (832) 285-2510

CUSTOMER

HITEC POWER PROTECTION Bradley Hill 25707 SOUTHWEST FRWY ROSENBERG, TX 77471

SERVICE ADDRESS

10101 Spectrum Drive Austin, TX 78717

DESCRIPTION

talking to client we had several leaking fittings, got him to shut down power to fuel pumps and observed leaks at 3 fittings. First i verified for tightness, they were all 3 loose, i then put down diapers incase of spillage and loosened fittings completely and cleaned threads, then tightened fittings to proper torque and had him restart pumps to verify no leakage, and there wasn't any leakage. Then they had a probe the wanted removed and changed out of day tank, had power disconnected again from pumps and I removed probe and replaced with new one and rewiring.

was having conversation with ATT rep and he asked if we could put a riser in for him to be able to stick the belly tank, so I confirmed with client and he said go ahead, so went and purchased a nipple and cap and drilled hole in access panel for riser then attached riser. Asked client if there was anything else we could do for him and he advice there was not. Got clients information and came back to shop.

Subject	Qty	Total
2'X 2" NIPPLE NIPPLE FOR RISER	1	\$38.72
2" PIPE CAP	1	\$11.11
Labor- Technician	4	\$380.00
TRAVEL - MILEAGE HCA MK MILEAGE / TRUCK WEAR AND TEAR	304	\$258.40



Subject	Qty	Total
TRVL - Labor travel labor	6	\$390.00

Service Fee: \$1,078.23

SERVICE NOTE

fix leaks on fuel lines going to belly tank and build riser for client start time 10am end time 2pm

APPROVAL	
Signature:	1

PHOTOS











