Error Summary - Initial Diagnosis

Date: October 20, 2025

Observed Errors

1. Zones Status API Error (500 Internal Server Error)

• Endpoint: /api/audio-processor/2910c2c1-3c00-4c92-b02b-68390db910bf/zones-status

• Status Code: 500

• Error Message: "Failed to fetch zones status from Atlas processor"

• Impact: Audio Zone Control page shows "Configuration Error"

2. Video Input Selection API Error (404 Not Found)

• **Endpoint**: /api/matrix/video-input-selection

• Status Code: 404

• Error Message: "Not Found"

• Impact: Video matrix functionality unavailable

3. Configuration Loading Error

• **Error**: "Error fetching dynamic Atlas configuration: Error: Failed to fetch zones status from Atlas processor"

• Location: Browser console

• Impact: Application cannot load Atlas configuration

Network Information

• **Application Server**: 24.123.87.42:3001

• Atlas Processor IP: 192.168.5.101

Atlas Processor Port: 5321 (TCP JSON-RPC)
Atlas Web Interface: http://192.168.5.101

Next Steps

- 1. Document Atlas configuration from web interface
- 2. Test network connectivity from application server to Atlas processor
- 3. Review API route implementations
- 4. Fix zones-status endpoint
- 5. Create or fix video-input-selection endpoint
- 6. Add verbose logging for debugging