Acer Lathe

Red Tool: Tool test required
Extra: An **additional** tool test is required beyond the *Intro to Lathe* class to use this lathe independently.

Materials List

☞ If your material is **not** listed below or if in doubt, check w/the shop lead. Ignorance is not an excuse.

Acceptable

- ✓ Steel – mild or annealed*
- ✓ Stainless steel
- ✓ Non-ferrous metals
  - ✓ aluminum
  - ✓ brass
  - ✓ bronze
  - ✓ copper
- ✓ Plastics
  - ✓ acetal
  - ✓ Delrin
  - ✓ HDPE
  - ✓ & similar

Special Method
Ask Shop Lead

- ✓ Steel – hardened
- ✓ Cast iron, Dura-Bar
- ✓ Titanium

Not Allowed

- ✘ Grinding
- ✘ Extensive filing
- ✘ Extensive sanding
- ✘ Beryllium or Beryllium alloy
- ✘ Composite materials with:
  - ✘ Silica (glass)
  - ✘ Kevlar
  - ✘ Tungsten
  - ✘ or other abrasives
- ✘ Graphite
- ✘ GR10
- ✘ Fiberglass
- ✘ Magnesium

* Hardness check: The steel is mild or annealed if it can be filed. The steel is hardened if the file skates across the surface, or doesn't remove material. Some pieces are coated so be sure to test the shiny, silver metal underneath it.

Rev. V1.0 on 6/27/2026