National Transportation Safety Board
Aviation Incident Factual Report

Location:	Jakarta, Indonesia	**Incident Number:**	DCA08WA016
Date & Time:	11/21/2007, 0001 UTC	**Registration:**	
Aircraft:	Boeing B737-400	**Aircraft Damage:**	Minor
Defining Event:		**Injuries:**	2 None
Flight Conducted Under:	Non-U.S., Commercial		

On November 21, 2007, a Batavia airlines B737-400 returned to Jakarta-Sukarno-Hatta airport after experiencing a loss of hydraulic pressure. Upon landing, an upper wing panel was found missing, and adjacent hydraulic tubing was damaged. Initial reports indicate that airplane had just undergone rotuine maintenance in the area and some fasteners were not reinstalled.

This investigation is being conducted by the National Transportation Safety Committee of Indonesia.

Republic of Indonesia

Ministry of Communications

National Transportation Safety Committee

Gedung Karsa Lt. 7

Departemen Perhubungan

Jalan Medan Merdeka Barat No. 8

Jakarta 10110 - Indonesia

Aircraft and Owner/Operator Information

Aircraft Make:	Boeing	**Registration:**	
Model/Series:	B737-400	**Aircraft Category:**	Airplane
Year of Manufacture:		**Amateur Built:**	No
Airworthiness Certificate:		**Serial Number:**	
Landing Gear Type:		**Seats:**	
Date/Type of Last Inspection:		**Certified Max Gross Wt.:**	
Time Since Last Inspection:		**Engines:**	
Airframe Total Time:		**Engine Manufacturer:**	
ELT:		**Engine Model/Series:**	
Registered Owner:		**Rated Power:**	
Operator:		**Operating Certificate(s) Held:**	None

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual Conditions	**Condition of Light:**	
Observation Facility, Elevation:		**Distance from Accident Site:**	
Observation Time:		**Direction from Accident Site:**	
Lowest Cloud Condition:		**Visibility**	
Lowest Ceiling:		**Visibility (RVR):**	
Wind Speed/Gusts:	/	**Turbulence Type Forecast/Actual:**	/
Wind Direction:		**Turbulence Severity Forecast/Actual:**	/
Altimeter Setting:		**Temperature/Dew Point:**	
Precipitation and Obscuration:			
Departure Point:	Jakarta	**Type of Flight Plan Filed:**	IFR
Destination:	UNK	**Type of Clearance:**	
Departure Time:	UTC	**Type of Airspace:**	

Airport Information

Airport:		**Runway Surface Type:**	
Airport Elevation:		**Runway Surface Condition:**	
Runway Used:		**IFR Approach:**	
Runway Length/Width:		**VFR Approach/Landing:**	

Wreckage and Impact Information

Crew Injuries:	2 None	**Aircraft Damage:**	Minor
Passenger Injuries:	N/A	**Aircraft Fire:**	
Ground Injuries:	N/A	**Aircraft Explosion:**	
Total Injuries:	2 None	**Latitude, Longitude:**	

Administrative Information

Investigator In Charge (IIC):	William English
Additional Participating Persons:	
Investigation Docket:	NTSB accident and incident dockets serve as permanent archival information for the NTSB's investigations. Dockets released prior to June 1, 2009 are publicly available from the NTSB's Record Management Division at pubinq@ntsb.gov, or at 800-877-6799. Dockets released after this date are available at http://dms.ntsb.gov/pubdms/.