National Transportation Safety Board
Aviation Accident Final Report

Location:	Wasilla, AK	**Accident Number:**	ANC08CA022
Date & Time:	11/28/2007, 1715 AST	**Registration:**	N8965R
Aircraft:	Aeronca 7JC	**Aircraft Damage:**	Substantial
Defining Event:		**Injuries:**	1 None
Flight Conducted Under:	Part 91: General Aviation - Personal		

Analysis

The private certificated pilot was landing a tundra tire, and tailwheel-equipped airplane on an asphalt surfaced runway during a Title 14, CFR Part 91, personal flight. During the landing roll, he reported that he applied the brakes and the airplane nosed over. The airplane received structural damage to the wings and the vertical stabilizer. In the Pilot/Operator Aircraft Accident Report (NTSB Form 6120.1) submitted by the pilot, he indicated that there was no mechanical malfunction with the airplane. In the optional safety recommendation portion of the form, (How could this accident have been prevented?), the pilot stated in part: "maybe longer roll."

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: The pilot's excessive application of the airplane's brakes during the landing roll, which resulted in a nose-over.

Findings

Occurrence #1: NOSE OVER
Phase of Operation: LANDING - ROLL

Findings
1. TERRAIN CONDITION - RUNWAY
2. (C) BRAKES(NORMAL) - EXCESSIVE - PILOT IN COMMAND

Factual Information

Pilot Information

Certificate:	Private	**Age:**	40, Male
Airplane Rating(s):	Single-engine Land	**Seat Occupied:**	
Other Aircraft Rating(s):	None	**Restraint Used:**	Seatbelt, Shoulder harness
Instrument Rating(s):	Airplane	**Second Pilot Present:**	
Instructor Rating(s):		**Toxicology Performed:**	
Medical Certification:	Class 3	**Last FAA Medical Exam:**	10/01/2006
Occupational Pilot:		**Last Flight Review or Equivalent:**	
Flight Time:	204 hours (Total, all aircraft), 23 hours (Total, this make and model), 23 hours (Last 90 days, all aircraft), 10 hours (Last 30 days, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	Aeronca	**Registration:**	N8965R
Model/Series:	7JC	**Aircraft Category:**	Airplane
Year of Manufacture:		**Amateur Built:**	No
Airworthiness Certificate:	Normal	**Serial Number:**	7JC-11
Landing Gear Type:	Tailwheel	**Seats:**	
Date/Type of Last Inspection:		**Certified Max Gross Wt.:**	
Time Since Last Inspection:		**Engines:**	1 Reciprocating
Airframe Total Time:		**Engine Manufacturer:**	Continental
ELT:		**Engine Model/Series:**	C90-12F
Registered Owner:	Terry J. Miracle	**Rated Power:**	
Operator:	Terry J. Miracle	**Operating Certificate(s) Held:**	None

Meteorological Information and Flight Plan

Conditions at Accident Site:	Instrument Conditions	**Condition of Light:**	Night/Bright
Observation Facility, Elevation:		**Distance from Accident Site:**	
Observation Time:		**Direction from Accident Site:**	
Lowest Cloud Condition:		**Visibility**	
Lowest Ceiling:		**Visibility (RVR):**	
Wind Speed/Gusts:	/	**Turbulence Type Forecast/Actual:**	/
Wind Direction:		**Turbulence Severity Forecast/Actual:**	/
Altimeter Setting:		**Temperature/Dew Point:**	
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	Chugiak, AK (PABV)	**Type of Flight Plan Filed:**	None
Destination:	Wasilla, AL (PAWS)	**Type of Clearance:**	None
Departure Time:		**Type of Airspace:**	

Airport Information

Airport:	Wasilla (PAWS)	**Runway Surface Type:**	Asphalt
Airport Elevation:		**Runway Surface Condition:**	Dry
Runway Used:	21	**IFR Approach:**	None
Runway Length/Width:		**VFR Approach/Landing:**	

Wreckage and Impact Information

Crew Injuries:	1 None	**Aircraft Damage:**	Substantial
Passenger Injuries:	N/A	**Aircraft Fire:**	None
Ground Injuries:	N/A	**Aircraft Explosion:**	
Total Injuries:	1 None	**Latitude, Longitude:**	61.571667, -149.540278

Administrative Information

Investigator In Charge (IIC):	Scott Erickson	**Report Date:**	01/31/2008
Additional Participating Persons:			
Publish Date:			
Note:	This accident report documents the factual circumstances of this accident as described to the NTSB.		
Investigation Docket:	NTSB accident and incident dockets serve as permanent archival information for the NTSB's investigations. Dockets released prior to June 1, 2009 are publicly available from the NTSB's Record Management Division at pubinq@ntsb.gov, or at 800-877-6799. Dockets released after this date are available at http://dms.ntsb.gov/pubdms/.		

The National Transportation Safety Board (NTSB), established in 1967, is an independent federal agency mandated by Congress through the Independent Safety Board Act of 1974 to investigate transportation accidents, determine the probable causes of the accidents, issue safety recommendations, study transportation safety issues, and evaluate the safety effectiveness of government agencies involved in transportation. The NTSB makes public its actions and decisions through accident reports, safety studies, special investigation reports, safety recommendations, and statistical reviews.

The Independent Safety Board Act, as codified at 49 U.S.C. Section 1154(b), precludes the admission into evidence or use of any part of an NTSB report related to an incident or accident in a civil action for damages resulting from a matter mentioned in the report. A factual report that may be admissible under 49 U.S.C. § 1154(b) is available here.