National Transportation Safety Board
Aviation Accident Final Report

Location:	Santa Ana, CA	**Accident Number:**	SEA08CA056
Date & Time:	12/31/2007, 1215 PST	**Registration:**	N2800D
Aircraft:	Piper PA-12	**Aircraft Damage:**	Substantial
Defining Event:		**Injuries:**	2 None
Flight Conducted Under:	Part 91: General Aviation - Instructional		

Analysis

The pilot was receiving dual instruction from the flight instructor for the purpose of receiving a tail wheel endorsement. He had accumulated a total of 7 hours tail wheel instruction in the accident airplane. The flight instructor reported that during the landing roll, the airplane yawed to the right and entered a ground loop which collapsed the left main landing gear.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: The failure of the student to maintain directional control during landing and the flight instructor's inadequate supervision of the flight.

Findings

Occurrence #1: LOSS OF CONTROL - ON GROUND/WATER
Phase of Operation: LANDING - ROLL

Findings
1. (C) DIRECTIONAL CONTROL - NOT MAINTAINED - DUAL STUDENT
2. (C) SUPERVISION - INADEQUATE - PILOT IN COMMAND(CFI)
3. GROUND LOOP/SWERVE - ENCOUNTERED

Occurrence #2: MAIN GEAR COLLAPSED
Phase of Operation: LANDING - ROLL

Findings
4. TERRAIN CONDITION - RUNWAY

Factual Information

Flight Instructor Information

Certificate:	Flight Instructor; Commercial	**Age:**	68, Male
Airplane Rating(s):	Single-engine Land; Single-engine Sea	**Seat Occupied:**	
Other Aircraft Rating(s):	None	**Restraint Used:**	Seatbelt, Shoulder harness
Instrument Rating(s):	Airplane	**Second Pilot Present:**	Yes
Instructor Rating(s):	Airplane Single-engine; Instrument Airplane	**Toxicology Performed:**	
Medical Certification:	Class 2	**Last FAA Medical Exam:**	06/01/2007
Occupational Pilot:		**Last Flight Review or Equivalent:**	
Flight Time:	7784 hours (Total, all aircraft), 6 hours (Total, this make and model), 117 hours (Last 90 days, all aircraft), 44 hours (Last 30 days, all aircraft)		

Student Pilot Information

Certificate:	Airline Transport; Commercial	**Age:**	52, Male
Airplane Rating(s):	Multi-engine Land; Single-engine Land; Single-engine Sea	**Seat Occupied:**	
Other Aircraft Rating(s):	None	**Restraint Used:**	Seatbelt, Shoulder harness
Instrument Rating(s):	Airplane	**Second Pilot Present:**	Yes
Instructor Rating(s):		**Toxicology Performed:**	
Medical Certification:	Class 3	**Last FAA Medical Exam:**	05/01/2007
Occupational Pilot:		**Last Flight Review or Equivalent:**	
Flight Time:	2303 hours (Total, all aircraft), 7 hours (Total, this make and model), 70 hours (Last 90 days, all aircraft), 10 hours (Last 30 days, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	Piper	**Registration:**	N2800D
Model/Series:	PA-12	**Aircraft Category:**	Airplane
Year of Manufacture:		**Amateur Built:**	No
Airworthiness Certificate:	Normal	**Serial Number:**	12-1637
Landing Gear Type:	Tailwheel	**Seats:**	
Date/Type of Last Inspection:		**Certified Max Gross Wt.:**	
Time Since Last Inspection:		**Engines:**	1 Reciprocating
Airframe Total Time:		**Engine Manufacturer:**	Lycoming
ELT:		**Engine Model/Series:**	O-320
Registered Owner:	On file	**Rated Power:**	
Operator:	On file	**Operating Certificate(s) Held:**	None

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual Conditions	**Condition of Light:**	Day
Observation Facility, Elevation:	SNA, 40 ft msl	**Distance from Accident Site:**	0 Nautical Miles
Observation Time:	1153 PST	**Direction from Accident Site:**	
Lowest Cloud Condition:	Clear	**Visibility**	4 Miles
Lowest Ceiling:	None	**Visibility (RVR):**	
Wind Speed/Gusts:	3 knots /	**Turbulence Type Forecast/Actual:**	/
Wind Direction:	200°	**Turbulence Severity Forecast/Actual:**	/
Altimeter Setting:	30.09 inches Hg	**Temperature/Dew Point:**	19°C / -14°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	Santa Ana, CA (SNA)	**Type of Flight Plan Filed:**	None
Destination:	(SNA)	**Type of Clearance:**	VFR
Departure Time:	PST	**Type of Airspace:**	

Airport Information

Airport:	John Wayne - Orange County (SNA)	**Runway Surface Type:**	Asphalt
Airport Elevation:		**Runway Surface Condition:**	Dry
Runway Used:	19L	**IFR Approach:**	None
Runway Length/Width:	2887 ft / 75 ft	**VFR Approach/Landing:**	

Wreckage and Impact Information

Crew Injuries:	2 None	**Aircraft Damage:**	Substantial
Passenger Injuries:	N/A	**Aircraft Fire:**	None
Ground Injuries:	N/A	**Aircraft Explosion:**	
Total Injuries:	2 None	**Latitude, Longitude:**	33.675556, -117.868056

Administrative Information

Investigator In Charge (IIC):	Georgia R Struhsaker	**Report Date:**	02/28/2008
Additional Participating Persons:			
Publish Date:			
Note:	This accident report documents the factual circumstances of this accident as described to the NTSB.		
Investigation Docket:	NTSB accident and incident dockets serve as permanent archival information for the NTSB's investigations. Dockets released prior to June 1, 2009 are publicly available from the NTSB's Record Management Division at pubinq@ntsb.gov, or at 800-877-6799. Dockets released after this date are available at http://dms.ntsb.gov/pubdms/.		

The National Transportation Safety Board (NTSB), established in 1967, is an independent federal agency mandated by Congress through the Independent Safety Board Act of 1974 to investigate transportation accidents, determine the probable causes of the accidents, issue safety recommendations, study transportation safety issues, and evaluate the safety effectiveness of government agencies involved in transportation. The NTSB makes public its actions and decisions through accident reports, safety studies, special investigation reports, safety recommendations, and statistical reviews.

The Independent Safety Board Act, as codified at 49 U.S.C. Section 1154(b), precludes the admission into evidence or use of any part of an NTSB report related to an incident or accident in a civil action for damages resulting from a matter mentioned in the report. A factual report that may be admissible under 49 U.S.C. § 1154(b) is available here.