National Transportation Safety Board
Aviation Accident Final Report

Location:	Orlando, FL	**Accident Number:**	MIA08CA022
Date & Time:	11/28/2007, 1430 EST	**Registration:**	N148ND
Aircraft:	Piper PA-28-161	**Aircraft Damage:**	Substantial
Defining Event:		**Injuries:**	1 None
Flight Conducted Under:	Part 91: General Aviation - Instructional		

Analysis

The pilot stated that he was practicing patterns. It was his third one. He was making a short field landing. As soon as he landed on the numbers, put the flaps down, carburetor heat off, tapped the brakes gently along with pulling the yoke back slowly, he felt the nose entering the grassy area. He tried to control it with the rudder but couldn't fix that. Finally he stopped in the middle of the grassy area. He then brought the plane to the taxiway at 15 and switched off the engine. The student pilot stated there were no mechanical failures or malfunctions to the airplane or any of its systems prior to the accident.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: The student pilot's failure to maintain directional control during landing.

Findings

Occurrence #1: LOSS OF CONTROL - ON GROUND/WATER
Phase of Operation: LANDING - ROLL

Findings
1. (C) DIRECTIONAL CONTROL - NOT MAINTAINED - PILOT IN COMMAND

Occurrence #2: ON GROUND/WATER COLLISION WITH OBJECT
Phase of Operation: LANDING - ROLL

Findings
2. OBJECT - SIGN

Factual Information

Student Pilot Information

Certificate:	Student	**Age:**	19, Male
Airplane Rating(s):	Single-engine Land	**Seat Occupied:**	
Other Aircraft Rating(s):	None	**Restraint Used:**	Seatbelt, Shoulder harness
Instrument Rating(s):	None	**Second Pilot Present:**	
Instructor Rating(s):		**Toxicology Performed:**	
Medical Certification:	Class 2	**Last FAA Medical Exam:**	10/01/2007
Occupational Pilot:		**Last Flight Review or Equivalent:**	
Flight Time:	39 hours (Total, all aircraft), 39 hours (Total, this make and model)		

Aircraft and Owner/Operator Information

Aircraft Make:	Piper	**Registration:**	N148ND
Model/Series:	PA-28-161	**Aircraft Category:**	Airplane
Year of Manufacture:		**Amateur Built:**	No
Airworthiness Certificate:	Normal	**Serial Number:**	2841338
Landing Gear Type:	Tricycle	**Seats:**	
Date/Type of Last Inspection:		**Certified Max Gross Wt.:**	
Time Since Last Inspection:		**Engines:**	1 Reciprocating
Airframe Total Time:		**Engine Manufacturer:**	Lycoming
ELT:		**Engine Model/Series:**	O-320-D3G
Registered Owner:	Euro 2000 INC	**Rated Power:**	
Operator:	Orlando Flight School	**Operating Certificate(s) Held:**	None

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual Conditions	**Condition of Light:**	Day
Observation Facility, Elevation:	KISM	**Distance from Accident Site:**	
Observation Time:	1348	**Direction from Accident Site:**	
Lowest Cloud Condition:	Scattered / 2500 ft agl	**Visibility**	10 Miles
Lowest Ceiling:	None	**Visibility (RVR):**	
Wind Speed/Gusts:	4 knots /	**Turbulence Type Forecast/Actual:**	/
Wind Direction:	120°	**Turbulence Severity Forecast/Actual:**	/
Altimeter Setting:	30.1 inches Hg	**Temperature/Dew Point:**	27°C / 21°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	Kissimmee, FL (KISM)	**Type of Flight Plan Filed:**	None
Destination:	Kissimmee, FL	**Type of Clearance:**	None
Departure Time:	EST	**Type of Airspace:**	

Airport Information

Airport:	Kissimmee Gateway (KISM)	**Runway Surface Type:**	Asphalt
Airport Elevation:		**Runway Surface Condition:**	Dry
Runway Used:	15	**IFR Approach:**	None
Runway Length/Width:	6000 ft / 100 ft	**VFR Approach/Landing:**	Traffic Pattern

Wreckage and Impact Information

Crew Injuries:	1 None	**Aircraft Damage:**	Substantial
Passenger Injuries:	N/A	**Aircraft Fire:**	None
Ground Injuries:	N/A	**Aircraft Explosion:**	
Total Injuries:	1 None	**Latitude, Longitude:**	28.289722, -81.436944

Administrative Information

Investigator In Charge (IIC):	Jose Obregon	**Report Date:**	02/28/2008
Additional Participating Persons:			
Publish Date:			
Note:	This accident report documents the factual circumstances of this accident as described to the NTSB.		
Investigation Docket:	NTSB accident and incident dockets serve as permanent archival information for the NTSB's investigations. Dockets released prior to June 1, 2009 are publicly available from the NTSB's Record Management Division at pubinq@ntsb.gov, or at 800-877-6799. Dockets released after this date are available at http://dms.ntsb.gov/pubdms/.		

The National Transportation Safety Board (NTSB), established in 1967, is an independent federal agency mandated by Congress through the Independent Safety Board Act of 1974 to investigate transportation accidents, determine the probable causes of the accidents, issue safety recommendations, study transportation safety issues, and evaluate the safety effectiveness of government agencies involved in transportation. The NTSB makes public its actions and decisions through accident reports, safety studies, special investigation reports, safety recommendations, and statistical reviews.

The Independent Safety Board Act, as codified at 49 U.S.C. Section 1154(b), precludes the admission into evidence or use of any part of an NTSB report related to an incident or accident in a civil action for damages resulting from a matter mentioned in the report. A factual report that may be admissible under 49 U.S.C. § 1154(b) is available here.