National Transportation Safety Board
Aviation Accident Final Report

Location:	Muskogee, OK	**Accident Number:**	DFW08CA032
Date & Time:	11/17/2007, 1900 CST	**Registration:**	N45137
Aircraft:	Cessna 150	**Aircraft Damage:**	Substantial
Defining Event:		**Injuries:**	2 None
Flight Conducted Under:	Part 91: General Aviation - Personal		

Analysis

The private pilot stated in the NTSB Form 6120.1 (Pilot/Operator Aircraft Accident/Incident Report) that during the take-off roll the airplane developed a severe nose-wheel shimmy. He said he circled for a landing, made a stable approach to the runway, and landed "on the numbers." During the landing the airplane departed the left side of the runway onto the grass, and impacted a shallow ditch. The airplane's nose gear collapsed, and the firewall sustained structural damage. The operator stated that the airplane's prior flight was for 1.6-hours, which included six landings, with no reported problems.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: The pilot's failure to maintain directional control while landing.

Findings

Occurrence #1: LOSS OF CONTROL - ON GROUND/WATER
Phase of Operation: LANDING - ROLL

Findings
1. (C) DIRECTIONAL CONTROL - NOT MAINTAINED - PILOT IN COMMAND
2. (F) LIGHT CONDITION - NIGHT

Occurrence #2: ON GROUND/WATER COLLISION WITH OBJECT
Phase of Operation: LANDING

Findings
3. TERRAIN CONDITION - DITCH

Factual Information

Pilot Information

Certificate:	Private	**Age:**	73, Male
Airplane Rating(s):	Single-engine Land	**Seat Occupied:**	Left
Other Aircraft Rating(s):	None	**Restraint Used:**	Seatbelt, Shoulder harness
Instrument Rating(s):	None	**Second Pilot Present:**	No
Instructor Rating(s):	None	**Toxicology Performed:**	No
Medical Certification:	Class 3 With Waivers/Limitations	**Last FAA Medical Exam:**	05/01/2006
Occupational Pilot:		**Last Flight Review or Equivalent:**	06/01/2006
Flight Time:	700 hours (Total, all aircraft), 150 hours (Total, this make and model), 700 hours (Pilot In Command, all aircraft), 8 hours (Last 30 days, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	Cessna	**Registration:**	N45137
Model/Series:	150	**Aircraft Category:**	Airplane
Year of Manufacture:		**Amateur Built:**	No
Airworthiness Certificate:	Normal	**Serial Number:**	15076749
Landing Gear Type:	Tricycle	**Seats:**	2
Date/Type of Last Inspection:	09/01/2007, 100 Hour	**Certified Max Gross Wt.:**	
Time Since Last Inspection:		**Engines:**	1 Reciprocating
Airframe Total Time:	6492.7 Hours at time of accident	**Engine Manufacturer:**	Continental
ELT:	Installed, not activated	**Engine Model/Series:**	O-200
Registered Owner:	Davis Field Aviation, LLC	**Rated Power:**	100 hp
Operator:	Davis Field Aviation, LLC	**Operating Certificate(s) Held:**	None

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual Conditions	**Condition of Light:**	Night
Observation Facility, Elevation:	KMKO	**Distance from Accident Site:**	
Observation Time:	1853 CST	**Direction from Accident Site:**	
Lowest Cloud Condition:	Clear	**Visibility**	10 Miles
Lowest Ceiling:	None	**Visibility (RVR):**	
Wind Speed/Gusts:	4 knots /	**Turbulence Type Forecast/Actual:**	/
Wind Direction:	170°	**Turbulence Severity Forecast/Actual:**	/
Altimeter Setting:	29.96 inches Hg	**Temperature/Dew Point:**	14°C / 4°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	Muskogee, OK (MKO)	**Type of Flight Plan Filed:**	None
Destination:	Muskogee, OK	**Type of Clearance:**	None
Departure Time:	CST	**Type of Airspace:**	

Airport Information

Airport:	DAVIS FIELD (MKO)	**Runway Surface Type:**	Asphalt
Airport Elevation:		**Runway Surface Condition:**	Dry
Runway Used:	13	**IFR Approach:**	None
Runway Length/Width:	7201 ft / 150 ft	**VFR Approach/Landing:**	Traffic Pattern

Wreckage and Impact Information

Crew Injuries:	1 None	**Aircraft Damage:**	Substantial
Passenger Injuries:	1 None	**Aircraft Fire:**	None
Ground Injuries:	N/A	**Aircraft Explosion:**	None
Total Injuries:	2 None	**Latitude, Longitude:**	35.653333, -95.356667

Administrative Information

Investigator In Charge (IIC):	Craig R Hatch	**Report Date:**	02/28/2008
Additional Participating Persons:	John Thomas; FAA FSDO; Oklahoma City, OK		
Publish Date:			
Note:	This accident report documents the factual circumstances of this accident as described to the NTSB.		
Investigation Docket:	NTSB accident and incident dockets serve as permanent archival information for the NTSB's investigations. Dockets released prior to June 1, 2009 are publicly available from the NTSB's Record Management Division at pubinq@ntsb.gov, or at 800-877-6799. Dockets released after this date are available at http://dms.ntsb.gov/pubdms/.		

The National Transportation Safety Board (NTSB), established in 1967, is an independent federal agency mandated by Congress through the Independent Safety Board Act of 1974 to investigate transportation accidents, determine the probable causes of the accidents, issue safety recommendations, study transportation safety issues, and evaluate the safety effectiveness of government agencies involved in transportation. The NTSB makes public its actions and decisions through accident reports, safety studies, special investigation reports, safety recommendations, and statistical reviews.

The Independent Safety Board Act, as codified at 49 U.S.C. Section 1154(b), precludes the admission into evidence or use of any part of an NTSB report related to an incident or accident in a civil action for damages resulting from a matter mentioned in the report. A factual report that may be admissible under 49 U.S.C. § 1154(b) is available here.