National Transportation Safety Board
Aviation Accident Final Report

Location:	Hastings, MI	**Accident Number:**	CHI08CA049
Date & Time:	12/08/2007, 1130 EST	**Registration:**	N173DA
Aircraft:	Cessna 172	**Aircraft Damage:**	Substantial
Defining Event:		**Injuries:**	1 None
Flight Conducted Under:	Part 91: General Aviation - Instructional		

Analysis

The student pilot reported that he was on his first solo flight and was practicing takeoffs and landings to a full stop. The first landing was successful. During the landing rollout on the second full stop landing, the student pilot applied brakes. The braking action on the runway was uneven due to icy patches of snow and ice on the runway. The airplane began to depart the left side of the runway and the student pilot attempted to apply right rudder and right brake, but it had no effect. The airplane departed the left side of the runway and nosed over when the airplane impacted a shallow drainage ditch.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: The student pilot failed to maintain directional control during landing. Factors were the ditch and the icy runway.

Findings

Occurrence #1: NOSE OVER
Phase of Operation: LANDING - ROLL

Findings
1. (C) DIRECTIONAL CONTROL - NOT MAINTAINED - PILOT IN COMMAND
2. TERRAIN CONDITION - DITCH
3. (F) TERRAIN CONDITION - RUNWAY
4. (F) TERRAIN CONDITION - ICY

Factual Information

Student Pilot Information

Certificate:	Student	**Age:**	37, Male
Airplane Rating(s):	None	**Seat Occupied:**	
Other Aircraft Rating(s):	None	**Restraint Used:**	Seatbelt, Shoulder harness
Instrument Rating(s):	None	**Second Pilot Present:**	
Instructor Rating(s):		**Toxicology Performed:**	
Medical Certification:	None	**Last FAA Medical Exam:**	
Occupational Pilot:		**Last Flight Review or Equivalent:**	
Flight Time:	32 hours (Total, all aircraft), 19 hours (Total, this make and model), 32 hours (Last 90 days, all aircraft), 10 hours (Last 30 days, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	Cessna	**Registration:**	N173DA
Model/Series:	172	**Aircraft Category:**	Airplane
Year of Manufacture:		**Amateur Built:**	No
Airworthiness Certificate:	Normal	**Serial Number:**	17253664
Landing Gear Type:	Tricycle	**Seats:**	
Date/Type of Last Inspection:		**Certified Max Gross Wt.:**	
Time Since Last Inspection:		**Engines:**	1 Reciprocating
Airframe Total Time:		**Engine Manufacturer:**	Continental
ELT:		**Engine Model/Series:**	O-300
Registered Owner:	Skykid Aviation LLC	**Rated Power:**	
Operator:	Skykid Aviation LLC	**Operating Certificate(s) Held:**	None

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual Conditions	**Condition of Light:**	Day
Observation Facility, Elevation:		**Distance from Accident Site:**	
Observation Time:		**Direction from Accident Site:**	
Lowest Cloud Condition:		**Visibility**	
Lowest Ceiling:		**Visibility (RVR):**	
Wind Speed/Gusts:	/	**Turbulence Type Forecast/Actual:**	/
Wind Direction:		**Turbulence Severity Forecast/Actual:**	/
Altimeter Setting:		**Temperature/Dew Point:**	
Precipitation and Obscuration:			
Departure Point:	Hastings, MI (9D9)	**Type of Flight Plan Filed:**	None
Destination:		**Type of Clearance:**	None
Departure Time:	EST	**Type of Airspace:**	

Airport Information

Airport:	Hastings Airport (9D9)	**Runway Surface Type:**	
Airport Elevation:		**Runway Surface Condition:**	
Runway Used:	NA	**IFR Approach:**	None
Runway Length/Width:		**VFR Approach/Landing:**	

Wreckage and Impact Information

Crew Injuries:	1 None	**Aircraft Damage:**	Substantial
Passenger Injuries:	N/A	**Aircraft Fire:**	None
Ground Injuries:	N/A	**Aircraft Explosion:**	
Total Injuries:	1 None	**Latitude, Longitude:**	42.663611, -85.346111

Administrative Information

Investigator In Charge (IIC):	Jim Silliman	**Report Date:**	02/28/2008
Additional Participating Persons:			
Publish Date:			
Note:	This accident report documents the factual circumstances of this accident as described to the NTSB.		
Investigation Docket:	NTSB accident and incident dockets serve as permanent archival information for the NTSB's investigations. Dockets released prior to June 1, 2009 are publicly available from the NTSB's Record Management Division at pubinq@ntsb.gov, or at 800-877-6799. Dockets released after this date are available at http://dms.ntsb.gov/pubdms/.		

The National Transportation Safety Board (NTSB), established in 1967, is an independent federal agency mandated by Congress through the Independent Safety Board Act of 1974 to investigate transportation accidents, determine the probable causes of the accidents, issue safety recommendations, study transportation safety issues, and evaluate the safety effectiveness of government agencies involved in transportation. The NTSB makes public its actions and decisions through accident reports, safety studies, special investigation reports, safety recommendations, and statistical reviews.

The Independent Safety Board Act, as codified at 49 U.S.C. Section 1154(b), precludes the admission into evidence or use of any part of an NTSB report related to an incident or accident in a civil action for damages resulting from a matter mentioned in the report. A factual report that may be admissible under 49 U.S.C. § 1154(b) is available here.