National Transportation Safety Board
Aviation Accident Factual Report

Location:	Pointe-A-Pitre, Guadeloupe	**Accident Number:**	DEN08RA050
Date & Time:	12/22/2007, 1500 UTC	**Registration:**	N901TP
Aircraft:	Partenavia AP 68 TP	**Aircraft Damage:**	Substantial
Defining Event:		**Injuries:**	2 None
Flight Conducted Under:	Non-U.S., Non-Commercial		

On December 22, 2007, at 1815 coordinated universal time, a Partenavia AP 68 TP, U.S. registered N901TP, owned by Air Coulibri Inc., and piloted by the accident pilot, was substantially damaged when it experienced an uncontained engine failure during the takeoff roll at Pointe-A-Pitre le Raizet (TFFR), Guadeloupe. Visual meteorological conditions prevailed at the time of the accident. The pilot and one passenger were not injured. The flight was originating at the time of the accident.

The French investigators reported that pilot experienced a problem during the takeoff roll. The pilot aborted the takeoff. Further examination revealed an uncontained "rupture" of the left engine.

The accident investigation is under the jurisdiction and control of the French government. This report is for informational purposes only and contains only information released by or obtained from the French government or French Bureau d'Enquêtes et d'Analyses. Further information pertaining to this accident may be obtained from:

Aircraft Accident Investigation Bureau

Bureau d'Enquêtes et d'Analyses

Zone Sud

200 rue de Paris

Aêroport du Bourget

93350 Le Bourget Cedex

France

Aircraft and Owner/Operator Information

Aircraft Make:	Partenavia	**Registration:**	N901TP
Model/Series:	AP 68 TP	**Aircraft Category:**	Airplane
Year of Manufacture:		**Amateur Built:**	No
Airworthiness Certificate:		**Serial Number:**	
Landing Gear Type:		**Seats:**	
Date/Type of Last Inspection:		**Certified Max Gross Wt.:**	
Time Since Last Inspection:		**Engines:**	
Airframe Total Time:		**Engine Manufacturer:**	
ELT:		**Engine Model/Series:**	
Registered Owner:		**Rated Power:**	
Operator:		**Operating Certificate(s) Held:**	None

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual Conditions	**Condition of Light:**	
Observation Facility, Elevation:	TFFR	**Distance from Accident Site:**	
Observation Time:	1400	**Direction from Accident Site:**	
Lowest Cloud Condition:	Scattered / 2600 ft agl	**Visibility**	6 Miles
Lowest Ceiling:	None	**Visibility (RVR):**	
Wind Speed/Gusts:	10 knots /	**Turbulence Type Forecast/Actual:**	/
Wind Direction:	130°	**Turbulence Severity Forecast/Actual:**	/
Altimeter Setting:	29.92 inches Hg	**Temperature/Dew Point:**	29°C / 21°C
Precipitation and Obscuration:			
Departure Point:	Pointe-A-Pitre (TFFR)	**Type of Flight Plan Filed:**	Unknown
Destination:	Antilles Franc. (TFFC)	**Type of Clearance:**	
Departure Time:	1815 UTC	**Type of Airspace:**	

Airport Information

Airport:		**Runway Surface Type:**	
Airport Elevation:		**Runway Surface Condition:**	
Runway Used:		**IFR Approach:**	
Runway Length/Width:		**VFR Approach/Landing:**	

Wreckage and Impact Information

Crew Injuries:	2 None	**Aircraft Damage:**	Substantial
Passenger Injuries:	N/A	**Aircraft Fire:**	
Ground Injuries:	N/A	**Aircraft Explosion:**	
Total Injuries:	2 None	**Latitude, Longitude:**	16.250000, -61.516667

Administrative Information

Investigator In Charge (IIC):	Jennifer S Kaiser
Additional Participating Persons:	Francois Hochart; French BEA
Investigation Docket:	NTSB accident and incident dockets serve as permanent archival information for the NTSB's investigations. Dockets released prior to June 1, 2009 are publicly available from the NTSB's Record Management Division at pubinq@ntsb.gov, or at 800-877-6799. Dockets released after this date are available at http://dms.ntsb.gov/pubdms/.