National Transportation Safety Board
Aviation Accident Final Report

Location:	Austin, TX	**Accident Number:**	DFW08CA049
Date & Time:	12/22/2007, 1230 CST	**Registration:**	N212CG
Aircraft:	Cessna 182	**Aircraft Damage:**	Substantial
Defining Event:		**Injuries:**	1 None
Flight Conducted Under:	Part 91: General Aviation - Personal		

Analysis

The private pilot stated as he approached the airport for a landing, the winds were reported as 320 degrees at 20-knots, gusting to 30-knots. The pilot added, as he touched down for a landing, a gust of wind pushed the airplane to the right and off the 5,987-foot by 100-foot wide runway. The pilot was unable to maneuver the airplane back onto the runway, and the airplane's nose-gear collapsed after impacting a rock.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: The pilot's failure to maintain directional control while landing. A contributing factor was the gusting winds.

Findings

Occurrence #1: LOSS OF CONTROL - ON GROUND/WATER
Phase of Operation: LANDING - FLARE/TOUCHDOWN

Findings
1. (C) DIRECTIONAL CONTROL - NOT MAINTAINED - PILOT IN COMMAND
2. (F) WEATHER CONDITION - GUSTS

Occurrence #2: ON GROUND/WATER COLLISION WITH OBJECT
Phase of Operation: LANDING - ROLL

Findings
3. TERRAIN CONDITION - ROCK(S)/BOULDER(S)

Factual Information

Pilot Information

Certificate:	Private	**Age:**	32, Male
Airplane Rating(s):	Single-engine Land	**Seat Occupied:**	Left
Other Aircraft Rating(s):	None	**Restraint Used:**	Seatbelt, Shoulder harness
Instrument Rating(s):	Airplane	**Second Pilot Present:**	No
Instructor Rating(s):	None	**Toxicology Performed:**	No
Medical Certification:	Class 3 Without Waivers/Limitations	**Last FAA Medical Exam:**	08/01/2007
Occupational Pilot:		**Last Flight Review or Equivalent:**	09/01/2006
Flight Time:	185 hours (Total, all aircraft), 35 hours (Total, this make and model), 149 hours (Pilot In Command, all aircraft), 11 hours (Last 90 days, all aircraft), 5 hours (Last 30 days, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	Cessna	**Registration:**	N212CG
Model/Series:	182	**Aircraft Category:**	Airplane
Year of Manufacture:		**Amateur Built:**	No
Airworthiness Certificate:	Normal	**Serial Number:**	18267988
Landing Gear Type:	Tricycle	**Seats:**	
Date/Type of Last Inspection:	Unknown	**Certified Max Gross Wt.:**	
Time Since Last Inspection:		**Engines:**	1 Reciprocating
Airframe Total Time:		**Engine Manufacturer:**	Continental
ELT:	Installed, not activated	**Engine Model/Series:**	O-470
Registered Owner:	Rare Tech Corp	**Rated Power:**	
Operator:	Rare Tech Corp	**Operating Certificate(s) Held:**	None

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual Conditions	**Condition of Light:**	Day
Observation Facility, Elevation:	KBMQ	**Distance from Accident Site:**	14 Nautical Miles
Observation Time:	1253	**Direction from Accident Site:**	30°
Lowest Cloud Condition:	Clear	**Visibility**	10 Miles
Lowest Ceiling:	None	**Visibility (RVR):**	
Wind Speed/Gusts:	23 knots / 33 knots	**Turbulence Type Forecast/Actual:**	/
Wind Direction:	290°	**Turbulence Severity Forecast/Actual:**	/
Altimeter Setting:	29.99 inches Hg	**Temperature/Dew Point:**	16°C / -4°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	HOUSTON, TX (HOU)	**Type of Flight Plan Filed:**	IFR
Destination:	AUSTIN, TX (4R2)	**Type of Clearance:**	IFR
Departure Time:	1045 CST	**Type of Airspace:**	

Airport Information

Airport:	HORSESHOE BAY AIRPARK (4R2)	**Runway Surface Type:**	Asphalt
Airport Elevation:		**Runway Surface Condition:**	Dry
Runway Used:	35	**IFR Approach:**	Visual
Runway Length/Width:	5978 ft / 100 ft	**VFR Approach/Landing:**	Traffic Pattern

Wreckage and Impact Information

Crew Injuries:	1 None	**Aircraft Damage:**	Substantial
Passenger Injuries:	N/A	**Aircraft Fire:**	None
Ground Injuries:	N/A	**Aircraft Explosion:**	None
Total Injuries:	1 None	**Latitude, Longitude:**	30.525000, -98.358333

Administrative Information

Investigator In Charge (IIC):	Craig R Hatch	**Report Date:**	02/28/2008
Additional Participating Persons:	John Burris; FAA FSDO; San Antonio, TX		
Publish Date:			
Note:	This accident report documents the factual circumstances of this accident as described to the NTSB.		
Investigation Docket:	NTSB accident and incident dockets serve as permanent archival information for the NTSB's investigations. Dockets released prior to June 1, 2009 are publicly available from the NTSB's Record Management Division at pubinq@ntsb.gov, or at 800-877-6799. Dockets released after this date are available at http://dms.ntsb.gov/pubdms/.		

The National Transportation Safety Board (NTSB), established in 1967, is an independent federal agency mandated by Congress through the Independent Safety Board Act of 1974 to investigate transportation accidents, determine the probable causes of the accidents, issue safety recommendations, study transportation safety issues, and evaluate the safety effectiveness of government agencies involved in transportation. The NTSB makes public its actions and decisions through accident reports, safety studies, special investigation reports, safety recommendations, and statistical reviews.

The Independent Safety Board Act, as codified at 49 U.S.C. Section 1154(b), precludes the admission into evidence or use of any part of an NTSB report related to an incident or accident in a civil action for damages resulting from a matter mentioned in the report. A factual report that may be admissible under 49 U.S.C. § 1154(b) is available here.