National Transportation Safety Board
Aviation Accident Factual Report

Location:	Ocumare del Tuy, Venezuela	**Accident Number:**	MIA08WA058
Date & Time:	12/26/2007, 1245 AST	**Registration:**	N761YL
Aircraft:	Cessna T210L	**Aircraft Damage:**	Substantial
Defining Event:		**Injuries:**	1 Minor
Flight Conducted Under:	Part 91: General Aviation - Personal		

On December 26, 2007, about 1245 Atlantic standard time, a Cessna 210, N761YL, impacted with the ground during the approach to the Metropoltano Airport, Ocumare Del Tuy, Venezuela. Visual meteorological conditions prevailed and no flight plan information is known. The pilot received minor injuries and the aircraft incurred substantial damage. The flight originated from the Aerodromo Guanare, Portuguesa, Venezuela, earlier that day, about 1120.

Information from the Venezuelan government states that the pilot declared a loss of engine power during the final approach and impact the ground 300 meters short of runway 8.

The investigation is under the jurisdiction of the Government of Venezuela. Further information pertaining to this accident may be obtained from:

Junta Investigadora de Accidentes de Aviación

Ministerio de Infraestructura

Republica Bolivariana de Venezuela

Av. Francisco de Miranda

Torre MINFRA, piso-20

Caracas, Republica de Bolivariana de Venezuela

This report is for informational purposes only and contains only information released by or obtained for the Government of Venezuela.

Pilot Information

Certificate:		**Age:**	
Airplane Rating(s):		**Seat Occupied:**	
Other Aircraft Rating(s):		**Restraint Used:**	
Instrument Rating(s):		**Second Pilot Present:**	
Instructor Rating(s):		**Toxicology Performed:**	
Medical Certification:		**Last FAA Medical Exam:**	
Occupational Pilot:		**Last Flight Review or Equivalent:**	
Flight Time:			

Aircraft and Owner/Operator Information

Aircraft Make:	Cessna	**Registration:**	N761YL
Model/Series:	T210L	**Aircraft Category:**	Airplane
Year of Manufacture:		**Amateur Built:**	No
Airworthiness Certificate:		**Serial Number:**	
Landing Gear Type:		**Seats:**	
Date/Type of Last Inspection:		**Certified Max Gross Wt.:**	
Time Since Last Inspection:		**Engines:**	
Airframe Total Time:		**Engine Manufacturer:**	
ELT:		**Engine Model/Series:**	
Registered Owner:		**Rated Power:**	
Operator:		**Operating Certificate(s) Held:**	None

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual Conditions	**Condition of Light:**	
Observation Facility, Elevation:	SVBC	**Distance from Accident Site:**	
Observation Time:	1300	**Direction from Accident Site:**	
Lowest Cloud Condition:	Scattered / 10000 ft agl	**Visibility**	10 Miles
Lowest Ceiling:	None	**Visibility (RVR):**	
Wind Speed/Gusts:	10 knots /	**Turbulence Type Forecast/Actual:**	/
Wind Direction:	360°	**Turbulence Severity Forecast/Actual:**	/
Altimeter Setting:	30 inches Hg	**Temperature/Dew Point:**	33°C / 23°C
Precipitation and Obscuration:			
Departure Point:	Portuguesa (SVGU)	**Type of Flight Plan Filed:**	None
Destination:	Ocumare del Tuy (SVMP)	**Type of Clearance:**	
Departure Time:	1115 AST	**Type of Airspace:**	

Airport Information

Airport:		**Runway Surface Type:**	
Airport Elevation:		**Runway Surface Condition:**	
Runway Used:		**IFR Approach:**	
Runway Length/Width:		**VFR Approach/Landing:**	

Wreckage and Impact Information

Crew Injuries:	1 Minor	**Aircraft Damage:**	Substantial
Passenger Injuries:	N/A	**Aircraft Fire:**	
Ground Injuries:	N/A	**Aircraft Explosion:**	
Total Injuries:	1 Minor	**Latitude, Longitude:**	10.121667, -66.771667

Administrative Information

Investigator In Charge (IIC):	Jose L Obregon
Additional Participating Persons:	Javier Rodriguez; FAA Miami International
Investigation Docket:	NTSB accident and incident dockets serve as permanent archival information for the NTSB's investigations. Dockets released prior to June 1, 2009 are publicly available from the NTSB's Record Management Division at pubinq@ntsb.gov, or at 800-877-6799. Dockets released after this date are available at http://dms.ntsb.gov/pubdms/.