National Transportation Safety Board
Aviation Accident Factual Report

Location:	Gurupi, Brazil	**Accident Number:**	NYC08WA065
Date & Time:	12/19/2007, 0800	**Registration:**	
Aircraft:	Cirrus SR22	**Aircraft Damage:**	Substantial
Defining Event:		**Injuries:**	1 Fatal, 1 Serious
Flight Conducted Under:	Non-U.S., Non-Commercial		

On December 19, 2007, at 0800 local time, a Brazilian registered Cirrus SR-22, PR-OGM, was substantially damaged when it impacted the ground during a landing at the Gurupi Airport (SWGI), Gurupi, Brazil. The pilot was fatally injured and the owner/passenger was seriously injured. The flight was conducted under Brazilian flight regulations.

According to a witness, the airplane made a "low and tight" left turn while on the base leg of the traffic pattern. The airplane's left wing tip then struck the ground and the airplane "cartwheeled" before coming to rest.

This investigation is under jurisdiction of the Government of Brazil. For further information contact:

Aeronautical Accident Prevention And Investigation Center (CENIPA)

SHIS-QI 05-VI Comar

Brasilia-DF, Brazil, 71.615.600

Phone: 55 61 3364 8819

Facsimile: 55 61 3365 1004

E-mail: dti@cenipa.aer.mil.br

This report is for informational purposes only and contains information released by the Government of Brazil.

Aircraft and Owner/Operator Information

Aircraft Make:	Cirrus	**Registration:**	
Model/Series:	SR22	**Aircraft Category:**	Airplane
Year of Manufacture:		**Amateur Built:**	No
Airworthiness Certificate:		**Serial Number:**	
Landing Gear Type:		**Seats:**	
Date/Type of Last Inspection:		**Certified Max Gross Wt.:**	
Time Since Last Inspection:		**Engines:**	
Airframe Total Time:		**Engine Manufacturer:**	
ELT:		**Engine Model/Series:**	
Registered Owner:		**Rated Power:**	
Operator:		**Operating Certificate(s) Held:**	None

Meteorological Information and Flight Plan

Conditions at Accident Site:		**Condition of Light:**	
Observation Facility, Elevation:		**Distance from Accident Site:**	
Observation Time:		**Direction from Accident Site:**	
Lowest Cloud Condition:		**Visibility**	
Lowest Ceiling:		**Visibility (RVR):**	
Wind Speed/Gusts:	/	**Turbulence Type Forecast/Actual:**	/
Wind Direction:		**Turbulence Severity Forecast/Actual:**	/
Altimeter Setting:		**Temperature/Dew Point:**	
Precipitation and Obscuration:			
Departure Point:		**Type of Flight Plan Filed:**	
Destination:	Gurupi (SWGI)	**Type of Clearance:**	
Departure Time:		**Type of Airspace:**	

Airport Information

Airport:		**Runway Surface Type:**	
Airport Elevation:		**Runway Surface Condition:**	
Runway Used:		**IFR Approach:**	
Runway Length/Width:		**VFR Approach/Landing:**	

Wreckage and Impact Information

Crew Injuries:	1 Serious	**Aircraft Damage:**	Substantial
Passenger Injuries:	1 Fatal	**Aircraft Fire:**	
Ground Injuries:	N/A	**Aircraft Explosion:**	
Total Injuries:	1 Fatal, 1 Serious	**Latitude, Longitude:**	

Administrative Information

Investigator In Charge (IIC):	Jill M Andrews
Additional Participating Persons:	
Investigation Docket:	NTSB accident and incident dockets serve as permanent archival information for the NTSB's investigations. Dockets released prior to June 1, 2009 are publicly available from the NTSB's Record Management Division at pubinq@ntsb.gov, or at 800-877-6799. Dockets released after this date are available at http://dms.ntsb.gov/pubdms/.