National Transportation Safety Board
Aviation Accident Factual Report

Location:	Parral, Chile	**Accident Number:**	NYC08WA329
Date & Time:	12/17/2007, 1900 UTC	**Registration:**	
Aircraft:	GRUMMAN G164A	**Aircraft Damage:**	Substantial
Defining Event:		**Injuries:**	1 None
Flight Conducted Under:	Non-U.S., Non-Commercial		

On December 17, 2007, about 1900 coordinated universal time, a Grumman G164A, Chilean registry CC-CCG, was substantially damaged during a forced landing near Parral, Chile. The pilot was not injured. Visual meteorological conditions prevailed for the local aerial application flight.

The airplane was maneuvering during an aerial application flight when the engine began to experience a loss of power, and the pilot performed a forced landing to a field.

This accident investigation is under the jurisdiction of the Government of Chile. Any further information pertaining to this accident may be obtained from:

Direccion General de Aeronauticia Civil

Miguel Claro 1314 Providencia

Santiago, Chile

This report is for informational purposes only and contains only information obtained for or released by the Government of Chile.

Pilot Information

Certificate:		**Age:**	, Male
Airplane Rating(s):		**Seat Occupied:**	Front
Other Aircraft Rating(s):		**Restraint Used:**	
Instrument Rating(s):		**Second Pilot Present:**	No
Instructor Rating(s):		**Toxicology Performed:**	
Medical Certification:		**Last FAA Medical Exam:**	
Occupational Pilot:	Yes	**Last Flight Review or Equivalent:**	
Flight Time:	8400 hours (Total, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	GRUMMAN	**Registration:**	
Model/Series:	G164A	**Aircraft Category:**	Airplane
Year of Manufacture:		**Amateur Built:**	No
Airworthiness Certificate:		**Serial Number:**	
Landing Gear Type:	Tailwheel	**Seats:**	
Date/Type of Last Inspection:	Unknown	**Certified Max Gross Wt.:**	
Time Since Last Inspection:		**Engines:**	1 Reciprocating
Airframe Total Time:		**Engine Manufacturer:**	Pratt & Whitney
ELT:		**Engine Model/Series:**	R-985AN-14B
Registered Owner:		**Rated Power:**	450 hp
Operator:		**Operating Certificate(s) Held:**	None

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual Conditions	**Condition of Light:**	Day
Observation Facility, Elevation:		**Distance from Accident Site:**	
Observation Time:		**Direction from Accident Site:**	
Lowest Cloud Condition:		**Visibility**	
Lowest Ceiling:		**Visibility (RVR):**	
Wind Speed/Gusts:	/	**Turbulence Type Forecast/Actual:**	/
Wind Direction:		**Turbulence Severity Forecast/Actual:**	/
Altimeter Setting:		**Temperature/Dew Point:**	
Precipitation and Obscuration:			
Departure Point:	Parral	**Type of Flight Plan Filed:**	Unknown
Destination:		**Type of Clearance:**	None
Departure Time:	UTC	**Type of Airspace:**	Unknown

Wreckage and Impact Information

Crew Injuries:	1 None	**Aircraft Damage:**	Substantial
Passenger Injuries:	N/A	**Aircraft Fire:**	None
Ground Injuries:	N/A	**Aircraft Explosion:**	None
Total Injuries:	1 None	**Latitude, Longitude:**	-36.143333, -71.826667 (est)

Administrative Information

Investigator In Charge (IIC):	Luke Schiada
Additional Participating Persons:	
Investigation Docket:	NTSB accident and incident dockets serve as permanent archival information for the NTSB's investigations. Dockets released prior to June 1, 2009 are publicly available from the NTSB's Record Management Division at pubinq@ntsb.gov, or at 800-877-6799. Dockets released after this date are available at http://dms.ntsb.gov/pubdms/.