


Exterior magnetic jackets reduce the second location's support burden



Necessary straight-section test. Missing points have no feasible $k \leq 1$; bend mechanics remain open.