AIS AssetTrack — End-to-End Process Flow

Returnable pallets · AIS plant → OEM / OES / AFM customer → AIS · one server for all plants · revised Oct 2026 · server 1.20 · HHT 2.9

Scan step (HHT / gate) · AssetTrack function · Control check
External (Bench/ERP/EBS) · Customer HHT step · Normal end state · Exception

PLANTS & USERS
One server · plant chosen at sign-in
Roles · extra plants · Customer Staff

PALLETS & TYPES
QR AIS-plant-type-serial-global
Type: value · HSN · L×W×H · weight

CUSTOMERS & TRANSPORTERS
Auto-created from the GCS file
Holding days · e-mails · vehicles

CUSTOMER HHT
Paired by QR from the web
Staff sign-in · works offline

HHT SETUP
Scan server QR · Online / Offline
Any BT printer · scanner or camera

INTEGRATIONS
Bench trips (plant-wise) · GCS FTP
per plant · EBS challan / GCS-IN

DISPATCH

Dispatch Bench
plant-wise trip · picks LPN
PDI done here

→ **ERP invoice + GCS**
GCS file to the plant's FTP folder

→ **GCS inbox → load sheet**
per plant · joined with its Bench trip (one record)

→ **HHT · Vehicle loading**
scan part card + pallet (scanner or camera)

→ **Card in GCS?**
PDI passed for this vehicle

short → keep loading

yes → **Finish loading**
qty vs invoice
missing / extra

ok → **Gate pass + Challan**
auto PDF · signed GCS QR
GCS slip on BT printer

→ **AIS OUT gate**
scan GCS QR
vehicle released

→ **AT CUSTOMER**
holding days start

no → **STOP – do PDI**
wrong vehicle refused

HHT gets the sheet within 30 s · only the chosen plant's lists

Oracle EBS
challan · e-way bill

CUSTOMER

Receive delivery
staff scan each pallet while unloading

→ **Received/missing/extra**
visible to AIS

→ **Holding days · reminders**
mail before / after limit escalation

→ **Return empty pallets · A**
scan pallets · pick vehicle customer DC if any

emptied → **Return slip printed**
no. auto · signed QR
offline: RO- slip from HHT

→ **Vehicle to AIS**
with slip, document or nothing

Customer HHT: staff sign in with their own user · works without network, sends later

RETURN

Vehicle brings?

slip → **Scan return slip QR**
Option A (or offline RO- slip)

no slip → **Make slip B at gate**
count + document photo (required) → read & matched

plant challan → **Scan plant challan**
other AIS plant: challan only

→ **Gate inward register**
IN gate · one entry no. for every inward vehicle + GCS inward (ERP)

→ **Pallet yard receiving**
scan each pallet · slip / document list + photo shown

→ **Reconcile**
received vs slip / document

match → **AVAILABLE**
back in plant stock

other plant → **HELD – other plant**
owner plant alerted

mismatch → **Discrepancy queue**
short · extra · unknown
damaged · supervisor PIN

→ **Reports & dashboard**
plant position
at customer · aging
missed scans
customer receipts
Excel / PDF everywhere

INTERPLANT

Other-plant pallets
emptied in FGWH / Packing

→ **HHT · Yard loading**
owner plant · scan pallets

→ **Challan + e-way bill**
EBS / app challan

→ **OUT gate**
scan challan QR

→ **Owner plant IN gate**
scans the same challan

→ **Owner plant Yard**
scan each pallet

→ **AVAILABLE at home**

Rules: every inward (slip A, slip B, plant challan) is registered at the IN gate · a part card not in the GCS is stopped (do PDI) · Option B needs a photo of the customer document and is knocked off at the pallet yard