AIS AssetTrack — End-to-End Process Flow

Returnable pallets · AIS plant → OEM / OES / AFM customer → AIS · one server for all plants · revised Oct 2026 · server 1.21 · HHT 2.11

Scan step (HHT / gate) · AssetTrack function · Control check
External (Bench/ERP/EBS) · Customer HHT step · Normal end state · Exception

PLANTS & USERS
One server · plant chosen at sign-in
Roles · extra plants · Customer Staff

PALLETS & TYPES
QR AIS-plant-type-serial-global
Type: value · HSN · L×W×H · weight

CUSTOMERS & TRANSPORTERS
Auto-created from the GCS file
Holding days · e-mails · vehicles

CUSTOMER HHT
Paired by QR from the web
Staff sign-in · works offline

HHT SETUP
Scan server QR · Online / Offline
BT printer: return slips only

INTEGRATIONS
Bench trips (plant-wise) · GCS FTP per plant · EBS challan / GCS-IN

DISPATCH

Dispatch Bench — plant-wise trip · picks LPN · PDI done here
→ **ERP invoice + GCS** — GCS file to the plant's FTP folder
→ **GCS inbox → load sheet** — per plant · joined with its Bench trip (one record)
→ **HHT · Vehicle loading** — scan part card + pallet (scanner or camera)
→ **Card in GCS?** — PDI passed for this vehicle
- yes → **Finish loading** — qty vs invoice · missing / extra
  - ok → **Gate pass + Challan** — auto PDF · signed GCS QR · plant network printer
    → **AIS OUT gate** — scan GCS QR · vehicle released
- no → **STOP – do PDI** — wrong vehicle refused

short → keep loading

HHT gets the sheet within 30 s · only the chosen plant's lists

Oracle EBS — challan · e-way bill

AT CUSTOMER — holding days start

CUSTOMER

Receive delivery — staff scan each pallet while unloading
→ **Received/missing/extra** — visible to AIS
→ **Holding days · reminders** — mail before / after limit escalation
→ **Return empty pallets · A** — scan pallets · pick vehicle customer DC if any
→ **Return slip printed** — BT printer · no. auto signed QR (offline: RO-)
→ **Vehicle to AIS** — with slip, document or nothing

emptied

Customer HHT: staff sign in with their own user · works without network, sends later

RETURN

Vehicle brings?
- slip → **Scan return slip QR** — Option A (or offline RO- slip)
- no slip → **Make slip B at gate** — count + document photo (required) · read & matched slip on BT printer
- plant challan → **Scan plant challan** — other AIS plant: challan only

→ **Gate inward register** — IN gate · one entry no. for every inward vehicle + GCS inward (ERP)
→ **Pallet yard receiving** — scan RTS → A or B known · A: tick pallets vs slip list · B: photo → scan → count
→ **Reconcile** — received vs slip / document
- match → **AVAILABLE** — back in plant stock
- other plant → **HELD – other plant** — owner plant alerted
- mismatch → **Discrepancy queue** — short · extra · unknown · damaged · supervisor PIN

→ **Reports & dashboard** — plant position · at customer · aging · missed scans · customer receipts · Excel / PDF everywhere

INTERPLANT

Other-plant pallets — emptied in FGWH / Packing
→ **HHT · Yard loading** — owner plant · scan pallets
→ **Challan + e-way bill** — EBS / app challan
→ **OUT gate** — scan challan QR
→ **Owner plant IN gate** — scans the same challan
→ **Owner plant Yard** — scan each pallet
→ **AVAILABLE at home**

Rules: every inward (slip A, slip B, plant challan) is registered at the IN gate · a part card not in the GCS is stopped (do PDI) · Option B needs a photo of the customer document and is knocked off at the pallet yard