

Inspection Report - Flat 101

Project: Highland

Building: Tower D

Floor: Floor 1

Flattype: 1 BHK

Generated On: 17-09-2025

Summary

386

TOTAL CHECKPOINTS

1

PENDING

193

COMPLETED

0

REJECTED

Stage:

Checklist: Polish Checklists

QUESTION	STATUS	ATTEMPT DETAILS
Polish Finish is Uniform without Patches or Polish Droplets on the frames	COMPLETED (2 attempts)	Attempt 1 CHECKER Anurag Sharmaa Status: Rejected_By_Checker Remarks: polish not finish 22-08-2025 10:14 
		Attempt 2 MAKER Devendra Verma 26-08-2025 07:33
		CHECKER Anurag Sharmaa Status: Pending_Supervisor
The polish on the top surface of the shutter is Uniformly applied.	COMPLETED (1 attempt)	Attempt 1 CHECKER Anurag Sharmaa Status: Completed Remarks: done 22-08-2025 10:14

Checklist: Carpentry Checklists

QUESTION	STATUS	ATTEMPT DETAILS
All hardwares fixed properly as per the approved drawing and dimensions, Tower bolt and handles fixed properly, peep hole is in place	COMPLETED (1 attempt)	Attempt 1 CHECKER Jayant Yadav Status: Completed 26-08-2025 07:09
Lock slot is cut properly, lock plate, Architrave is fixed properly	COMPLETED (2 attempts)	Attempt 1 CHECKER Anurag Sharmaa Status: Rejected_By_Checker Remarks: not done 22-08-2025 10:52 
Attempt 2		
MAKER Devendra Verma 26-08-2025 07:33		
CHECKER Anurag Sharmaa Status: Pending_Supervisor		

QUESTION	STATUS	ATTEMPT DETAILS
The hinge slots are properly cut, and the hinges are fixed properly.	COMPLETED (1 attempt)	<p>Attempt 1</p> <p>CHECKER Anurag Sharmaa Status: Completed Remarks: done 22-08-2025 10:52</p> 
Is the hinges screw heads flushed with plates	COMPLETED (1 attempt)	<p>Attempt 1</p> <p>CHECKER Anurag Sharmaa Status: Completed Remarks: done 22-08-2025 10:52</p>
The intumescent strip has been properly fixed on the main door and kitchen door shutters.	COMPLETED (2 attempts)	<p>Attempt 1</p> <p>CHECKER Jayant Yadav Status: Rejected_By_Checker 26-08-2025 07:10</p>

QUESTION	STATUS	ATTEMPT DETAILS
		<p>Attempt 2</p> <p>MAKER Devendra Verma 26-08-2025 07:33</p> <p>CHECKER Jayant Yadav Status: Pending_Supervisor</p>
Is any undulations observed in Door shutter Laminate	COMPLETED (2 attempts)	<p>Attempt 1</p> <p>CHECKER Jayant Yadav Status: Rejected_By_Checker 26-08-2025 07:10</p> <p>Attempt 2</p> <p>MAKER Devendra Verma 26-08-2025 07:33</p> <p>CHECKER Jayant Yadav Status: Pending_Supervisor</p>
Is the 3mm gap is maintained at door frame bottom and sealant is applied	COMPLETED (2 attempts)	<p>Attempt 1</p> <p>CHECKER Jayant Yadav Status: Rejected_By_Checker 26-08-2025 07:10</p>

QUESTION	STATUS	ATTEMPT DETAILS
		<p>Attempt 2</p> <p>MAKER Devendra Verma 26-08-2025 07:33</p> <p>CHECKER Jayant Yadav Status: Pending_Supervisor</p>
Gap Between Door Shutter and Frame & Shutter Edges with Flooring is uniform & within tolerance limits.	<p>COMPLETED (2 attempts)</p>	<p>Attempt 1</p> <p>CHECKER Jayant Yadav Status: Rejected_By_Checker 26-08-2025 07:10</p> <p>Attempt 2</p> <p>MAKER Devendra Verma 26-08-2025 07:33</p> <p>CHECKER Jayant Yadav Status: Pending_Supervisor</p>
Magnetic Door catches & PVC buffers installed at the Correct Location and Securely Fixed	<p>COMPLETED (1 attempt)</p>	<p>Attempt 1</p> <p>CHECKER Jayant Yadav Status: Completed 26-08-2025 07:10</p>

QUESTION	STATUS	ATTEMPT DETAILS
Is the lock and other hardwares fixed properly and working smoothly.	COMPLETED (2 attempts)	Attempt 1 CHECKER Jayant Yadav Status: Rejected_By_Checker Remarks: not yet done 26-08-2025 07:10 
		Attempt 2 MAKER Devendra Verma 26-08-2025 07:33 CHECKER Jayant Yadav Status: Pending_Supervisor

Checklist: Flooring Checklists

QUESTION	STATUS	ATTEMPT DETAILS
Floor tiles no crack, chipped off observed	COMPLETED <small>(1 attempt)</small>	<p>Attempt 1</p> <p>CHECKER Anurag Sharmaa Status: Completed Remarks: done 22-08-2025 10:24</p>
Hollow sound is observed in floor tile or skirting	COMPLETED <small>(2 attempts)</small>	<p>Attempt 1</p> <p>CHECKER Anurag Sharmaa Status: Rejected_By_Checker Remarks: not done 22-08-2025 10:25</p> 
		<p>Attempt 2</p> <p>MAKER Devendra Verma 26-08-2025 07:33</p> <p>CHECKER Anurag Sharmaa Status: Pending_Supervisor</p>

QUESTION	STATUS	ATTEMPT DETAILS
Flooring tiles / marble observed without any leapages/ offsets	COMPLETED (1 attempt)	Attempt 1 CHECKER Anurag Sharmaa Status: Completed Remarks: done 22-08-2025 10:25

Checklist: Skirting Checklists

QUESTION	STATUS	ATTEMPT DETAILS
Is the Skirting aligned with Finished top Edge & without offset.	COMPLETED (1 attempt)	Attempt 1 CHECKER Jayant Yadav Status: Completed 26-08-2025 07:10
The top surface of the tile skirting has been properly finished using a Facile diamond hand pad	COMPLETED (2 attempts)	Attempt 1 CHECKER Jayant Yadav Status: Rejected_By_Checker 26-08-2025 07:10
		Attempt 2 MAKER Devendra Verma 26-08-2025 07:33
		CHECKER Jayant Yadav Status: Pending_Supervisor

Checklist: AL Window Checklists

QUESTION	STATUS	ATTEMPT DETAILS
Aluminium window & locks are working smoothly	COMPLETED (1 attempt)	<p>Attempt 1</p> <p>CHECKER Jayant Yadav Status: Completed 26-08-2025 07:12</p>
Anchor fasteners are provided as per drawing	COMPLETED (1 attempt)	<p>Attempt 1</p> <p>CHECKER Jayant Yadav Status: Completed 26-08-2025 07:12</p>
The shutter lock is functioning properly	COMPLETED (2 attempts)	<p>Attempt 1</p> <p>CHECKER Jayant Yadav Status: Rejected_By_Checker 26-08-2025 07:12</p> <p>Attempt 2</p> <p>MAKER Devendra Verma 26-08-2025 07:34</p> <p>CHECKER Jayant Yadav Status: Pending_Supervisor</p>

QUESTION	STATUS	ATTEMPT DETAILS
No damage or peeling of the coating was observed on the window.	COMPLETED (1 attempt)	Attempt 1 CHECKER Jayant Yadav Status: Completed 26-08-2025 07:12
The roller was functioning properly during the operation of the sliding shutter.	COMPLETED (1 attempt)	Attempt 1 CHECKER Jayant Yadav Status: Completed 26-08-2025 07:12
The coating on the living balcony track angle is observed to be proper.	COMPLETED (2 attempts)	Attempt 1 CHECKER Jayant Yadav Status: Rejected_By_Checker 26-08-2025 07:12
		Attempt 2 MAKER Devendra Verma 26-08-2025 07:34
		CHECKER Jayant Yadav Status: Pending_Supervisor

QUESTION	STATUS	ATTEMPT DETAILS
Silicone sealant has been properly filled around the window periphery	COMPLETED (2 attempts)	Attempt 1 CHECKER Jayant Yadav Status: Rejected_By_Checker 26-08-2025 07:12
		Attempt 2 MAKER Devendra Verma 26-08-2025 07:34

Gasket is fixed properly, drain caps are provided	COMPLETED (1 attempt)	Attempt 1 CHECKER Jayant Yadav Status: Completed 26-08-2025 07:11
--	---------------------------------	--

QUESTION	STATUS	ATTEMPT DETAILS
No cracks/ scratches are observed on the window glass	COMPLETED <small>(2 attempts)</small>	Attempt 1 CHECKER Jayant Yadav Status: Rejected_By_Checker Remarks: Cracks not fixed 26-08-2025 07:11 
		Attempt 2 MAKER Devendra Verma 26-08-2025 07:34 CHECKER Jayant Yadav Status: Pending_Supervisor

Checklist: Painting Checklists

QUESTION	STATUS	ATTEMPT DETAILS
Internal painting is done up to the mark without any patch work is balance or without any shade variation of paint	COMPLETED (1 attempt)	Attempt 1 CHECKER Jayant Yadav Status: Completed 26-08-2025 07:12
The wall paint finish is found to be uniform.	COMPLETED (1 attempt)	Attempt 1 CHECKER Jayant Yadav Status: Completed 26-08-2025 07:12
The skirting projection from the wall is observed to be proper and uniform	COMPLETED (2 attempts)	Attempt 1 CHECKER Anurag Sharmaa Status: Rejected_By_Checker Remarks: skirting projection uneven at door corner 22-08-2025 11:09 

QUESTION	STATUS	ATTEMPT DETAILS
		<p>Attempt 2</p> <p>MAKER Devendra Verma 26-08-2025 07:34</p> <p>CHECKER Anurag Sharmaa Status: Pending_Supervisor</p>
The wall internal corners of rooms paint is found to be proper & uniform	COMPLETED (1 attempt)	<p>Attempt 1</p> <p>CHECKER Jayant Yadav Status: Completed 26-08-2025 07:12</p>
The walls are observed without any undulations	COMPLETED (2 attempts)	<p>Attempt 1</p> <p>CHECKER Jayant Yadav Status: Rejected_By_Checker 26-08-2025 07:12</p> <p>Attempt 2</p> <p>MAKER Devendra Verma 26-08-2025 07:34</p> <p>CHECKER Jayant Yadav Status: Pending_Supervisor</p>

QUESTION	STATUS	ATTEMPT DETAILS
No Cracks observed in walls	COMPLETED (1 attempt)	Attempt 1 CHECKER Jayant Yadav Status: Completed 26-08-2025 07:12
Is the surface preparation done properly for wallpaper fixing	COMPLETED (2 attempts)	Attempt 1 CHECKER Jayant Yadav Status: Rejected_By_Checker 26-08-2025 07:12
		Attempt 2 MAKER Devendra Verma 26-08-2025 07:34
		CHECKER Jayant Yadav Status: Pending_Supervisor

Checklist: Flase Ceiling Checklists

QUESTION	STATUS	ATTEMPT DETAILS
No Cracks observed in false ceiling	COMPLETED (1 attempt)	<p>Attempt 1</p> <p>CHECKER Jayant Yadav Status: Completed 26-08-2025 07:13</p>
Finishing around the lights and sprinkler is done properly	COMPLETED (2 attempts)	<p>Attempt 1</p> <p>CHECKER Jayant Yadav Status: Rejected_By_Checker Remarks: finishing not yet done 26-08-2025 07:13</p> 
		<p>Attempt 2</p> <p>MAKER Devendra Verma 26-08-2025 07:35</p> <p>CHECKER Jayant Yadav Status: Pending_Supervisor</p>

QUESTION	STATUS	ATTEMPT DETAILS
Cove area facia edges are in line and level and thickness maintained	COMPLETED (2 attempts)	<p>Attempt 1</p> <p>CHECKER Jayant Yadav Status: Rejected_By_Checker 26-08-2025 07:13</p>
		<p>Attempt 2</p> <p>MAKER Devendra Verma 26-08-2025 07:35</p>
		<p>CHECKER Jayant Yadav Status: Pending_Supervisor</p>
Is the false ceiling joints finished evenly without any undulations	COMPLETED (2 attempts)	<p>Attempt 1</p> <p>CHECKER Jayant Yadav Status: Rejected_By_Checker 26-08-2025 07:13</p>
		<p>Attempt 2</p> <p>MAKER Devendra Verma 26-08-2025 07:35</p>
		<p>CHECKER Jayant Yadav Status: Pending_Supervisor</p>

Checklist: Electrical Checklists


QUESTION	STATUS	ATTEMPT DETAILS
All switches ,switch plates fixed properly in line and level.	COMPLETED (1 attempt)	Attempt 1 CHECKER Jayant Yadav Status: Completed 26-08-2025 07:14
The chart has been fixed on the distribution board	COMPLETED (1 attempt)	Attempt 1 CHECKER Jayant Yadav Status: Completed 26-08-2025 07:14
All lights are working properly	COMPLETED (2 attempts)	Attempt 1 CHECKER Jayant Yadav Status: Rejected_By_Checker 26-08-2025 07:14
		Attempt 2 MAKER Devendra Verma 26-08-2025 07:33
		CHECKER Jayant Yadav Status: Pending_Supervisor

QUESTION	STATUS	ATTEMPT DETAILS
Main DB box fixed properly with All screws available and SLD is provided	COMPLETED (1 attempt)	Attempt 1 CHECKER Jayant Yadav Status: Completed Remarks: all okay 26-08-2025 07:14 

Checklist: AC Checklists

QUESTION	STATUS	ATTEMPT DETAILS
No Water Leakage Observed in Internal AC Unit	COMPLETED (1 attempt)	Attempt 1 CHECKER Jayant Yadav Status: Completed 26-08-2025 07:14
AC IDU is fixed in line and level	COMPLETED (2 attempts)	Attempt 1 CHECKER Jayant Yadav Status: Rejected_By_Checker 26-08-2025 07:14
		Attempt 2 MAKER Devendra Verma 26-08-2025 07:34

Checklist: Polish Checklists

QUESTION	STATUS	ATTEMPT DETAILS
Door frame polishing is carried out upto the mark	COMPLETED (2 attempts)	Attempt 1 CHECKER Jayant Yadav Status: Rejected_By_Checker 26-08-2025 07:15 
		Attempt 2 MAKER Devendra Verma 26-08-2025 07:35 CHECKER Jayant Yadav Status: Pending_Supervisor

The polish on the top surface of the shutter is Uniformly applied.	COMPLETED (1 attempt)	Attempt 1 CHECKER Jayant Yadav Status: Completed 26-08-2025 07:14
---	---------------------------------	--

Checklist: Carpentry Checklists

QUESTION	STATUS	ATTEMPT DETAILS
All hardwares fixed properly as per the approved drawing and dimensions	COMPLETED (2 attempts)	<p>Attempt 1</p> <p>CHECKER Jayant Yadav Status: Rejected_By_Checker 26-08-2025 07:16</p>
		<p>Attempt 2</p> <p>MAKER Devendra Verma 26-08-2025 07:36</p>
		<p>CHECKER Jayant Yadav Status: Pending_Supervisor</p>
Lock slot is cut properly, lock plate, Architrave is fixed properly	COMPLETED (2 attempts)	<p>Attempt 1</p> <p>CHECKER Jayant Yadav Status: Rejected_By_Checker 26-08-2025 07:16</p>
		<p>Attempt 2</p> <p>MAKER Devendra Verma 26-08-2025 07:36</p>
		<p>CHECKER Jayant Yadav Status: Pending_Supervisor</p>

QUESTION	STATUS	ATTEMPT DETAILS
Hinges screws are fixed properly, screw heads flushed with plates	COMPLETED (1 attempt)	Attempt 1 CHECKER Jayant Yadav Status: Completed 26-08-2025 07:16
The intumescent strip has been properly fixed on the door shutters.	COMPLETED (2 attempts)	Attempt 1 CHECKER Jayant Yadav Status: Rejected_By_Checker 26-08-2025 07:16
		Attempt 2 MAKER Devendra Verma 26-08-2025 07:36
		CHECKER Jayant Yadav Status: Pending_Supervisor
The hinge slots are properly cut, and the hinges were fixed.	COMPLETED (1 attempt)	Attempt 1 CHECKER Jayant Yadav Status: Completed 26-08-2025 07:16

QUESTION	STATUS	ATTEMPT DETAILS
Screws are provided and fixed as per the hinge screw holes.	COMPLETED (1 attempt)	Attempt 1 CHECKER Jayant Yadav Status: Completed 26-08-2025 07:16
Is the 3mm gap is maintained at door frame bottom and sealant is applied	COMPLETED (1 attempt)	Attempt 1 CHECKER Jayant Yadav Status: Completed 26-08-2025 07:16
Proper and equal gap is maintained between door shutter and flooring.	COMPLETED (2 attempts)	Attempt 1 CHECKER Jayant Yadav Status: Rejected_By_Checker 26-08-2025 07:16
		Attempt 2 MAKER Devendra Verma 26-08-2025 07:36
		CHECKER Jayant Yadav Status: Pending_Supervisor

QUESTION	STATUS	ATTEMPT DETAILS
The gap between the frame and the shutter should be proper and uniform.	COMPLETED (1 attempt)	Attempt 1 CHECKER Jayant Yadav Status: Completed 26-08-2025 07:16
Is the lock and other hardwares fixed properly and working smoothly.	COMPLETED (2 attempts)	Attempt 1 CHECKER Jayant Yadav Status: Rejected_By_Checker 26-08-2025 07:16
Attempt 2		
MAKER Devendra Verma 26-08-2025 07:36		
CHECKER Jayant Yadav Status: Pending_Supervisor		


Checklist: Flooring Checklists

QUESTION	STATUS	ATTEMPT DETAILS
Floor tiles no crack, chipped off observed	COMPLETED (1 attempt)	Attempt 1 CHECKER Jayant Yadav Status: Completed 26-08-2025 07:16
Floor ling observed without any leapages/ offsets	COMPLETED (2 attempts)	Attempt 1 CHECKER Jayant Yadav Status: Rejected_By_Checker 26-08-2025 07:16
		Attempt 2 MAKER Devendra Verma 26-08-2025 07:36

Checklist: Carpentry Checklists

QUESTION	STATUS	ATTEMPT DETAILS
Floor tiles no crack, chipped off observed	COMPLETED (2 attempts)	<p>Attempt 1</p> <p>CHECKER Jayant Yadav Status: Rejected_By_Checker 26-08-2025 07:16</p>
		<p>Attempt 2</p> <p>MAKER Devendra Verma 26-08-2025 07:36</p>
		<p>CHECKER Jayant Yadav Status: Pending_Supervisor</p>
Floor ling observed without any leapages/ offsets	COMPLETED (1 attempt)	<p>Attempt 1</p> <p>CHECKER Jayant Yadav Status: Completed 26-08-2025 07:16</p>
Hinges screws are fixed properly, screw heads flushed with plates	COMPLETED (1 attempt)	<p>Attempt 1</p> <p>CHECKER Jayant Yadav Status: Completed 26-08-2025 07:16</p>

QUESTION	STATUS	ATTEMPT DETAILS
The intumescent strip has been properly fixed on the door shutters.	COMPLETED (2 attempts)	<p>Attempt 1</p> <p>CHECKER Jayant Yadav Status: Rejected_By_Checker 26-08-2025 07:16</p>
		<p>Attempt 2</p> <p>MAKER Devendra Verma 26-08-2025 07:36</p>
		<p>CHECKER Jayant Yadav Status: Pending_Supervisor</p>
The hinge slots are properly cut, and the hinges were fixed.	COMPLETED (2 attempts)	<p>Attempt 1</p> <p>CHECKER Jayant Yadav Status: Rejected_By_Checker 26-08-2025 07:16</p>
		<p>Attempt 2</p> <p>MAKER Devendra Verma 26-08-2025 07:36</p>
		<p>CHECKER Jayant Yadav Status: Pending_Supervisor</p>

QUESTION	STATUS	ATTEMPT DETAILS
Screws are provided and fixed as per the hinge screw holes.	COMPLETED (1 attempt)	<p>Attempt 1</p> <p>CHECKER Jayant Yadav Status: Completed 26-08-2025 07:16</p>
Is the 3mm gap is maintained at door frame bottom and sealant is applied	COMPLETED (2 attempts)	<p>Attempt 1</p> <p>CHECKER Jayant Yadav Status: Rejected_By_Checker Remarks: not okay 26-08-2025 07:18</p>  <p>Attempt 2</p> <p>MAKER Devendra Verma 26-08-2025 07:36</p> <p>CHECKER Jayant Yadav Status: Pending_Supervisor</p>

QUESTION	STATUS	ATTEMPT DETAILS
Proper and equal gap is maintained between door shutter and flooring.	COMPLETED (1 attempt)	Attempt 1 CHECKER Jayant Yadav Status: Completed 26-08-2025 07:16
The gap between the frame and the shutter should be proper and uniform.	COMPLETED (2 attempts)	Attempt 1 CHECKER Jayant Yadav Status: Rejected_By_Checker 26-08-2025 07:16
		Attempt 2 MAKER Devendra Verma 26-08-2025 07:36
		 CHECKER Jayant Yadav Status: Pending_Supervisor
Is the lock and other hardwares fixed properly and working smoothly.	COMPLETED (2 attempts)	Attempt 1 CHECKER Jayant Yadav Status: Rejected_By_Checker 26-08-2025 07:16

QUESTION	STATUS	ATTEMPT DETAILS
		<p>Attempt 2</p> <p>MAKER Devendra Verma 26-08-2025 07:36</p> <p>CHECKER Jayant Yadav Status: Pending_Supervisor</p>

Checklist: Dado Checklists

QUESTION	STATUS	ATTEMPT DETAILS
No hollow sound / debonding of tiles is observed	COMPLETED (1 attempt)	<p>Attempt 1</p> <p>CHECKER Jayant Yadav Status: Completed 26-08-2025 07:18</p>
No cracks observed in Dado tile	COMPLETED (1 attempt)	<p>Attempt 1</p> <p>CHECKER Jayant Yadav Status: Completed 26-08-2025 07:18</p>
No dado tiles are chipped off, edges not magaed	COMPLETED (2 attempts)	<p>Attempt 1</p> <p>CHECKER Jayant Yadav Status: Rejected_By_Checker 26-08-2025 07:18</p> <p>Attempt 2</p> <p>MAKER Devendra Verma 26-08-2025 07:36</p> <p>CHECKER Jayant Yadav Status: Pending_Supervisor</p>

QUESTION	STATUS	ATTEMPT DETAILS
No hollowness is observed in the marble jamb of the kitchen door opening.	COMPLETED (1 attempt)	Attempt 1 CHECKER Jayant Yadav Status: Completed 26-08-2025 07:18
After fixing the CP connector, no tile damage or cracks are observed.	COMPLETED (2 attempts)	Attempt 1 CHECKER Jayant Yadav Status: Rejected_By_Checker 26-08-2025 07:18
		Attempt 2 MAKER Devendra Verma 26-08-2025 07:36
		 CHECKER Jayant Yadav Status: Pending_Supervisor
Below kitchen Platform Dado tiles are not chipped off, no cracks observed	COMPLETED (2 attempts)	Attempt 1 CHECKER Jayant Yadav Status: Rejected_By_Checker 26-08-2025 07:18

QUESTION	STATUS	ATTEMPT DETAILS
		<p>Attempt 2</p> <p>MAKER Devendra Verma 26-08-2025 07:36</p> <p>CHECKER Jayant Yadav Status: Pending_Supervisor</p>
All bird mouth joints are finished properly with emery.	COMPLETED (1 attempt)	<p>Attempt 1</p> <p>CHECKER Jayant Yadav Status: Completed 26-08-2025 07:18</p>
Kitchen platform top marble/ quartz drip mould is provided on edge	COMPLETED (1 attempt)	<p>Attempt 1</p> <p>CHECKER Jayant Yadav Status: Completed 26-08-2025 07:18</p>
Kitchen opening marble is fixed in proper line and plumb, marble is not chipped off, No cracks observed in marble jambs, joints of marble jambs are finished properly.	COMPLETED (1 attempt)	<p>Attempt 1</p> <p>CHECKER Jayant Yadav Status: Completed 26-08-2025 07:19</p>

Checklist: Skirting Checklists

QUESTION	STATUS	ATTEMPT DETAILS
skirting is fixed properly in line without any offsets	COMPLETED (1 attempt)	Attempt 1 CHECKER Jayant Yadav Status: Completed 26-08-2025 07:19

Checklist: Modular Kitchen Checklists

QUESTION	STATUS	ATTEMPT DETAILS
All cabinets working smoothly, hinges of approved make are provided.	COMPLETED (2 attempts)	<p>Attempt 1</p> <p>CHECKER Jayant Yadav Status: Rejected_By_Checker 26-08-2025 07:19</p>
		<p>Attempt 2</p> <p>MAKER Devendra Verma 26-08-2025 07:36</p>
		<p>CHECKER Jayant Yadav Status: Pending_Supervisor</p>
Gas pump/ Spring hinges provided	COMPLETED (2 attempts)	<p>Attempt 1</p> <p>CHECKER Jayant Yadav Status: Rejected_By_Checker 26-08-2025 07:19</p>
		<p>Attempt 2</p> <p>MAKER Devendra Verma 26-08-2025 07:36</p>
		<p>CHECKER Jayant Yadav Status: Pending_Supervisor</p>

QUESTION	STATUS	ATTEMPT DETAILS
All cabinet shutters are intact, coating is not damaged	COMPLETED (1 attempt)	<p>Attempt 1</p> <p>CHECKER Jayant Yadav Status: Completed 26-08-2025 07:19</p>
Proper alignment is observed in the top and bottom unit shutters	COMPLETED (2 attempts)	<p>Attempt 1</p> <p>CHECKER Jayant Yadav Status: Rejected_By_Checker 26-08-2025 07:19</p> <p>Attempt 2</p> <p>MAKER Devendra Verma 26-08-2025 07:36</p> <p>CHECKER Jayant Yadav Status: Pending_Supervisor</p>
The cabinet's internal screw caps were found okay	COMPLETED (1 attempt)	<p>Attempt 1</p> <p>CHECKER Jayant Yadav Status: Completed 26-08-2025 07:19</p>

QUESTION	STATUS	ATTEMPT DETAILS
No rust is found on the bottom unit shutter hinges	COMPLETED (2 attempts)	<p>Attempt 1</p> <p>CHECKER Jayant Yadav Status: Rejected_By_Checker 26-08-2025 07:19</p>
		<p>Attempt 2</p> <p>MAKER Devendra Verma 26-08-2025 07:36</p>
		<p>CHECKER Jayant Yadav Status: Pending_Supervisor</p>
Top storages are provided with pivot hinges/ kechi hinges	COMPLETED (1 attempt)	<p>Attempt 1</p> <p>CHECKER Jayant Yadav Status: Completed 26-08-2025 07:19</p>
All horizontal partitions are provided with load capacity stickers	COMPLETED (2 attempts)	<p>Attempt 1</p> <p>CHECKER Jayant Yadav Status: Rejected_By_Checker 26-08-2025 07:19</p>

QUESTION	STATUS	ATTEMPT DETAILS
		<p>Attempt 2</p> <p>MAKER Devendra Verma 26-08-2025 07:36</p> <p>CHECKER Jayant Yadav Status: Pending_Supervisor</p>
The drawer for the cutlery tray closes smoothly and properly	COMPLETED (2 attempts)	<p>Attempt 1</p> <p>CHECKER Jayant Yadav Status: Rejected_By_Checker 26-08-2025 07:19</p>
		<p>Attempt 2</p> <p>MAKER Devendra Verma 26-08-2025 07:36</p> <p>CHECKER Jayant Yadav Status: Pending_Supervisor</p>
Marble Countertop is Polished and Crack-Free & Joint Between Marble Countertop and Dado Wall is properly Sealed with Silicone.	COMPLETED (1 attempt)	<p>Attempt 1</p> <p>CHECKER Jayant Yadav Status: Completed 26-08-2025 07:19</p>

Checklist: AL Window Checklists

QUESTION	STATUS	ATTEMPT DETAILS
The shutter lock is functioning properly	COMPLETED (2 attempts)	<p>Attempt 1</p> <p>CHECKER Jayant Yadav Status: Rejected_By_Checker 26-08-2025 07:22</p>
		<p>Attempt 2</p> <p>MAKER Devendra Verma 26-08-2025 07:36</p>
		<p>CHECKER Jayant Yadav Status: Pending_Supervisor</p>
No damage or peeling of the coating was observed on the window.	COMPLETED (1 attempt)	<p>Attempt 1</p> <p>CHECKER Jayant Yadav Status: Completed 26-08-2025 07:22</p>
Silicone sealant has been properly filled around the window periphery	COMPLETED (1 attempt)	<p>Attempt 1</p> <p>CHECKER Jayant Yadav Status: Completed 26-08-2025 07:22</p>

QUESTION	STATUS	ATTEMPT DETAILS
The roller was functioning properly during the operation of the sliding shutter.	COMPLETED (2 attempts)	Attempt 1 CHECKER Jayant Yadav Status: Rejected_By_Checker 26-08-2025 07:22
		Attempt 2 MAKER Devendra Verma 26-08-2025 07:36

Checklist: Electrical Checklists

QUESTION	STATUS	ATTEMPT DETAILS
Switches and Sockets Properly fixed and functional	COMPLETED (1 attempt)	Attempt 1 CHECKER Jayant Yadav Status: Completed 26-08-2025 07:22

Checklist: Plumbing Checklists

QUESTION	STATUS	ATTEMPT DETAILS
WC , Washbasin, and Shower Fixtures Installed and Leak-Free.	COMPLETED (1 attempt)	Attempt 1 CHECKER Jayant Yadav Status: Completed 26-08-2025 07:22
All Accessories like Towel Rod, Brush Holder, Partition Glass, Mirror are fixed properly.	COMPLETED (2 attempts)	Attempt 1 CHECKER Jayant Yadav Status: Rejected_By_Checker 26-08-2025 07:22
		Attempt 2 MAKER Devendra Verma 26-08-2025 07:37
		CHECKER Jayant Yadav Status: Pending_Supervisor
Darin pipes fixing, saddling is done properly and connections are leakfree	COMPLETED (2 attempts)	Attempt 1 CHECKER Jayant Yadav Status: Rejected_By_Checker 26-08-2025 07:22

QUESTION	STATUS	ATTEMPT DETAILS
		<p>Attempt 2</p> <p>MAKER Devendra Verma 26-08-2025 07:37</p> <p>CHECKER Jayant Yadav Status: Pending_Supervisor</p>

Checklist: Polish Checklists

QUESTION	STATUS	ATTEMPT DETAILS
Door frame polishing is carried out upto the mark	COMPLETED (2 attempts)	Attempt 1 CHECKER Jayant Yadav Status: Rejected_By_Checker 26-08-2025 07:23
		Attempt 2 MAKER Devendra Verma 26-08-2025 07:37
		 CHECKER Jayant Yadav Status: Pending_Supervisor
The polish on the top surface of the shutter is Uniformly applied.	COMPLETED (2 attempts)	Attempt 1 CHECKER Jayant Yadav Status: Rejected_By_Checker 26-08-2025 07:23
		Attempt 2 MAKER Devendra Verma 26-08-2025 07:37
		 CHECKER Jayant Yadav Status: Pending_Supervisor

Checklist: Carpentry Checklists

QUESTION	STATUS	ATTEMPT DETAILS
All hardwares fixed properly as per the approved drawing and dimensions	COMPLETED (2 attempts)	<p>Attempt 1</p> <p>CHECKER Jayant Yadav Status: Rejected_By_Checker 26-08-2025 07:24</p>
		<p>Attempt 2</p> <p>MAKER Devendra Verma 26-08-2025 07:38</p>
		<p>CHECKER Jayant Yadav Status: Pending_Supervisor</p>
Lock slot is cut properly, lock plate, Architrave is fixed properly	COMPLETED (1 attempt)	<p>Attempt 1</p> <p>CHECKER Jayant Yadav Status: Completed 26-08-2025 07:24</p>
Hinges screws are fixed properly, screw heads flushed with plates	COMPLETED (1 attempt)	<p>Attempt 1</p> <p>CHECKER Jayant Yadav Status: Completed 26-08-2025 07:24</p>

QUESTION	STATUS	ATTEMPT DETAILS
Is the 3mm gap is maintained at door frame bottom and sealant is applied	COMPLETED (1 attempt)	Attempt 1 CHECKER Jayant Yadav Status: Completed 26-08-2025 07:24
Proper and equal gap is maintained between door shutter and flooring.	COMPLETED (1 attempt)	Attempt 1 CHECKER Jayant Yadav Status: Completed 26-08-2025 07:24
Is any undulations observed in Door shutter Laminate	COMPLETED (1 attempt)	Attempt 1 CHECKER Jayant Yadav Status: Completed 26-08-2025 07:24
Is the lock and other hardwares fixed properly and working smoothly.	COMPLETED (1 attempt)	Attempt 1 CHECKER Jayant Yadav Status: Completed 26-08-2025 07:24

Checklist: Flooring Checklists

QUESTION	STATUS	ATTEMPT DETAILS
Floor tiles no crack, chipped off observed	COMPLETED (1 attempt)	Attempt 1 CHECKER Jayant Yadav Status: Completed 26-08-2025 07:25
Floor ling observed without any leapages/ offsets	COMPLETED (1 attempt)	Attempt 1 CHECKER Jayant Yadav Status: Completed 26-08-2025 07:25
Skirting is fixed properly in line without any offsets	COMPLETED (2 attempts)	Attempt 1 CHECKER Jayant Yadav Status: Rejected_By_Checker 26-08-2025 07:25

Checklist: AL Window Checklists

QUESTION	STATUS	ATTEMPT DETAILS
Aluminium window is working smoothly	COMPLETED (1 attempt)	<p>Attempt 1</p> <p>CHECKER Jayant Yadav Status: Completed 26-08-2025 07:25</p>
Anchor fasteners are provided as per drawing	COMPLETED (1 attempt)	<p>Attempt 1</p> <p>CHECKER Jayant Yadav Status: Completed 26-08-2025 07:25</p>
The shutter lock is functioning properly	COMPLETED (1 attempt)	<p>Attempt 1</p> <p>CHECKER Jayant Yadav Status: Completed 26-08-2025 07:25</p>
No damage or peeling of the coating was observed on the window.	COMPLETED (1 attempt)	<p>Attempt 1</p> <p>CHECKER Jayant Yadav Status: Completed 26-08-2025 07:25</p>
The roller is functioning properly during the operation of the sliding shutter.	COMPLETED (1 attempt)	<p>Attempt 1</p> <p>CHECKER Jayant Yadav Status: Completed 26-08-2025 07:25</p>

QUESTION	STATUS	ATTEMPT DETAILS
Silicone sealant has been properly filled around the window periphery	COMPLETED (1 attempt)	Attempt 1 CHECKER Jayant Yadav Status: Completed 26-08-2025 07:25
Gasket is fixed properly, drain caps are provided	COMPLETED (1 attempt)	Attempt 1 CHECKER Jayant Yadav Status: Completed 26-08-2025 07:25
No cracks/scratches are observed on the window glass	COMPLETED (1 attempt)	Attempt 1 CHECKER Jayant Yadav Status: Completed 26-08-2025 07:25

Checklist: Painting Checklists

QUESTION	STATUS	ATTEMPT DETAILS
Internal painting is done up to the mark, No undulations/ patch work is balance	COMPLETED <small>(1 attempt)</small>	<p>Attempt 1</p> <p>CHECKER Jayant Yadav Status: Completed 26-08-2025 07:26</p>
Ensure the shade variation is not observed in painted walls	COMPLETED <small>(2 attempts)</small>	<p>Attempt 1</p> <p>CHECKER Jayant Yadav Status: Rejected_By_Checker 26-08-2025 07:26</p> <p>Attempt 2</p> <p>MAKER Devendra Verma 26-08-2025 07:38</p> <p>CHECKER Jayant Yadav Status: Pending_Supervisor</p>
No Cracks observed in walls	COMPLETED <small>(2 attempts)</small>	<p>Attempt 1</p> <p>CHECKER Jayant Yadav Status: Rejected_By_Checker 26-08-2025 07:26</p>

QUESTION	STATUS	ATTEMPT DETAILS
		<p>Attempt 2</p> <p>MAKER Devendra Verma 26-08-2025 07:38</p> <p>CHECKER Jayant Yadav Status: Pending_Supervisor</p>

Checklist: False ceiling Checklists

QUESTION	STATUS	ATTEMPT DETAILS
No Cracks observed in false ceiling	COMPLETED (1 attempt)	<p>Attempt 1</p> <p>CHECKER Jayant Yadav Status: Completed 26-08-2025 07:27</p>
Cove area facia edges are in line and level and thickness maintained	COMPLETED (1 attempt)	<p>Attempt 1</p> <p>CHECKER Jayant Yadav Status: Completed 26-08-2025 07:27</p>
Finishing around the lights and sprinkler is done properly	COMPLETED (1 attempt)	<p>Attempt 1</p> <p>CHECKER Jayant Yadav Status: Completed 26-08-2025 07:27</p>

Checklist: Electrical Checklists

QUESTION	STATUS	ATTEMPT DETAILS
All switches ,switch plates fixed properly in line and level.	COMPLETED (1 attempt)	Attempt 1 CHECKER Jayant Yadav Status: Completed 26-08-2025 07:27
All lights are working properly	COMPLETED (1 attempt)	Attempt 1 CHECKER Jayant Yadav Status: Completed 26-08-2025 07:27

Checklist: Flooring Checklists

QUESTION	STATUS	ATTEMPT DETAILS
Is the Slope of Toilet flooring ok	COMPLETED (1 attempt)	<p>Attempt 1</p> <p>CHECKER Jayant Yadav Status: Completed 26-08-2025 07:22</p>
No offsets are observed Flooring, tile joints filling is done properly	COMPLETED (2 attempts)	<p>Attempt 1</p> <p>CHECKER Jayant Yadav Status: Rejected_By_Checker 26-08-2025 07:22</p> <p>Attempt 2</p> <p>MAKER Devendra Verma 26-08-2025 07:37</p> <p>CHECKER Jayant Yadav Status: Pending_Supervisor</p>
Is the tile cutting is done properly Around nahani trap	COMPLETED (1 attempt)	<p>Attempt 1</p> <p>CHECKER Jayant Yadav Status: Completed 26-08-2025 07:22</p>

QUESTION	STATUS	ATTEMPT DETAILS
Saddling bracket supports are ok for WC trap of above floor	COMPLETED (2 attempts)	<p>Attempt 1</p> <p>CHECKER Jayant Yadav Status: Rejected_By_Checker 26-08-2025 07:22</p>
		<p>Attempt 2</p> <p>MAKER Devendra Verma 26-08-2025 07:37</p>
		<p>CHECKER Jayant Yadav Status: Pending_Supervisor</p>
The toilet flooring threshold angle has been properly fixed	COMPLETED (1 attempt)	<p>Attempt 1</p> <p>CHECKER Jayant Yadav Status: Completed 26-08-2025 07:22</p>
Floor tile is not damaged/ Chipped off,	COMPLETED (2 attempts)	<p>Attempt 1</p> <p>CHECKER Jayant Yadav Status: Rejected_By_Checker 26-08-2025 07:22</p>

QUESTION	STATUS	ATTEMPT DETAILS
		<p>Attempt 2</p> <p>MAKER Devendra Verma 26-08-2025 07:37</p> <p>CHECKER Jayant Yadav Status: Pending_Supervisor</p>

Checklist: Flooring Checklists

QUESTION	STATUS	ATTEMPT DETAILS
Is the Slope of Toilet flooring ok	COMPLETED (1 attempt)	Attempt 1 CHECKER Jayant Yadav Status: Completed 26-08-2025 07:28
No offsets are observed Flooring, tile joints filling is done properly	COMPLETED (1 attempt)	Attempt 1 CHECKER Jayant Yadav Status: Completed 26-08-2025 07:28
Is the tile cutting is done properly Around nahani trap	COMPLETED (1 attempt)	Attempt 1 CHECKER Jayant Yadav Status: Completed 26-08-2025 07:28
Saddling bracket supports are ok for WC trap of above floor	COMPLETED (1 attempt)	Attempt 1 CHECKER Jayant Yadav Status: Completed 26-08-2025 07:28
The toilet flooring threshold angle has been properly fixed	COMPLETED (1 attempt)	Attempt 1 CHECKER Jayant Yadav Status: Completed 26-08-2025 07:28

QUESTION	STATUS	ATTEMPT DETAILS
Floor tile is not damaged/ Chipped off,	COMPLETED (1 attempt)	Attempt 1 CHECKER Jayant Yadav Status: Completed 26-08-2025 07:28

Checklist: Dado Checklists

QUESTION	STATUS	ATTEMPT DETAILS
No hollow sound / debonding of tiles is observed	COMPLETED (1 attempt)	<p>Attempt 1</p> <p>CHECKER Jayant Yadav Status: Completed 26-08-2025 07:23</p>
No cracks observed in Dado tile	COMPLETED (2 attempts)	<p>Attempt 1</p> <p>CHECKER Jayant Yadav Status: Rejected_By_Checker 26-08-2025 07:23</p> <p>Attempt 2</p> <p>MAKER Devendra Verma 26-08-2025 07:37</p> <p>CHECKER Jayant Yadav Status: Pending_Supervisor</p>
All bird mouth joints are finished properly with emery.	COMPLETED (2 attempts)	<p>Attempt 1</p> <p>CHECKER Jayant Yadav Status: Rejected_By_Checker 26-08-2025 07:23</p>

QUESTION	STATUS	ATTEMPT DETAILS
		<p>Attempt 2</p> <p>MAKER Devendra Verma 26-08-2025 07:37</p> <p>CHECKER Jayant Yadav Status: Pending_Supervisor</p>
No dado tiles are chipped off, edges not magaed	COMPLETED <small>(1 attempt)</small>	<p>Attempt 1</p> <p>CHECKER Jayant Yadav Status: Completed 26-08-2025 07:23</p>
No cracks observed in Ledge wall top marble	COMPLETED <small>(2 attempts)</small>	<p>Attempt 1</p> <p>CHECKER Jayant Yadav Status: Rejected_By_Checker 26-08-2025 07:23</p> <p>Attempt 2</p> <p>MAKER Devendra Verma 26-08-2025 07:37</p> <p>CHECKER Jayant Yadav Status: Pending_Supervisor</p>

QUESTION	STATUS	ATTEMPT DETAILS
In Windows & Door Jamb No hollow sound detected; Tiles are properly bonded.	COMPLETED (2 attempts)	Attempt 1 CHECKER Jayant Yadav Status: Rejected_By_Checker 26-08-2025 07:23
		Attempt 2 MAKER Devendra Verma 26-08-2025 07:37

Checklist: Dado Checklists

QUESTION	STATUS	ATTEMPT DETAILS
No hollow sound / debonding of tiles is observed	COMPLETED (1 attempt)	<p>Attempt 1</p> <p>CHECKER Jayant Yadav Status: Completed 26-08-2025 07:28</p>
No cracks observed in Dado tile	COMPLETED (1 attempt)	<p>Attempt 1</p> <p>CHECKER Jayant Yadav Status: Completed 26-08-2025 07:28</p>
All bird mouth joints are finished properly with emery.	COMPLETED (2 attempts)	<p>Attempt 1</p> <p>CHECKER Jayant Yadav Status: Rejected_By_Checker 26-08-2025 07:28</p> <p>Attempt 2</p> <p>MAKER Devendra Verma 26-08-2025 07:38</p> <p>CHECKER Jayant Yadav Status: Pending_Supervisor</p>

QUESTION	STATUS	ATTEMPT DETAILS
No dado tiles are chipped off, edges not magaed	COMPLETED (1 attempt)	Attempt 1 CHECKER Jayant Yadav Status: Completed 26-08-2025 07:28
No cracks observed in Ledge wall top marble	COMPLETED (1 attempt)	Attempt 1 CHECKER Jayant Yadav Status: Completed 26-08-2025 07:28
In Windows & Door Jamb No hollow sound detected; Tiles are properly bonded.	COMPLETED (1 attempt)	Attempt 1 CHECKER Jayant Yadav Status: Completed 26-08-2025 07:28

Checklist: Polish Checklists

QUESTION	STATUS	ATTEMPT DETAILS
Door frame polishing is carried out upto the mark	COMPLETED (1 attempt)	Attempt 1 CHECKER Jayant Yadav Status: Completed 26-08-2025 07:23
The polish on the top surface of the shutter is Uniformly applied.	COMPLETED (2 attempts)	Attempt 1 CHECKER Jayant Yadav Status: Rejected_By_Checker 26-08-2025 07:23
		Attempt 2 MAKER Devendra Verma 26-08-2025 07:37
		CHECKER Jayant Yadav Status: Pending_Supervisor

Checklist: Polish Checklists

QUESTION	STATUS	ATTEMPT DETAILS
Door frame polishing is carried out upto the mark	COMPLETED <small>(1 attempt)</small>	Attempt 1 CHECKER Jayant Yadav Status: Completed 26-08-2025 07:28
The polish on the top surface of the shutter is Uniformly applied.	COMPLETED <small>(1 attempt)</small>	Attempt 1 CHECKER Jayant Yadav Status: Completed 26-08-2025 07:28

Checklist: Carpentry Checklists

QUESTION	STATUS	ATTEMPT DETAILS
All hardwares fixed properly as per the approved drawing and dimensions	COMPLETED (2 attempts)	<p>Attempt 1</p> <p>CHECKER Jayant Yadav Status: Rejected_By_Checker 26-08-2025 07:24</p>
		<p>Attempt 2</p> <p>MAKER Devendra Verma 26-08-2025 07:37</p>
		<p>CHECKER Jayant Yadav Status: Pending_Supervisor</p>
Lock slot is cut properly, lock plate, Architrave is fixed properly	COMPLETED (1 attempt)	<p>Attempt 1</p> <p>CHECKER Jayant Yadav Status: Completed 26-08-2025 07:24</p>
Hinges screws are fixed properly, screw heads flushed with plates	COMPLETED (1 attempt)	<p>Attempt 1</p> <p>CHECKER Jayant Yadav Status: Completed 26-08-2025 07:24</p>

QUESTION	STATUS	ATTEMPT DETAILS
Is the 3mm gap is maintained at door frame bottom and sealant is applied	COMPLETED (1 attempt)	Attempt 1 CHECKER Jayant Yadav Status: Completed 26-08-2025 07:24
Proper and equal gap is maintained between door shutter and flooring.	COMPLETED (1 attempt)	Attempt 1 CHECKER Jayant Yadav Status: Completed 26-08-2025 07:24
Is any undulations observed in Door shutter Laminate	COMPLETED (1 attempt)	Attempt 1 CHECKER Jayant Yadav Status: Completed 26-08-2025 07:24

Checklist: Carpentry Checklists

QUESTION	STATUS	ATTEMPT DETAILS
All hardwares fixed properly as per the approved drawing and dimensions	COMPLETED (1 attempt)	Attempt 1 CHECKER Jayant Yadav Status: Completed 26-08-2025 07:28
Lock slot is cut properly, lock plate, Architrave is fixed properly	COMPLETED (1 attempt)	Attempt 1 CHECKER Jayant Yadav Status: Completed 26-08-2025 07:28
Hinges screws are fixed properly, screw heads flushed with plates	COMPLETED (2 attempts)	Attempt 1 CHECKER Jayant Yadav Status: Rejected_By_Checker 26-08-2025 07:28
		Attempt 2 MAKER Devendra Verma 26-08-2025 07:38
		CHECKER Jayant Yadav Status: Pending_Supervisor

QUESTION	STATUS	ATTEMPT DETAILS
Is the 3mm gap is maintained at door frame bottom and sealant is applied	COMPLETED (1 attempt)	Attempt 1 CHECKER Jayant Yadav Status: Completed 26-08-2025 07:28
Proper and equal gap is maintained between door shutter and flooring.	COMPLETED (1 attempt)	Attempt 1 CHECKER Jayant Yadav Status: Completed 26-08-2025 07:28
Is any undulations observed in Door shutter Laminate	COMPLETED (1 attempt)	Attempt 1 CHECKER Jayant Yadav Status: Completed 26-08-2025 07:28

Checklist: False ceiling Chekclists

QUESTION	STATUS	ATTEMPT DETAILS
The toilet false ceiling finishing was found to be satisfactory.	COMPLETED (1 attempt)	Attempt 1 CHECKER Jayant Yadav Status: Completed 26-08-2025 07:24
The trap door size and finish were observed to be satisfactory.	COMPLETED (2 attempts)	Attempt 1 CHECKER Jayant Yadav Status: Rejected_By_Checker 26-08-2025 07:24
		Attempt 2 MAKER Devendra Verma 26-08-2025 07:37
		CHECKER Jayant Yadav Status: Pending_Supervisor

Checklist: False ceiling Chekclists

QUESTION	STATUS	ATTEMPT DETAILS
<p>The toilet false ceiling finishing was found to be satisfactory.</p>	COMPLETED (1 attempt)	Attempt 1 CHECKER Jayant Yadav Status: Completed 26-08-2025 07:29
<p>The trap door size and finish were observed to be satisfactory.</p>	COMPLETED (1 attempt)	Attempt 1 CHECKER Jayant Yadav Status: Completed 26-08-2025 07:29

Checklist: Mirror Checklists

QUESTION	STATUS	ATTEMPT DETAILS
The gypsum on the back side wall behind the mirror was observed to have a proper finish	COMPLETED (2 attempts)	Attempt 1 CHECKER Jayant Yadav Status: Completed 26-08-2025 07:25
		Attempt 2 CHECKER Jayant Yadav Status: Completed 26-08-2025 07:25
Is the mirror fixed properly	COMPLETED (3 attempts)	Attempt 1 CHECKER Jayant Yadav Status: Rejected_By_Checker 26-08-2025 07:25
		Attempt 2 CHECKER Jayant Yadav Status: Created
		Attempt 3 CHECKER Jayant Yadav Status: Completed 26-08-2025 07:25

Checklist: Mirror Checklists

QUESTION	STATUS	ATTEMPT DETAILS
The gypsum on the back side wall behind the mirror was observed to have a proper finish	COMPLETED (1 attempt)	Attempt 1 CHECKER Jayant Yadav Status: Completed 26-08-2025 07:29
Is the mirror fixed properly	COMPLETED (1 attempt)	Attempt 1 CHECKER Jayant Yadav Status: Completed 26-08-2025 07:29

Checklist: Glass Partition Checklists

QUESTION	STATUS	ATTEMPT DETAILS
Is the glass partition fixed properly and sealant is applied / gasket is provided in gap near wall tile	COMPLETED (1 attempt)	Attempt 1 CHECKER Jayant Yadav Status: Completed 26-08-2025 07:26

Checklist: Glass Partition Checklists

QUESTION	STATUS	ATTEMPT DETAILS
Is the glass partition fixed properly and sealant is applied / gasket is provided in gap near wall tile	COMPLETED (1 attempt)	Attempt 1 CHECKER Jayant Yadav Status: Completed 26-08-2025 07:29

Checklist: Plumbing Checklists

QUESTION	STATUS	ATTEMPT DETAILS
All CP fitting installed and working properly	COMPLETED (1 attempt)	<p>Attempt 1</p> <p>CHECKER Jayant Yadav Status: Completed 26-08-2025 07:26</p>
Shower mixer/diverter working properly	COMPLETED (1 attempt)	<p>Attempt 1</p> <p>CHECKER Jayant Yadav Status: Completed 26-08-2025 07:26</p>
Is the Wash basin bottle trap fixed without any leakage	COMPLETED (2 attempts)	<p>Attempt 1</p> <p>CHECKER Jayant Yadav Status: Rejected_By_Checker 26-08-2025 07:26</p> <p>Attempt 2</p> <p>MAKER Devendra Verma 26-08-2025 07:37</p> <p>CHECKER Jayant Yadav Status: Pending_Supervisor</p>

QUESTION	STATUS	ATTEMPT DETAILS
All valves are Working properly without any leakage	COMPLETED (2 attempts)	Attempt 1 CHECKER Jayant Yadav Status: Rejected_By_Checker 26-08-2025 07:26
		Attempt 2 MAKER Devendra Verma 26-08-2025 07:37

Checklist: Plumbing Checklists

QUESTION	STATUS	ATTEMPT DETAILS
All CP fitting installed and working properly	COMPLETED (1 attempt)	<p>Attempt 1</p> <p>CHECKER Jayant Yadav Status: Completed 26-08-2025 07:30</p>
Shower mixer/diverter working properly	COMPLETED (1 attempt)	<p>Attempt 1</p> <p>CHECKER Jayant Yadav Status: Completed 26-08-2025 07:30</p>
Is the Wash basin bottle trap fixed without any leakage	COMPLETED (1 attempt)	<p>Attempt 1</p> <p>CHECKER Jayant Yadav Status: Completed 26-08-2025 07:30</p>
All valves are Working properly without any leakage	COMPLETED (1 attempt)	<p>Attempt 1</p> <p>CHECKER Jayant Yadav Status: Completed 26-08-2025 07:30</p>

Checklist: Waterproofing Checklists

QUESTION	STATUS	ATTEMPT DETAILS
Any leakages observed in ceiling of toilet	COMPLETED (1 attempt)	Attempt 1 CHECKER Jayant Yadav Status: Completed 26-08-2025 07:26

Checklist: Waterproofing Checklists

QUESTION	STATUS	ATTEMPT DETAILS
Any leakages observed in ceiling of toilet	COMPLETED (1 attempt)	Attempt 1 CHECKER Jayant Yadav Status: Completed 26-08-2025 07:29

Checklist: Service Window Checklists

QUESTION	STATUS	ATTEMPT DETAILS
the service duct window closes and locks properly.	COMPLETED (1 attempt)	Attempt 1 CHECKER Jayant Yadav Status: Completed 26-08-2025 07:26
No Sacrches are observed on froasted glass and windo frame	COMPLETED (1 attempt)	Attempt 1 CHECKER Jayant Yadav Status: Completed 26-08-2025 07:26
Service window sealant is applied from outside	COMPLETED (1 attempt)	Attempt 1 CHECKER Jayant Yadav Status: Completed 26-08-2025 07:26

Checklist: Service Window Checklists

QUESTION	STATUS	ATTEMPT DETAILS
the service duct window closes and locks properly.	COMPLETED (1 attempt)	Attempt 1 CHECKER Jayant Yadav Status: Completed 26-08-2025 07:30
No Sacrches are observed on froasted glass and windo frame	COMPLETED (1 attempt)	Attempt 1 CHECKER Jayant Yadav Status: Completed 26-08-2025 07:30
Service window sealant is applied from outside	COMPLETED (1 attempt)	Attempt 1 CHECKER Jayant Yadav Status: Completed 26-08-2025 07:30

Checklist: Painting Checklists

QUESTION	STATUS	ATTEMPT DETAILS
All drain pipes and water supply pipes painted as per color codes	COMPLETED (1 attempt)	Attempt 1 CHECKER Jayant Yadav Status: Completed 26-08-2025 07:27

Checklist: Painting Checklists

QUESTION	STATUS	ATTEMPT DETAILS
All drain pipes and water supply pipes painted as per color codes	COMPLETED (1 attempt)	<p>Attempt 1</p> <p>CHECKER Jayant Yadav Status: Completed 26-08-2025 07:29</p>

Checklist: DUCT Checklists

QUESTION	STATUS	ATTEMPT DETAILS
All Plumbing brackets PVC caps are provided.	COMPLETED (1 attempt)	<p>Attempt 1</p> <p>CHECKER Jayant Yadav Status: Completed 26-08-2025 07:27</p>

Checklist: DUCT Checklists

QUESTION	STATUS	ATTEMPT DETAILS
All Plumbing brackets PVC caps are provided.	COMPLETED (1 attempt)	<p>Attempt 1</p> <p>CHECKER Jayant Yadav Status: Completed 26-08-2025 07:30</p>

Stage:

Checklist: Polish Checklists

QUESTION	STATUS	ATTEMPT DETAILS
Polish Finish is Uniform without Patches or Polish Droplets on the frames	PENDING_FOR_INSPECTOR (3 attempts)	<p>CHECKER Anurag Sharmaa Status: Rejected_By_Checker Remarks: polish not finish 22-08-2025 10:14</p> 
		<p>Attempt 2</p> <p>MAKER Devendra Verma 26-08-2025 07:33</p> <p>CHECKER Anurag Sharmaa Status: Pending_Supervisor</p>
		<p>Attempt 3</p> <p>CHECKER Status: Pending_Checker</p>
The polish on the top surface of the shutter is Uniformly applied.	PENDING_FOR_INSPECTOR (2 attempts)	<p>CHECKER Anurag Sharmaa Status: Completed Remarks: done 22-08-2025 10:14</p>

QUESTION	STATUS	ATTEMPT DETAILS
		<p>Attempt 2</p> <p>CHECKER</p> <p>Status: Pending_Checker</p>

Checklist: Carpentry Checklists

QUESTION	STATUS	ATTEMPT DETAILS
All hardwares fixed properly as per the approved drawing and dimensions, Tower bolt and handles fixed properly, peep hole is in place	PENDING_FOR_CHECKER <small>(4 attempts)</small>	CHECKER Jayant Yadav Status: Completed 26-08-2025 07:09
		Attempt 2
		CHECKER Status: Pending_Checker
		Attempt 3
		CHECKER Anurag Sharmaa Status: Rejected_By_Checker 26-08-2025 09:53
		Attempt 4
		CHECKER Anurag Sharmaa Status: Created

QUESTION	STATUS	ATTEMPT DETAILS
Lock slot is cut properly, lock plate, Architrave is fixed properly	PENDING_FOR_INSPECTOR (3 attempts)	<p>CHECKER Anurag Sharmaa Status: Rejected_By_Checker Remarks: not done 22-08-2025 10:52</p> 
Attempt 2		
<p>MAKER Devendra Verma 26-08-2025 07:33</p> <p>CHECKER Anurag Sharmaa Status: Pending_Supervisor</p>		
Attempt 3		
<p>CHECKER Status: Pending_Checker</p>		

QUESTION	STATUS	ATTEMPT DETAILS
The hinge slots are properly cut, and the hinges are fixed properly.	PENDING_FOR_INSPECTOR (2 attempts)	<p>CHECKER Anurag Sharmaa Status: Completed Remarks: done 22-08-2025 10:52</p> 
		Attempt 2
		<p>CHECKER Status: Pending_Checker</p>
Is the hinges screw heads flushed with plates	PENDING_FOR_INSPECTOR (2 attempts)	<p>CHECKER Anurag Sharmaa Status: Completed Remarks: done 22-08-2025 10:52</p>
		Attempt 2
		<p>CHECKER Status: Pending_Checker</p>

QUESTION	STATUS	ATTEMPT DETAILS
The intumescent strip has been properly fixed on the main door and kitchen door shutters.	PENDING_FOR_INSPECTOR (3 attempts)	CHECKER Jayant Yadav Status: Rejected_By_Checker 26-08-2025 07:10
Attempt 2		
MAKER Devendra Verma 26-08-2025 07:33		
Attempt 3		
CHECKER Jayant Yadav Status: Pending_Supervisor		
Attempt 4		
Is any undulations observed in Door shutter Laminate	PENDING_FOR_INSPECTOR (3 attempts)	CHECKER Jayant Yadav Status: Rejected_By_Checker 26-08-2025 07:10

QUESTION	STATUS	ATTEMPT DETAILS
		<p>Attempt 2</p> <p>MAKER Devendra Verma 26-08-2025 07:33</p> <p>CHECKER Jayant Yadav Status: Pending_Supervisor</p>
		<p>Attempt 3</p> <p>CHECKER Status: Pending_Checker</p>
Is the 3mm gap is maintained at door frame bottom and sealant is applied	PENDING_FOR_INSPECTOR (3 attempts)	<p>CHECKER Jayant Yadav Status: Rejected_By_Checker 26-08-2025 07:10</p>
		<p>Attempt 2</p> <p>MAKER Devendra Verma 26-08-2025 07:33</p> <p>CHECKER Jayant Yadav Status: Pending_Supervisor</p>
		<p>Attempt 3</p> <p>CHECKER Status: Pending_Checker</p>

QUESTION	STATUS	ATTEMPT DETAILS
Gap Between Door Shutter and Frame & Shutter Edges with Flooring is uniform & within tolerance limits.	PENDING_FOR_INSPECTOR (3 attempts)	<p>CHECKER Jayant Yadav Status: Rejected_By_Checker 26-08-2025 07:10</p>
		Attempt 2
		<p>MAKER Devendra Verma 26-08-2025 07:33</p>
		<p>CHECKER Jayant Yadav Status: Pending_Supervisor</p>
		Attempt 3
		<p>CHECKER Status: Pending_Checker</p>
Magnetic Door catches & PVC buffers installed at the Correct Location and Securely Fixed	PENDING_FOR_INSPECTOR (2 attempts)	<p>CHECKER Jayant Yadav Status: Completed 26-08-2025 07:10</p>
		Attempt 2
		<p>CHECKER Status: Pending_Checker</p>

QUESTION	STATUS	ATTEMPT DETAILS
Is the lock and other hardwares fixed properly and working smoothly.	PENDING_FOR_INSPECTOR (3 attempts)	<p>CHECKER</p> <p>Jayant Yadav</p> <p>Status: Rejected_By_Checker</p> <p>Remarks: not yet done</p> <p>26-08-2025 07:10</p> 
Attempt 2		
<p>MAKER</p> <p>Devendra Verma</p> <p>26-08-2025 07:33</p>		
<p>CHECKER</p> <p>Jayant Yadav</p> <p>Status: Pending_Supervisor</p>		
Attempt 3		
<p>CHECKER</p> <p>Status: Pending_Checker</p>		

Checklist: Flooring Checklists

QUESTION	STATUS	ATTEMPT DETAILS
Floor tiles no crack, chipped off observed	PENDING_FOR_INSPECTOR (2 attempts)	<p>CHECKER Anurag Sharmaa Status: Completed Remarks: done 22-08-2025 10:24</p>
		Attempt 2
		<p>CHECKER Status: Pending_Checker</p>
Hollow sound is observed in floor tile or skirting	PENDING_FOR_INSPECTOR (3 attempts)	<p>CHECKER Anurag Sharmaa Status: Rejected_By_Checker Remarks: not done 22-08-2025 10:25</p> 
		Attempt 2
		<p>MAKER Devendra Verma 26-08-2025 07:33</p>
		<p>CHECKER Anurag Sharmaa Status: Pending_Supervisor</p>

QUESTION	STATUS	ATTEMPT DETAILS
		<p>Attempt 3</p> <p>CHECKER Status: Pending_Checker</p>
Flooring tiles / marble observed without any leapages/ offsets	PENDING_FOR_INSPECTOR (2 attempts)	<p>CHECKER Anurag Sharmaa Status: Completed Remarks: done 22-08-2025 10:25</p>
		<p>Attempt 2</p> <p>CHECKER Status: Pending_Checker</p>

Checklist: Skirting Checklists

QUESTION	STATUS	ATTEMPT DETAILS
Is the Skirting aligned with Finished top Edge & without offset.	PENDING_FOR_INSPECTOR (2 attempts)	CHECKER Jayant Yadav Status: Completed 26-08-2025 07:10
		Attempt 2
		CHECKER Status: Pending_Checker
The top surface of the tile skirting has been properly finished using a Facile diamond hand pad	PENDING_FOR_INSPECTOR (3 attempts)	CHECKER Jayant Yadav Status: Rejected_By_Checker 26-08-2025 07:10
		Attempt 2
		MAKER Devendra Verma 26-08-2025 07:33
		CHECKER Jayant Yadav Status: Pending_Supervisor
		Attempt 3
		CHECKER Status: Pending_Checker

Checklist: AL Window Checklists

QUESTION	STATUS	ATTEMPT DETAILS
Aluminium window & locks are working smoothly	PENDING_FOR_INSPECTOR (2 attempts)	<p>CHECKER Jayant Yadav Status: Completed 26-08-2025 07:12</p>
		Attempt 2
		<p>CHECKER Status: Pending_Checker</p>
Anchor fasteners are provided as per drawing	PENDING_FOR_INSPECTOR (2 attempts)	<p>CHECKER Jayant Yadav Status: Completed 26-08-2025 07:12</p>
		Attempt 2
		<p>CHECKER Status: Pending_Checker</p>
The shutter lock is functioning properly	PENDING_FOR_INSPECTOR (3 attempts)	<p>CHECKER Jayant Yadav Status: Rejected_By_Checker 26-08-2025 07:12</p>

QUESTION	STATUS	ATTEMPT DETAILS
		<p>Attempt 2</p> <p>MAKER Devendra Verma 26-08-2025 07:34</p> <p>CHECKER Jayant Yadav Status: Pending_Supervisor</p>
		<p>Attempt 3</p> <p>CHECKER Status: Pending_Checker</p>

No damage or peeling of the coating was observed on the window.	PENDING_FOR_INSPECTOR (2 attempts)	CHECKER Jayant Yadav Status: Completed 26-08-2025 07:12
		<p>Attempt 2</p> <p>CHECKER Status: Pending_Checker</p>

The roller was functioning properly during the operation of the sliding shutter.	PENDING_FOR_INSPECTOR (2 attempts)	CHECKER Jayant Yadav Status: Completed 26-08-2025 07:12
---	--	--

QUESTION	STATUS	ATTEMPT DETAILS
		<p>Attempt 2</p> <p>CHECKER Status: Pending_Checker</p>
The coating on the living balcony track angle is observed to be proper.	PENDING_FOR_INSPECTOR (3 attempts)	<p>CHECKER Jayant Yadav Status: Rejected_By_Checker 26-08-2025 07:12</p>
		<p>Attempt 2</p> <p>MAKER Devendra Verma 26-08-2025 07:34</p> <p>CHECKER Jayant Yadav Status: Pending_Supervisor</p>
		<p>Attempt 3</p> <p>CHECKER Status: Pending_Checker</p>
Silicone sealant has been properly filled around the window periphery	PENDING_FOR_INSPECTOR (3 attempts)	<p>CHECKER Jayant Yadav Status: Rejected_By_Checker 26-08-2025 07:12</p>

QUESTION	STATUS	ATTEMPT DETAILS
		<p>Attempt 2</p> <p>MAKER Devendra Verma 26-08-2025 07:34</p>
		<p>CHECKER Jayant Yadav Status: Pending_Supervisor</p>
		<p>Attempt 3</p> <p>CHECKER Status: Pending_Checker</p>
Gasket is fixed properly, drain caps are provided	PENDING_FOR_INSPECTOR (2 attempts)	<p>CHECKER Jayant Yadav Status: Completed 26-08-2025 07:11</p>
		<p>Attempt 2</p> <p>CHECKER Status: Pending_Checker</p>

QUESTION	STATUS	ATTEMPT DETAILS
No cracks/scratches are observed on the window glass	PENDING_FOR_INSPECTOR (3 attempts)	<p>CHECKER</p> <p>Jayant Yadav</p> <p>Status: Rejected_By_Checker</p> <p>Remarks: Cracks not fixed</p> <p>26-08-2025 07:11</p> 
Attempt 2		
<p>MAKER</p> <p>Devendra Verma</p> <p>26-08-2025 07:34</p>		
<p>CHECKER</p> <p>Jayant Yadav</p> <p>Status: Pending_Supervisor</p>		
Attempt 3		
<p>CHECKER</p> <p>Status: Pending_Checker</p>		

Checklist: Painting Checklists

QUESTION	STATUS	ATTEMPT DETAILS
Internal painting is done up to the mark without any patch work is balance or without any shade variation of paint	PENDING_FOR_INSPECTOR (2 attempts)	CHECKER Jayant Yadav Status: Completed 26-08-2025 07:12
		Attempt 2
		CHECKER Status: Pending_Checker
<hr/> The wall paint finish is found to be uniform.	PENDING_FOR_INSPECTOR (2 attempts)	CHECKER Jayant Yadav Status: Completed 26-08-2025 07:12
		Attempt 2
		CHECKER Status: Pending_Checker

QUESTION	STATUS	ATTEMPT DETAILS
The skirting projection from the wall is observed to be proper and uniform	PENDING_FOR_INSPECTOR (3 attempts)	<p>CHECKER Anurag Sharmaa Status: Rejected_By_Checker Remarks: skirting projection uneven at door corner 22-08-2025 11:09</p> 
		<p>Attempt 2</p> <p>MAKER Devendra Verma 26-08-2025 07:34</p> <p>CHECKER Anurag Sharmaa Status: Pending_Supervisor</p>
		<p>Attempt 3</p> <p>CHECKER Status: Pending_Checker</p>
The wall internal corners of rooms paint is found to be proper & uniform	PENDING_FOR_INSPECTOR (2 attempts)	<p>CHECKER Jayant Yadav Status: Completed 26-08-2025 07:12</p>

QUESTION	STATUS	ATTEMPT DETAILS
The walls are observed without any undulations	PENDING_FOR_INSPECTOR (3 attempts)	<p>Attempt 2</p> <p>CHECKER Status: Pending_Checker</p>
No Cracks observed in walls	PENDING_FOR_INSPECTOR (2 attempts)	<p>Attempt 2</p> <p>CHECKER Jayant Yadav Status: Rejected_By_Checker 26-08-2025 07:12</p> <p>Attempt 2</p> <p>MAKER Devendra Verma 26-08-2025 07:34</p> <p>CHECKER Jayant Yadav Status: Pending_Supervisor</p> <p>Attempt 3</p> <p>CHECKER Status: Pending_Checker</p>

QUESTION	STATUS	ATTEMPT DETAILS
		<p>Attempt 2</p> <p>CHECKER Status: Pending_Checker</p>
Is the surface preparation done properly for wallpaper fixing	PENDING_FOR_INSPECTOR (3 attempts)	<p>CHECKER Jayant Yadav Status: Rejected_By_Checker 26-08-2025 07:12</p>
		<p>Attempt 2</p> <p>MAKER Devendra Verma 26-08-2025 07:34</p>
		<p>CHECKER Jayant Yadav Status: Pending_Supervisor</p>
		<p>Attempt 3</p> <p>CHECKER Status: Pending_Checker</p>

Checklist: Flase Ceiling Checklists

QUESTION	STATUS	ATTEMPT DETAILS
No Cracks observed in false ceiling	PENDING_FOR_INSPECTOR (2 attempts)	<p>CHECKER Jayant Yadav Status: Completed 26-08-2025 07:13</p>
		Attempt 2
		<p>CHECKER Status: Pending_Checker</p>
Finishing around the lights and sprinkler is done properly	PENDING_FOR_INSPECTOR (3 attempts)	<p>CHECKER Jayant Yadav Status: Rejected_By_Checker Remarks: finishing not yet done 26-08-2025 07:13</p> 
		Attempt 2
		<p>MAKER Devendra Verma 26-08-2025 07:35</p>
		<p>CHECKER Jayant Yadav Status: Pending_Supervisor</p>

QUESTION	STATUS	ATTEMPT DETAILS
		<p>Attempt 3</p> <p>CHECKER Status: Pending_Checker</p>
Cove area facia edges are in line and level and thickness maintained	<p>PENDING_FOR_INSPECTOR (3 attempts)</p>	<p>CHECKER Jayant Yadav Status: Rejected_By_Checker 26-08-2025 07:13</p>
		<p>Attempt 2</p> <p>MAKER Devendra Verma 26-08-2025 07:35</p> <p>CHECKER Jayant Yadav Status: Pending_Supervisor</p>
		<p>Attempt 3</p> <p>CHECKER Status: Pending_Checker</p>
Is the false ceiling joints finished evenly without any undulations	<p>PENDING_FOR_INSPECTOR (3 attempts)</p>	<p>CHECKER Jayant Yadav Status: Rejected_By_Checker 26-08-2025 07:13</p>

QUESTION	STATUS	ATTEMPT DETAILS
		<p>Attempt 2</p> <p>MAKER Devendra Verma 26-08-2025 07:35</p> <p>CHECKER Jayant Yadav Status: Pending_Supervisor</p>
		<p>Attempt 3</p> <p>CHECKER Status: Pending_Checker</p>

Checklist: Electrical Checklists

QUESTION	STATUS	ATTEMPT DETAILS
All switches ,switch plates fixed properly in line and level.	PENDING_FOR_INSPECTOR (2 attempts)	<p>CHECKER Jayant Yadav Status: Completed 26-08-2025 07:14</p>
		Attempt 2
		<p>CHECKER Status: Pending_Checker</p>
The chart has been fixed on the distribution board	PENDING_FOR_INSPECTOR (2 attempts)	<p>CHECKER Jayant Yadav Status: Completed 26-08-2025 07:14</p>
		Attempt 2
		<p>CHECKER Status: Pending_Checker</p>
All lights are working properly	PENDING_FOR_INSPECTOR (3 attempts)	<p>CHECKER Jayant Yadav Status: Rejected_By_Checker 26-08-2025 07:14</p>


QUESTION	STATUS	ATTEMPT DETAILS
		<p>Attempt 2</p> <p>MAKER Devendra Verma 26-08-2025 07:33</p> <p>CHECKER Jayant Yadav Status: Pending_Supervisor</p>
		<p>Attempt 3</p> <p>CHECKER Status: Pending_Checker</p>

<p>Main DB box fixed properly with All screws available and SLD is provided</p>	<p>PENDING_FOR_INSPECTOR</p> <p>(2 attempts)</p>	<p>CHECKER Jayant Yadav Status: Completed Remarks: all okay 26-08-2025 07:14</p> 
		<p>Attempt 2</p> <p>CHECKER Status: Pending_Checker</p>

Checklist: AC Checklists

QUESTION	STATUS	ATTEMPT DETAILS
No Water Leakage Observed in Internal AC Unit	PENDING_FOR_INSPECTOR (2 attempts)	<p>CHECKER Jayant Yadav Status: Completed 26-08-2025 07:14</p>
		<p>Attempt 2</p> <p>CHECKER Status: Pending_Checker</p>
AC IDU is fixed in line and level	PENDING_FOR_INSPECTOR (3 attempts)	<p>CHECKER Jayant Yadav Status: Rejected_By_Checker 26-08-2025 07:14</p>
		<p>Attempt 2</p> <p>MAKER Devendra Verma 26-08-2025 07:34</p>
		<p>CHECKER Jayant Yadav Status: Pending_Supervisor</p>
		<p>Attempt 3</p> <p>CHECKER Status: Pending_Checker</p>

Checklist: Polish Checklists

QUESTION	STATUS	ATTEMPT DETAILS
Door frame polishing is carried out upto the mark	PENDING_FOR_INSPECTOR (3 attempts)	<p>CHECKER Jayant Yadav Status: Rejected_By_Checker 26-08-2025 07:15</p> 
Attempt 2		
	MAKER Devendra Verma 26-08-2025 07:35	<p>CHECKER Jayant Yadav Status: Pending_Supervisor</p>
Attempt 3		
The polish on the top surface of the shutter is Uniformly applied.	PENDING_FOR_INSPECTOR (2 attempts)	<p>CHECKER Jayant Yadav Status: Completed 26-08-2025 07:14</p>

QUESTION	STATUS	ATTEMPT DETAILS
		<p>Attempt 2</p> <p>CHECKER</p> <p>Status: Pending_Checker</p>

Checklist: Carpentry Checklists

QUESTION	STATUS	ATTEMPT DETAILS
All hardwares fixed properly as per the approved drawing and dimensions	PENDING_FOR_INSPECTOR (3 attempts)	<p>CHECKER Jayant Yadav Status: Rejected_By_Checker 26-08-2025 07:16</p>
		<p>Attempt 2</p> <p>MAKER Devendra Verma 26-08-2025 07:36</p> <p>CHECKER Jayant Yadav Status: Pending_Supervisor</p>
		<p>Attempt 3</p> <p>CHECKER Status: Pending_Checker</p>
Lock slot is cut properly, lock plate, Architrave is fixed properly	PENDING_FOR_INSPECTOR (3 attempts)	<p>CHECKER Jayant Yadav Status: Rejected_By_Checker 26-08-2025 07:16</p>

QUESTION	STATUS	ATTEMPT DETAILS
		<p>Attempt 2</p> <p>MAKER Devendra Verma 26-08-2025 07:36</p> <p>CHECKER Jayant Yadav Status: Pending_Supervisor</p>
		<p>Attempt 3</p> <p>CHECKER Status: Pending_Checker</p>
Hinges screws are fixed properly, screw heads flushed with plates	PENDING_FOR_INSPECTOR (2 attempts)	<p>CHECKER Jayant Yadav Status: Completed 26-08-2025 07:16</p>
		<p>Attempt 2</p> <p>CHECKER Status: Pending_Checker</p>
The intumescent strip has been properly fixed on the door shutters.	PENDING_FOR_INSPECTOR (3 attempts)	<p>CHECKER Jayant Yadav Status: Rejected_By_Checker 26-08-2025 07:16</p>

QUESTION	STATUS	ATTEMPT DETAILS
		<p>Attempt 2</p> <p>MAKER Devendra Verma 26-08-2025 07:36</p> <p>CHECKER Jayant Yadav Status: Pending_Supervisor</p>
		<p>Attempt 3</p> <p>CHECKER Status: Pending_Checker</p>

The hinge slots are properly cut, and the hinges were fixed.	PENDING_FOR_INSPECTOR (2 attempts)	<p>CHECKER Jayant Yadav Status: Completed 26-08-2025 07:16</p>
		<p>Attempt 2</p> <p>CHECKER Status: Pending_Checker</p>

Screws are provided and fixed as per the hinge screw holes.	PENDING_FOR_INSPECTOR (2 attempts)	<p>CHECKER Jayant Yadav Status: Completed 26-08-2025 07:16</p>
---	--	--

QUESTION	STATUS	ATTEMPT DETAILS
		<p>Attempt 2</p> <p>CHECKER Status: Pending_Checker</p>
Is the 3mm gap is maintained at door frame bottom and sealant is applied	<p>PENDING_FOR_INSPECTOR (2 attempts)</p>	<p>CHECKER Jayant Yadav Status: Completed 26-08-2025 07:16</p>
		<p>Attempt 2</p> <p>CHECKER Status: Pending_Checker</p>
Proper and equal gap is maintained between door shutter and flooring.	<p>PENDING_FOR_INSPECTOR (3 attempts)</p>	<p>CHECKER Jayant Yadav Status: Rejected_By_Checker 26-08-2025 07:16</p>
		<p>Attempt 2</p> <p>MAKER Devendra Verma 26-08-2025 07:36</p> <p>CHECKER Jayant Yadav Status: Pending_Supervisor</p>

QUESTION	STATUS	ATTEMPT DETAILS
The gap between the frame and the shutter should be proper and uniform.	PENDING_FOR_INSPECTOR (2 attempts)	<p>Attempt 3</p> <p>CHECKER Status: Pending_Checker</p>
Is the lock and other hardwares fixed properly and working smoothly.	PENDING_FOR_INSPECTOR (3 attempts)	<p>Attempt 2</p> <p>CHECKER Status: Pending_Checker</p>
		<p>Attempt 2</p> <p>MAKER Devendra Verma 26-08-2025 07:36</p> <p>CHECKER Jayant Yadav Status: Pending_Supervisor</p>

QUESTION	STATUS	ATTEMPT DETAILS
		<p>Attempt 3</p> <p>CHECKER</p> <p>Status: Pending_Checker</p>

Checklist: Flooring Checklists


QUESTION	STATUS	ATTEMPT DETAILS
Floor tiles no crack, chipped off observed	PENDING_FOR_INSPECTOR (2 attempts)	CHECKER Jayant Yadav Status: Completed 26-08-2025 07:16
		Attempt 2
		CHECKER Status: Pending_Checker
Floor ling observed without any leapages/ offsets	PENDING_FOR_INSPECTOR (3 attempts)	CHECKER Jayant Yadav Status: Rejected_By_Checker 26-08-2025 07:16
		Attempt 2
		MAKER Devendra Verma 26-08-2025 07:36
		CHECKER Jayant Yadav Status: Pending_Supervisor
		Attempt 3
		CHECKER Status: Pending_Checker

Checklist: Carpentry Checklists

QUESTION	STATUS	ATTEMPT DETAILS
Floor tiles no crack, chipped off observed	PENDING_FOR_INSPECTOR (3 attempts)	<p>CHECKER Jayant Yadav Status: Rejected_By_Checker 26-08-2025 07:16</p>
		<p>Attempt 2</p> <p>MAKER Devendra Verma 26-08-2025 07:36</p>
		<p>CHECKER Jayant Yadav Status: Pending_Supervisor</p>
		<p>Attempt 3</p> <p>CHECKER Status: Pending_Checker</p>
Floor ling observed without any leapages/ offsets	PENDING_FOR_INSPECTOR (2 attempts)	<p>CHECKER Jayant Yadav Status: Completed 26-08-2025 07:16</p>
		<p>Attempt 2</p> <p>CHECKER Status: Pending_Checker</p>

QUESTION	STATUS	ATTEMPT DETAILS
Hinges screws are fixed properly, screw heads flushed with plates	PENDING_FOR_INSPECTOR (2 attempts)	CHECKER Jayant Yadav Status: Completed 26-08-2025 07:16
		Attempt 2
		CHECKER Status: Pending_Checker
The intumescent strip has been properly fixed on the door shutters.	PENDING_FOR_INSPECTOR (3 attempts)	CHECKER Jayant Yadav Status: Rejected_By_Checker 26-08-2025 07:16
		Attempt 2
		MAKER Devendra Verma 26-08-2025 07:36
		CHECKER Jayant Yadav Status: Pending_Supervisor
		Attempt 3
		CHECKER Status: Pending_Checker

QUESTION	STATUS	ATTEMPT DETAILS
The hinge slots are properly cut, and the hinges were fixed.	PENDING_FOR_INSPECTOR (3 attempts)	<p>CHECKER Jayant Yadav Status: Rejected_By_Checker 26-08-2025 07:16</p>
		<p>Attempt 2</p> <p>MAKER Devendra Verma 26-08-2025 07:36</p> <p>CHECKER Jayant Yadav Status: Pending_Supervisor</p>
		<p>Attempt 3</p> <p>CHECKER Status: Pending_Checker</p>
Screws are provided and fixed as per the hinge screw holes.	PENDING_FOR_INSPECTOR (2 attempts)	<p>CHECKER Jayant Yadav Status: Completed 26-08-2025 07:16</p>
		<p>Attempt 2</p> <p>CHECKER Status: Pending_Checker</p>

QUESTION	STATUS	ATTEMPT DETAILS
Is the 3mm gap is maintained at door frame bottom and sealant is applied	PENDING_FOR_INSPECTOR (3 attempts)	<p>CHECKER</p> <p>Jayant Yadav</p> <p>Status: Rejected_By_Checker</p> <p>Remarks: not okay</p> <p>26-08-2025 07:18</p> 
		<p>Attempt 2</p> <p>MAKER</p> <p>Devendra Verma</p> <p>26-08-2025 07:36</p>
		<p>CHECKER</p> <p>Jayant Yadav</p> <p>Status: Pending_Supervisor</p>
		<p>Attempt 3</p> <p>CHECKER</p> <p>Status: Pending_Checker</p>
Proper and equal gap is maintained between door shutter and flooring.	PENDING_FOR_INSPECTOR (2 attempts)	<p>CHECKER</p> <p>Jayant Yadav</p> <p>Status: Completed</p> <p>26-08-2025 07:16</p>

QUESTION	STATUS	ATTEMPT DETAILS
		<p>Attempt 2</p> <p>CHECKER Status: Pending_Checker</p>
The gap between the frame and the shutter should be proper and uniform.	<p>PENDING_FOR_INSPECTOR (3 attempts)</p>	<p>CHECKER Jayant Yadav Status: Rejected_By_Checker 26-08-2025 07:16</p>
		<p>Attempt 2</p> <p>MAKER Devendra Verma 26-08-2025 07:36</p>
		<p>CHECKER Jayant Yadav Status: Pending_Supervisor</p>
		<p>Attempt 3</p> <p>CHECKER Status: Pending_Checker</p>
Is the lock and other hardwares fixed properly and working smoothly.	<p>PENDING_FOR_INSPECTOR (3 attempts)</p>	<p>CHECKER Jayant Yadav Status: Rejected_By_Checker 26-08-2025 07:16</p>

QUESTION	STATUS	ATTEMPT DETAILS
		<p>Attempt 2</p> <p>MAKER Devendra Verma 26-08-2025 07:36</p> <p>CHECKER Jayant Yadav Status: Pending_Supervisor</p>
		<p>Attempt 3</p> <p>CHECKER Status: Pending_Checker</p>

Checklist: Dado Checklists

QUESTION	STATUS	ATTEMPT DETAILS
No hollow sound / debonding of tiles is observed	PENDING_FOR_INSPECTOR (2 attempts)	<p>CHECKER Jayant Yadav Status: Completed 26-08-2025 07:18</p>
		Attempt 2
		<p>CHECKER Status: Pending_Checker</p>
No cracks observed in Dado tile	PENDING_FOR_INSPECTOR (2 attempts)	<p>CHECKER Jayant Yadav Status: Completed 26-08-2025 07:18</p>
		Attempt 2
		<p>CHECKER Status: Pending_Checker</p>
No dado tiles are chipped off, edges not magaed	PENDING_FOR_INSPECTOR (3 attempts)	<p>CHECKER Jayant Yadav Status: Rejected_By_Checker 26-08-2025 07:18</p>

QUESTION	STATUS	ATTEMPT DETAILS
		<p>Attempt 2</p> <div style="border-left: 2px solid green; padding-left: 10px;"> MAKER Devendra Verma 26-08-2025 07:36 </div> <div style="border-left: 2px solid blue; padding-left: 10px;"> CHECKER Jayant Yadav Status: Pending_Supervisor </div>
		<p>Attempt 3</p> <div style="border-left: 2px solid blue; padding-left: 10px;"> CHECKER Status: Pending_Checker </div>

<p>No hollowness is observed in the marble jamb of the kitchen door opening.</p>	<div style="background-color: #e0f2ff; border-radius: 10px; padding: 2px 10px;"> PENDING_FOR_INSPECTOR </div> (2 attempts)	CHECKER Jayant Yadav Status: Completed 26-08-2025 07:18
<p>After fixing the CP connector, no tile damage or cracks are observed.</p>	<div style="background-color: #e0f2ff; border-radius: 10px; padding: 2px 10px;"> PENDING_FOR_INSPECTOR </div> (3 attempts)	CHECKER Jayant Yadav Status: Rejected_By_Checker 26-08-2025 07:18

QUESTION	STATUS	ATTEMPT DETAILS
		<p>Attempt 2</p> <div style="border-left: 2px solid green; padding-left: 10px;"> MAKER Devendra Verma 26-08-2025 07:36 </div> <div style="border-left: 2px solid blue; padding-left: 10px;"> CHECKER Jayant Yadav Status: Pending_Supervisor </div>
		<p>Attempt 3</p> <div style="border-left: 2px solid blue; padding-left: 10px;"> CHECKER Status: Pending_Checker </div>
Below kitchen Platform Dado tiles are not chipped off, no cracks observed	PENDING_FOR_INSPECTOR (3 attempts)	<div style="border-left: 2px solid blue; padding-left: 10px;"> CHECKER Jayant Yadav Status: Rejected_By_Checker 26-08-2025 07:18 </div>
		<p>Attempt 2</p> <div style="border-left: 2px solid green; padding-left: 10px;"> MAKER Devendra Verma 26-08-2025 07:36 </div> <div style="border-left: 2px solid blue; padding-left: 10px;"> CHECKER Jayant Yadav Status: Pending_Supervisor </div>
		<p>Attempt 3</p> <div style="border-left: 2px solid blue; padding-left: 10px;"> CHECKER Status: Pending_Checker </div>

QUESTION	STATUS	ATTEMPT DETAILS
All bird mouth joints are finished properly with emery.	PENDING_FOR_INSPECTOR (2 attempts)	<p>CHECKER Jayant Yadav Status: Completed 26-08-2025 07:18</p> <p>Attempt 2</p> <p>CHECKER Status: Pending_Checker</p>
Kitchen platform top marble/ quartz drip mould is provided on edge	PENDING_FOR_INSPECTOR (2 attempts)	<p>CHECKER Jayant Yadav Status: Completed 26-08-2025 07:18</p> <p>Attempt 2</p> <p>CHECKER Status: Pending_Checker</p>
Kitchen opening marble is fixed in proper line and plumb, marble is not chipped off, No cracks observed in marble jambs, joints of marble jambs are finished properly.	PENDING_FOR_INSPECTOR (2 attempts)	<p>CHECKER Jayant Yadav Status: Completed 26-08-2025 07:19</p>

QUESTION	STATUS	ATTEMPT DETAILS
		<p>Attempt 2</p> <p>CHECKER Status: Pending_Checker</p>

Checklist: Skirting Checklists

QUESTION	STATUS	ATTEMPT DETAILS
skirting is fixed properly in line without any offsets	PENDING_FOR_INSPECTOR (2 attempts)	<p>CHECKER Jayant Yadav Status: Completed 26-08-2025 07:19</p> <p>Attempt 2</p> <p>CHECKER Status: Pending_Checker</p>

Checklist: Modular Kitchen Checklists

QUESTION	STATUS	ATTEMPT DETAILS
All cabinets working smoothly, hinges of approved make are provided.	PENDING_FOR_INSPECTOR (3 attempts)	<p>CHECKER Jayant Yadav Status: Rejected_By_Checker 26-08-2025 07:19</p>
		<p>Attempt 2</p> <p>MAKER Devendra Verma 26-08-2025 07:36</p>
		<p>CHECKER Jayant Yadav Status: Pending_Supervisor</p>
		<p>Attempt 3</p> <p>CHECKER Status: Pending_Checker</p>
Gas pump/ Spring hinges provided	PENDING_FOR_INSPECTOR (3 attempts)	<p>CHECKER Jayant Yadav Status: Rejected_By_Checker 26-08-2025 07:19</p>

QUESTION	STATUS	ATTEMPT DETAILS
		<p>Attempt 2</p> <div style="display: flex; justify-content: space-between;"> <div style="flex: 1;"> <p>MAKER Devendra Verma 26-08-2025 07:36</p> </div> <div style="flex: 1;"> <p>CHECKER Jayant Yadav Status: Pending_Supervisor</p> </div> </div>
		<p>Attempt 3</p> <div style="display: flex; justify-content: space-between;"> <div style="flex: 1;"></div> <div style="flex: 1;"> <p>CHECKER Status: Pending_Checker</p> </div> </div>

<p>All cabinet shutters are intact, coating is not damaged</p>	<div style="background-color: #e0f2ff; border-radius: 10px; padding: 5px; display: inline-block;"> PENDING_FOR_INSPECTOR </div> <small>(2 attempts)</small>	<div style="display: flex; justify-content: space-between;"> <div style="flex: 1;"> <p>CHECKER Jayant Yadav Status: Completed 26-08-2025 07:19</p> </div> </div>
---	---	--

	<p>Attempt 2</p> <div style="display: flex; justify-content: space-between;"> <div style="flex: 1;"></div> <div style="flex: 1;"> <p>CHECKER Status: Pending_Checker</p> </div> </div>
--	--

<p>Proper alignment is observed in the top and bottom unit shutters</p>	<div style="display: flex; justify-content: space-between;"> <div style="flex: 1;"> <div style="background-color: #e0f2ff; border-radius: 10px; padding: 5px; display: inline-block;"> PENDING_FOR_INSPECTOR </div> <small>(3 attempts)</small> </div> <div style="flex: 1;"> <p>CHECKER Jayant Yadav Status: Rejected_By_Checker 26-08-2025 07:19</p> </div> </div>
--	---

QUESTION	STATUS	ATTEMPT DETAILS
		<p>Attempt 2</p> <p>MAKER Devendra Verma 26-08-2025 07:36</p> <p>CHECKER Jayant Yadav Status: Pending_Supervisor</p>
		<p>Attempt 3</p> <p>CHECKER Status: Pending_Checker</p>

The cabinet's internal screw caps were found okay	PENDING_FOR_INSPECTOR (2 attempts)	<p>CHECKER Jayant Yadav Status: Completed 26-08-2025 07:19</p>
		<p>Attempt 2</p> <p>CHECKER Status: Pending_Checker</p>

No rust is found on the bottom unit shutter hinges	PENDING_FOR_INSPECTOR (3 attempts)	<p>CHECKER Jayant Yadav Status: Rejected_By_Checker 26-08-2025 07:19</p>
--	--	--

QUESTION	STATUS	ATTEMPT DETAILS
		<p>Attempt 2</p> <p>MAKER Devendra Verma 26-08-2025 07:36</p> <p>CHECKER Jayant Yadav Status: Pending_Supervisor</p>
		<p>Attempt 3</p> <p>CHECKER Status: Pending_Checker</p>

Top storages are provided with pivot hinges/ kechi hinges	PENDING_FOR_INSPECTOR (2 attempts)	CHECKER Jayant Yadav Status: Completed 26-08-2025 07:19
		<p>Attempt 2</p> <p>CHECKER Status: Pending_Checker</p>

All horizontal partitions are reprovided with load capacity stickers	PENDING_FOR_INSPECTOR (3 attempts)	CHECKER Jayant Yadav Status: Rejected_By_Checker 26-08-2025 07:19
---	--	--

QUESTION	STATUS	ATTEMPT DETAILS
The drawer for the cutlery tray closes smoothly and properly	PENDING_FOR_INSPECTOR (3 attempts)	<p>Attempt 2</p> <p>MAKER Devendra Verma 26-08-2025 07:36</p> <p>CHECKER Jayant Yadav Status: Pending_Supervisor</p>
		<p>Attempt 3</p> <p>CHECKER Status: Pending_Checker</p>
		<p>PENDING FOR INSPECTOR</p> <p>CHECKER Jayant Yadav Status: Rejected_By_Checker 26-08-2025 07:19</p>
		<p>Attempt 2</p> <p>MAKER Devendra Verma 26-08-2025 07:36</p> <p>CHECKER Jayant Yadav Status: Pending_Supervisor</p>
		<p>Attempt 3</p> <p>CHECKER Status: Pending_Checker</p>

QUESTION	STATUS	ATTEMPT DETAILS
<p>Marble Countertop is Polished and Crack-Free & Joint Between Marble Countertop and Dado Wall is properly Sealed with Silicone.</p>	<p>PENDING_FOR_INSPECTOR</p> <p>(2 attempts)</p>	<p>CHECKER</p> <p>Jayant Yadav</p> <p>Status: Completed 26-08-2025 07:19</p>
		<p>Attempt 2</p> <p>CHECKER</p> <p>Status: Pending_Checker</p>

Checklist: AL Window Checklists

QUESTION	STATUS	ATTEMPT DETAILS
The shutter lock is functioning properly	PENDING_FOR_INSPECTOR (3 attempts)	<p>CHECKER Jayant Yadav Status: Rejected_By_Checker 26-08-2025 07:22</p>
		<p>Attempt 2</p> <p>MAKER Devendra Verma 26-08-2025 07:36</p>
		<p>CHECKER Jayant Yadav Status: Pending_Supervisor</p>
		<p>Attempt 3</p> <p>CHECKER Status: Pending_Checker</p>
No damage or peeling of the coating was observed on the window.	PENDING_FOR_INSPECTOR (2 attempts)	<p>CHECKER Jayant Yadav Status: Completed 26-08-2025 07:22</p>
		<p>Attempt 2</p> <p>CHECKER Status: Pending_Checker</p>

QUESTION	STATUS	ATTEMPT DETAILS
Silicone sealant has been properly filled around the window periphery	PENDING_FOR_INSPECTOR (2 attempts)	CHECKER Jayant Yadav Status: Completed 26-08-2025 07:22
		Attempt 2
		CHECKER Status: Pending_Checker
The roller was functioning properly during the operation of the sliding shutter.	PENDING_FOR_INSPECTOR (3 attempts)	CHECKER Jayant Yadav Status: Rejected_By_Checker 26-08-2025 07:22
		Attempt 2
		MAKER Devendra Verma 26-08-2025 07:36
		CHECKER Jayant Yadav Status: Pending_Supervisor
		Attempt 3
		CHECKER Status: Pending_Checker

Checklist: Electrical Checklists

QUESTION	STATUS	ATTEMPT DETAILS
Switches and Sockets Properly fixed and functional	PENDING_FOR_INSPECTOR (2 attempts)	CHECKER Jayant Yadav Status: Completed 26-08-2025 07:22
		Attempt 2 CHECKER Status: Pending_Checker

Checklist: Plumbing Checklists

QUESTION	STATUS	ATTEMPT DETAILS
WC , Washbasin, and Shower Fixtures Installed and Leak-Free.	PENDING_FOR_INSPECTOR (2 attempts)	<p>CHECKER Jayant Yadav Status: Completed 26-08-2025 07:22</p>
		Attempt 2
		<p>CHECKER Status: Pending_Checker</p>
All Accessories like Towel Rod, Brush Holder, Partition Glass, Mirror are fixed properly.	PENDING_FOR_INSPECTOR (3 attempts)	<p>CHECKER Jayant Yadav Status: Rejected_By_Checker 26-08-2025 07:22</p>
		Attempt 2
		<p>MAKER Devendra Verma 26-08-2025 07:37</p>
		<p>CHECKER Jayant Yadav Status: Pending_Supervisor</p>
		Attempt 3
		<p>CHECKER Status: Pending_Checker</p>

QUESTION	STATUS	ATTEMPT DETAILS
Darin pipes fixing, saddling is done properly and connections are leakfree	PENDING_FOR_INSPECTOR (3 attempts)	CHECKER Jayant Yadav Status: Rejected_By_Checker 26-08-2025 07:22
Attempt 2		
MAKER Devendra Verma 26-08-2025 07:37		
CHECKER Jayant Yadav Status: Pending_Supervisor		
Attempt 3		
CHECKER Status: Pending_Checker		

Checklist: Polish Checklists

QUESTION	STATUS	ATTEMPT DETAILS
Door frame polishing is carried out upto the mark	PENDING_FOR_INSPECTOR (3 attempts)	<p>CHECKER Jayant Yadav Status: Rejected_By_Checker 26-08-2025 07:23</p>
		Attempt 2
		<p>MAKER Devendra Verma 26-08-2025 07:37</p>
		<p>CHECKER Jayant Yadav Status: Pending_Supervisor</p>
		Attempt 3
		<p>CHECKER Status: Pending_Checker</p>
The polish on the top surface of the shutter is Uniformly applied.	PENDING_FOR_INSPECTOR (3 attempts)	<p>CHECKER Jayant Yadav Status: Rejected_By_Checker 26-08-2025 07:23</p>

QUESTION	STATUS	ATTEMPT DETAILS
		<p>Attempt 2</p> <p>MAKER Devendra Verma 26-08-2025 07:37</p> <p>CHECKER Jayant Yadav Status: Pending_Supervisor</p>
		<p>Attempt 3</p> <p>CHECKER Status: Pending_Checker</p>

Checklist: Carpentry Checklists

QUESTION	STATUS	ATTEMPT DETAILS
All hardwares fixed properly as per the approved drawing and dimensions	PENDING_FOR_INSPECTOR (3 attempts)	<p>CHECKER Jayant Yadav Status: Rejected_By_Checker 26-08-2025 07:24</p>
		<p>Attempt 2</p> <p>MAKER Devendra Verma 26-08-2025 07:38</p>
		<p>CHECKER Jayant Yadav Status: Pending_Supervisor</p>
		<p>Attempt 3</p> <p>CHECKER Status: Pending_Checker</p>
Lock slot is cut properly, lock plate, Architrave is fixed properly	PENDING_FOR_INSPECTOR (2 attempts)	<p>CHECKER Jayant Yadav Status: Completed 26-08-2025 07:24</p>
		<p>Attempt 2</p> <p>CHECKER Status: Pending_Checker</p>

QUESTION	STATUS	ATTEMPT DETAILS
Hinges screws are fixed properly, screw heads flushed with plates	PENDING_FOR_INSPECTOR (2 attempts)	<p>CHECKER Jayant Yadav Status: Completed 26-08-2025 07:24</p>
Attempt 2		
Is the 3mm gap is maintained at door frame bottom and sealant is applied	PENDING_FOR_INSPECTOR (2 attempts)	<p>CHECKER Jayant Yadav Status: Completed 26-08-2025 07:24</p>
Attempt 2		
Proper and equal gap is maintained between door shutter and flooring.	PENDING_FOR_INSPECTOR (2 attempts)	<p>CHECKER Jayant Yadav Status: Completed 26-08-2025 07:24</p>

QUESTION	STATUS	ATTEMPT DETAILS
		<p>Attempt 2</p> <p>CHECKER Status: Pending_Checker</p>
Is any undulations observed in Door shutter Laminate	PENDING_FOR_INSPECTOR (2 attempts)	<p>CHECKER Jayant Yadav Status: Completed 26-08-2025 07:24</p>
		<p>Attempt 2</p> <p>CHECKER Status: Pending_Checker</p>
Is the lock and other hardwares fixed properly and working smoothly.	PENDING_FOR_INSPECTOR (2 attempts)	<p>CHECKER Jayant Yadav Status: Completed 26-08-2025 07:24</p>
		<p>Attempt 2</p> <p>CHECKER Status: Pending_Checker</p>

Checklist: Flooring Checklists

QUESTION	STATUS	ATTEMPT DETAILS
Floor tiles no crack, chipped off observed	PENDING_FOR_INSPECTOR (2 attempts)	<p>CHECKER Jayant Yadav Status: Completed 26-08-2025 07:25</p>
		Attempt 2
		<p>CHECKER Status: Pending_Checker</p>
Floor ling observed without any leapages/ offsets	PENDING_FOR_INSPECTOR (2 attempts)	<p>CHECKER Jayant Yadav Status: Completed 26-08-2025 07:25</p>
		Attempt 2
		<p>CHECKER Status: Pending_Checker</p>
Skirting is fixed properly in line without any offsets	PENDING_FOR_INSPECTOR (3 attempts)	<p>CHECKER Jayant Yadav Status: Rejected_By_Checker 26-08-2025 07:25</p>

QUESTION	STATUS	ATTEMPT DETAILS
		<p>Attempt 2</p> <p>MAKER Devendra Verma 26-08-2025 07:38</p> <p>CHECKER Jayant Yadav Status: Pending_Supervisor</p>
		<p>Attempt 3</p> <p>CHECKER Status: Pending_Checker</p>

Checklist: AL Window Checklists

QUESTION	STATUS	ATTEMPT DETAILS
Aluminium window is working smoothly	PENDING_FOR_INSPECTOR (2 attempts)	CHECKER Jayant Yadav Status: Completed 26-08-2025 07:25
		Attempt 2
		CHECKER Status: Pending_Checker
Anchor fasteners are provided as per drawing	PENDING_FOR_INSPECTOR (2 attempts)	CHECKER Jayant Yadav Status: Completed 26-08-2025 07:25
		Attempt 2
		CHECKER Status: Pending_Checker

QUESTION	STATUS	ATTEMPT DETAILS
The shutter lock is functioning properly	PENDING_FOR_INSPECTOR (2 attempts)	CHECKER Jayant Yadav Status: Completed 26-08-2025 07:25

QUESTION	STATUS	ATTEMPT DETAILS
		<p>Attempt 2</p> <p>CHECKER Status: Pending_Checker</p>
No damage or peeling of the coating was observed on the window.	PENDING_FOR_INSPECTOR (2 attempts)	<p>CHECKER Jayant Yadav Status: Completed 26-08-2025 07:25</p>
		<p>Attempt 2</p> <p>CHECKER Status: Pending_Checker</p>
The roller is functioning properly during the operation of the sliding shutter.	PENDING_FOR_INSPECTOR (2 attempts)	<p>CHECKER Jayant Yadav Status: Completed 26-08-2025 07:25</p>
		<p>Attempt 2</p> <p>CHECKER Status: Pending_Checker</p>

QUESTION	STATUS	ATTEMPT DETAILS
Silicone sealant has been properly filled around the window periphery	PENDING_FOR_INSPECTOR (2 attempts)	CHECKER Jayant Yadav Status: Completed 26-08-2025 07:25
		Attempt 2
		CHECKER Status: Pending_Checker
Gasket is fixed properly, drain caps are provided	PENDING_FOR_INSPECTOR (2 attempts)	CHECKER Jayant Yadav Status: Completed 26-08-2025 07:25
		Attempt 2
		CHECKER Status: Pending_Checker
No cracks/scratches are observed on the window glass	PENDING_FOR_INSPECTOR (2 attempts)	CHECKER Jayant Yadav Status: Completed 26-08-2025 07:25

QUESTION	STATUS	ATTEMPT DETAILS
		<p>Attempt 2</p> <p>CHECKER</p> <p>Status: Pending_Checker</p>

Checklist: Painting Checklists

QUESTION	STATUS	ATTEMPT DETAILS
Internal painting is done up to the mark, No undulations/ patch work is balance	PENDING_FOR_INSPECTOR (2 attempts)	<p>CHECKER Jayant Yadav Status: Completed 26-08-2025 07:26</p>
		Attempt 2
		<p>CHECKER Status: Pending_Checker</p>
Ensure the shade variation is not observed in painted walls	PENDING_FOR_INSPECTOR (3 attempts)	<p>CHECKER Jayant Yadav Status: Rejected_By_Checker 26-08-2025 07:26</p>
		Attempt 2
		<p>MAKER Devendra Verma 26-08-2025 07:38</p>
		<p>CHECKER Jayant Yadav Status: Pending_Supervisor</p>
		Attempt 3
		<p>CHECKER Status: Pending_Checker</p>

QUESTION	STATUS	ATTEMPT DETAILS
No Cracks observed in walls	PENDING_FOR_INSPECTOR (3 attempts)	CHECKER Jayant Yadav Status: Rejected_By_Checker 26-08-2025 07:26
		Attempt 2 MAKER Devendra Verma 26-08-2025 07:38
		CHECKER Jayant Yadav Status: Pending_Supervisor
		Attempt 3 CHECKER Status: Pending_Checker

Checklist: False ceiling Checklists

QUESTION	STATUS	ATTEMPT DETAILS
No Cracks observed in false ceiling	PENDING_FOR_INSPECTOR (2 attempts)	<p>CHECKER Jayant Yadav Status: Completed 26-08-2025 07:27</p>
		Attempt 2
		<p>CHECKER Status: Pending_Checker</p>
Cove area facia edges are in line and level and thickness maintained	PENDING_FOR_INSPECTOR (2 attempts)	<p>CHECKER Jayant Yadav Status: Completed 26-08-2025 07:27</p>
		Attempt 2
		<p>CHECKER Status: Pending_Checker</p>
Finishing around the lights and sprinkler is done properly	PENDING_FOR_INSPECTOR (2 attempts)	<p>CHECKER Jayant Yadav Status: Completed 26-08-2025 07:27</p>

QUESTION	STATUS	ATTEMPT DETAILS
		<p>Attempt 2</p> <p>CHECKER Status: Pending_Checker</p>

Checklist: Electrical Checklists

QUESTION	STATUS	ATTEMPT DETAILS
All switches ,switch plates fixed properly in line and level.	PENDING_FOR_INSPECTOR (2 attempts)	<p>CHECKER Jayant Yadav Status: Completed 26-08-2025 07:27</p>
		<p>Attempt 2</p> <p>CHECKER Status: Pending_Checker</p>

All lights are working properly	PENDING_FOR_INSPECTOR (2 attempts)	<p>CHECKER Jayant Yadav Status: Completed 26-08-2025 07:27</p>
		<p>Attempt 2</p> <p>CHECKER Status: Pending_Checker</p>

Checklist: Flooring Checklists

QUESTION	STATUS	ATTEMPT DETAILS
Is the Slope of Toilet flooring ok	PENDING_FOR_INSPECTOR (2 attempts)	<p>CHECKER Jayant Yadav Status: Completed 26-08-2025 07:22</p>
		Attempt 2
		<p>CHECKER Status: Pending_Checker</p>
No offsets are observed Flooring, tile joints filling is done properly	PENDING_FOR_INSPECTOR (3 attempts)	<p>CHECKER Jayant Yadav Status: Rejected_By_Checker 26-08-2025 07:22</p>
		Attempt 2
		<p>MAKER Devendra Verma 26-08-2025 07:37</p>
		<p>CHECKER Jayant Yadav Status: Pending_Supervisor</p>
		Attempt 3
		<p>CHECKER Status: Pending_Checker</p>

QUESTION	STATUS	ATTEMPT DETAILS
Is the tile cutting is done properly Around nahani trap	PENDING_FOR_INSPECTOR (2 attempts)	CHECKER Jayant Yadav Status: Completed 26-08-2025 07:22
		Attempt 2
		CHECKER Status: Pending_Checker
Saddling bracket supports are ok for WC trap of above floor	PENDING_FOR_INSPECTOR (3 attempts)	CHECKER Jayant Yadav Status: Rejected_By_Checker 26-08-2025 07:22
		Attempt 2
		MAKER Devendra Verma 26-08-2025 07:37
		CHECKER Jayant Yadav Status: Pending_Supervisor
		Attempt 3
		CHECKER Status: Pending_Checker

QUESTION	STATUS	ATTEMPT DETAILS
The toilet flooring threshold angle has been properly fixed	PENDING_FOR_INSPECTOR (2 attempts)	CHECKER Jayant Yadav Status: Completed 26-08-2025 07:22
		Attempt 2
		CHECKER Status: Pending_Checker
Floor tile is not damaged/ Chipped off,	PENDING_FOR_INSPECTOR (3 attempts)	CHECKER Jayant Yadav Status: Rejected_By_Checker 26-08-2025 07:22
		Attempt 2
		MAKER Devendra Verma 26-08-2025 07:37
		CHECKER Jayant Yadav Status: Pending_Supervisor
		Attempt 3
		CHECKER Status: Pending_Checker

Checklist: Flooring Checklists

QUESTION	STATUS	ATTEMPT DETAILS
Is the Slope of Toilet flooring ok	PENDING_FOR_INSPECTOR (2 attempts)	<p>CHECKER Jayant Yadav Status: Completed 26-08-2025 07:28</p>
		Attempt 2
		<p>CHECKER Status: Pending_Checker</p>
No offsets are observed Flooring, tile joints filling is done properly	PENDING_FOR_INSPECTOR (2 attempts)	<p>CHECKER Jayant Yadav Status: Completed 26-08-2025 07:28</p>
		Attempt 2
		<p>CHECKER Status: Pending_Checker</p>
Is the tile cutting is done properly Around nahani trap	PENDING_FOR_INSPECTOR (2 attempts)	<p>CHECKER Jayant Yadav Status: Completed 26-08-2025 07:28</p>

QUESTION	STATUS	ATTEMPT DETAILS
		<p>Attempt 2</p> <p>CHECKER Status: Pending_Checker</p>
Saddling bracket supports are ok for WC trap of above floor	PENDING_FOR_INSPECTOR (2 attempts)	<p>CHECKER Jayant Yadav Status: Completed 26-08-2025 07:28</p>
		<p>Attempt 2</p> <p>CHECKER Status: Pending_Checker</p>
The toilet flooring threshold angle has been properly fixed	PENDING_FOR_INSPECTOR (2 attempts)	<p>CHECKER Jayant Yadav Status: Completed 26-08-2025 07:28</p>
		<p>Attempt 2</p> <p>CHECKER Status: Pending_Checker</p>

QUESTION	STATUS	ATTEMPT DETAILS
Floor tile is not damaged/ Chipped off,	PENDING_FOR_INSPECTOR (2 attempts)	CHECKER Jayant Yadav Status: Completed 26-08-2025 07:28
		Attempt 2 CHECKER Status: Pending_Checker

Checklist: Dado Checklists

QUESTION	STATUS	ATTEMPT DETAILS
No hollow sound / debonding of tiles is observed	PENDING_FOR_INSPECTOR (2 attempts)	<p>CHECKER Jayant Yadav Status: Completed 26-08-2025 07:23</p>
		Attempt 2
		<p>CHECKER Status: Pending_Checker</p>
No cracks observed in Dado tile	PENDING_FOR_INSPECTOR (3 attempts)	<p>CHECKER Jayant Yadav Status: Rejected_By_Checker 26-08-2025 07:23</p>
		Attempt 2
		<p>MAKER Devendra Verma 26-08-2025 07:37</p>
		<p>CHECKER Jayant Yadav Status: Pending_Supervisor</p>
		Attempt 3
		<p>CHECKER Status: Pending_Checker</p>

QUESTION	STATUS	ATTEMPT DETAILS
All bird mouth joints are finished properly with emery.	PENDING_FOR_INSPECTOR (3 attempts)	<p>CHECKER Jayant Yadav Status: Rejected_By_Checker 26-08-2025 07:23</p>
		<p>Attempt 2</p> <p>MAKER Devendra Verma 26-08-2025 07:37</p> <p>CHECKER Jayant Yadav Status: Pending_Supervisor</p>
		<p>Attempt 3</p> <p>CHECKER Status: Pending_Checker</p>
No dado tiles are chipped off, edges not magaed	PENDING_FOR_INSPECTOR (2 attempts)	<p>CHECKER Jayant Yadav Status: Completed 26-08-2025 07:23</p>
		<p>Attempt 2</p> <p>CHECKER Status: Pending_Checker</p>

QUESTION	STATUS	ATTEMPT DETAILS
No cracks observed in Ledge wall top marble	PENDING_FOR_INSPECTOR (3 attempts)	CHECKER Jayant Yadav Status: Rejected_By_Checker 26-08-2025 07:23
Attempt 2		
MAKER Devendra Verma 26-08-2025 07:37		
CHECKER Jayant Yadav Status: Pending_Supervisor		
Attempt 3		
CHECKER Status: Pending_Checker		
In Windows & Door Jamb No hollow sound detected; Tiles are properly bonded.	PENDING_FOR_INSPECTOR (3 attempts)	CHECKER Jayant Yadav Status: Rejected_By_Checker 26-08-2025 07:23

QUESTION	STATUS	ATTEMPT DETAILS
		<p>Attempt 2</p> <p>MAKER Devendra Verma 26-08-2025 07:37</p> <p>CHECKER Jayant Yadav Status: Pending_Supervisor</p>
		<p>Attempt 3</p> <p>CHECKER Status: Pending_Checker</p>

Checklist: Dado Checklists

QUESTION	STATUS	ATTEMPT DETAILS
No hollow sound / debonding of tiles is observed	PENDING_FOR_INSPECTOR (2 attempts)	<p>CHECKER Jayant Yadav Status: Completed 26-08-2025 07:28</p>
		Attempt 2
		<p>CHECKER Status: Pending_Checker</p>
No cracks observed in Dado tile	PENDING_FOR_INSPECTOR (2 attempts)	<p>CHECKER Jayant Yadav Status: Completed 26-08-2025 07:28</p>
		Attempt 2
		<p>CHECKER Status: Pending_Checker</p>
All bird mouth joints are finished properly with emery.	PENDING_FOR_INSPECTOR (3 attempts)	<p>CHECKER Jayant Yadav Status: Rejected_By_Checker 26-08-2025 07:28</p>

QUESTION	STATUS	ATTEMPT DETAILS
		<p>Attempt 2</p> <p>MAKER Devendra Verma 26-08-2025 07:38</p> <p>CHECKER Jayant Yadav Status: Pending_Supervisor</p>
		<p>Attempt 3</p> <p>CHECKER Status: Pending_Checker</p>

No dado tiles are chipped off, edges not magaed	PENDING_FOR_INSPECTOR (2 attempts)	<p>CHECKER Jayant Yadav Status: Completed 26-08-2025 07:28</p>
		<p>Attempt 2</p> <p>CHECKER Status: Pending_Checker</p>

No cracks observed in Ledge wall top marble	PENDING_FOR_INSPECTOR (2 attempts)	<p>CHECKER Jayant Yadav Status: Completed 26-08-2025 07:28</p>
---	--	--

QUESTION	STATUS	ATTEMPT DETAILS
		<p>Attempt 2</p> <p>CHECKER Status: Pending_Checker</p>
In Windows & Door Jamb No hollow sound detected; Tiles are properly bonded.	PENDING_FOR_INSPECTOR (2 attempts)	<p>CHECKER Jayant Yadav Status: Completed 26-08-2025 07:28</p>
		<p>Attempt 2</p> <p>CHECKER Status: Pending_Checker</p>

Checklist: Polish Checklists

QUESTION	STATUS	ATTEMPT DETAILS
Door frame polishing is carried out upto the mark	PENDING_FOR_INSPECTOR (2 attempts)	CHECKER Jayant Yadav Status: Completed 26-08-2025 07:23
		Attempt 2
		CHECKER Status: Pending_Checker
The polish on the top surface of the shutter is Uniformly applied.	PENDING_FOR_INSPECTOR (3 attempts)	CHECKER Jayant Yadav Status: Rejected_By_Checker 26-08-2025 07:23
		Attempt 2
		MAKER Devendra Verma 26-08-2025 07:37
		CHECKER Jayant Yadav Status: Pending_Supervisor
		Attempt 3
		CHECKER Status: Pending_Checker

Checklist: Polish Checklists

QUESTION	STATUS	ATTEMPT DETAILS
Door frame polishing is carried out upto the mark	PENDING_FOR_INSPECTOR (2 attempts)	CHECKER Jayant Yadav Status: Completed 26-08-2025 07:28
		Attempt 2
		CHECKER Status: Pending_Checker
The polish on the top surface of the shutter is Uniformly applied.	PENDING_FOR_INSPECTOR (2 attempts)	CHECKER Jayant Yadav Status: Completed 26-08-2025 07:28
		Attempt 2
		CHECKER Status: Pending_Checker

Checklist: Carpentry Checklists

QUESTION	STATUS	ATTEMPT DETAILS
All hardwares fixed properly as per the approved drawing and dimensions	PENDING_FOR_INSPECTOR (3 attempts)	CHECKER Jayant Yadav Status: Rejected_By_Checker 26-08-2025 07:24
		Attempt 2
		MAKER Devendra Verma 26-08-2025 07:37
		CHECKER Jayant Yadav Status: Pending_Supervisor
		Attempt 3
		CHECKER Status: Pending_Checker
Lock slot is cut properly, lock plate, Architrave is fixed properly	PENDING_FOR_INSPECTOR (2 attempts)	CHECKER Jayant Yadav Status: Completed 26-08-2025 07:24
		Attempt 2
		CHECKER Status: Pending_Checker

QUESTION	STATUS	ATTEMPT DETAILS
Hinges screws are fixed properly, screw heads flushed with plates	PENDING_FOR_INSPECTOR (2 attempts)	<p>CHECKER Jayant Yadav Status: Completed 26-08-2025 07:24</p>
Attempt 2		
Is the 3mm gap is maintained at door frame bottom and sealant is applied	PENDING_FOR_INSPECTOR (2 attempts)	<p>CHECKER Jayant Yadav Status: Completed 26-08-2025 07:24</p>
Attempt 2		
Proper and equal gap is maintained between door shutter and flooring.	PENDING_FOR_INSPECTOR (2 attempts)	<p>CHECKER Jayant Yadav Status: Completed 26-08-2025 07:24</p>

QUESTION	STATUS	ATTEMPT DETAILS
		<p>Attempt 2</p> <p>CHECKER Status: Pending_Checker</p>
Is any undulations observed in Door shutter Laminate	PENDING_FOR_INSPECTOR (2 attempts)	<p>CHECKER Jayant Yadav Status: Completed 26-08-2025 07:24</p>
		<p>Attempt 2</p> <p>CHECKER Status: Pending_Checker</p>

Checklist: Carpentry Checklists

QUESTION	STATUS	ATTEMPT DETAILS
All hardwares fixed properly as per the approved drawing and dimensions	PENDING_FOR_INSPECTOR (2 attempts)	CHECKER Jayant Yadav Status: Completed 26-08-2025 07:28
		Attempt 2
		CHECKER Status: Pending_Checker
Lock slot is cut properly, lock plate, Architrave is fixed properly	PENDING_FOR_INSPECTOR (2 attempts)	CHECKER Jayant Yadav Status: Completed 26-08-2025 07:28
		Attempt 2
		CHECKER Status: Pending_Checker
Hinges screws are fixed properly, screw heads flushed with plates	PENDING_FOR_INSPECTOR (3 attempts)	CHECKER Jayant Yadav Status: Rejected_By_Checker 26-08-2025 07:28

QUESTION	STATUS	ATTEMPT DETAILS
		<p>Attempt 2</p> <div style="border-left: 2px solid green; padding-left: 10px;"> MAKER Devendra Verma 26-08-2025 07:38 </div> <div style="border-left: 2px solid blue; padding-left: 10px;"> CHECKER Jayant Yadav Status: Pending_Supervisor </div>
		<p>Attempt 3</p> <div style="border-left: 2px solid blue; padding-left: 10px;"> CHECKER Status: Pending_Checker </div>

Is the 3mm gap is maintained at door frame bottom and sealant is applied	PENDING_FOR_INSPECTOR (2 attempts)	CHECKER Jayant Yadav Status: Completed 26-08-2025 07:28
	PENDING_FOR_INSPECTOR (2 attempts)	CHECKER Status: Pending_Checker

Proper and equal gap is maintained between door shutter and flooring.	PENDING_FOR_INSPECTOR (2 attempts)	CHECKER Jayant Yadav Status: Completed 26-08-2025 07:28
--	--	--

QUESTION	STATUS	ATTEMPT DETAILS
		<p>Attempt 2</p> <p>CHECKER Status: Pending_Checker</p>
Is any undulations observed in Door shutter Laminate	PENDING_FOR_INSPECTOR (2 attempts)	<p>CHECKER Jayant Yadav Status: Completed 26-08-2025 07:28</p>
		<p>Attempt 2</p> <p>CHECKER Status: Pending_Checker</p>

Checklist: False ceiling Checklists

QUESTION	STATUS	ATTEMPT DETAILS
<p>The toilet false ceiling finishing was found to be satisfactory.</p>	<p>PENDING_FOR_INSPECTOR (2 attempts)</p>	<p>CHECKER Jayant Yadav Status: Completed 26-08-2025 07:24</p>
		<p>Attempt 2</p>
		<p>CHECKER Status: Pending_Checker</p>
<p>The trap door size and finish were observed to be satisfactory.</p>	<p>PENDING_FOR_INSPECTOR (3 attempts)</p>	<p>CHECKER Jayant Yadav Status: Rejected_By_Checker 26-08-2025 07:24</p>
		<p>Attempt 2</p>
		<p>MAKER Devendra Verma 26-08-2025 07:37</p>
		<p>CHECKER Jayant Yadav Status: Pending_Supervisor</p>
		<p>Attempt 3</p>
		<p>CHECKER Status: Pending_Checker</p>

Checklist: False ceiling Checklists

QUESTION	STATUS	ATTEMPT DETAILS
<p>The toilet false ceiling finishing was found to be satisfactory.</p>	<p>PENDING_FOR_INSPECTOR (2 attempts)</p>	<p>CHECKER Jayant Yadav Status: Completed 26-08-2025 07:29</p>
		<p>Attempt 2</p>
		<p>CHECKER Status: Pending_Checker</p>
<p>The trap door size and finish were observed to be satisfactory.</p>	<p>PENDING_FOR_INSPECTOR (2 attempts)</p>	<p>CHECKER Jayant Yadav Status: Completed 26-08-2025 07:29</p>
		<p>Attempt 2</p>
		<p>CHECKER Status: Pending_Checker</p>

Checklist: Mirror Checklists

QUESTION	STATUS	ATTEMPT DETAILS
The gypsum on the back side wall behind the mirror was observed to have a proper finish	PENDING_FOR_INSPECTOR (3 attempts)	CHECKER Jayant Yadav Status: Completed 26-08-2025 07:25
		Attempt 2
		CHECKER Jayant Yadav Status: Completed 26-08-2025 07:25
		Attempt 3
		CHECKER Status: Pending_Checker
Is the mirror fixed properly	PENDING_FOR_INSPECTOR (4 attempts)	CHECKER Jayant Yadav Status: Rejected_By_Checker 26-08-2025 07:25
		Attempt 2
		CHECKER Jayant Yadav Status: Created

QUESTION	STATUS	ATTEMPT DETAILS
		<p>Attempt 3</p> <p>CHECKER</p> <p>Jayant Yadav</p> <p>Status: Completed</p> <p>26-08-2025 07:25</p>
		<p>Attempt 4</p> <p>CHECKER</p> <p>Status: Pending_Checker</p>

Checklist: Mirror Checklists

QUESTION	STATUS	ATTEMPT DETAILS
The gypsum on the back side wall behind the mirror was observed to have a proper finish	PENDING_FOR_INSPECTOR (2 attempts)	CHECKER Jayant Yadav Status: Completed 26-08-2025 07:29
		Attempt 2
		CHECKER Status: Pending_Checker
Is the mirror fixed properly	PENDING_FOR_INSPECTOR (2 attempts)	CHECKER Jayant Yadav Status: Completed 26-08-2025 07:29
		Attempt 2
		CHECKER Status: Pending_Checker

Checklist: Glass Partition Checklists

QUESTION	STATUS	ATTEMPT DETAILS
Is the glass partition fixed properly and sealant is applied / gasket is provided in gap near wall tile	PENDING_FOR_INSPECTOR (2 attempts)	CHECKER Jayant Yadav Status: Completed 26-08-2025 07:26
		Attempt 2 CHECKER Status: Pending_Checker

Checklist: Glass Partition Checklists

QUESTION	STATUS	ATTEMPT DETAILS
Is the glass partition fixed properly and sealant is applied / gasket is provided in gap near wall tile	PENDING_FOR_INSPECTOR (2 attempts)	CHECKER Jayant Yadav Status: Completed 26-08-2025 07:29
		Attempt 2 CHECKER Status: Pending_Checker

Checklist: Plumbing Checklists

QUESTION	STATUS	ATTEMPT DETAILS
All CP fitting installed and working properly	PENDING_FOR_INSPECTOR (2 attempts)	<p>CHECKER Jayant Yadav Status: Completed 26-08-2025 07:26</p> <p>Attempt 2</p> <p>CHECKER Status: Pending_Checker</p>
Shower mixer/diverter working properly	PENDING_FOR_INSPECTOR (2 attempts)	<p>CHECKER Jayant Yadav Status: Completed 26-08-2025 07:26</p> <p>Attempt 2</p> <p>CHECKER Status: Pending_Checker</p>
Is the Wash basin bottle trap fixed without any leakage	PENDING_FOR_INSPECTOR (3 attempts)	<p>CHECKER Jayant Yadav Status: Rejected_By_Checker 26-08-2025 07:26</p>

QUESTION	STATUS	ATTEMPT DETAILS
All valves are Working properly without any leakage	PENDING_FOR_INSPECTOR (3 attempts)	<p>Attempt 2</p> <p>MAKER Devendra Verma 26-08-2025 07:37</p> <p>CHECKER Jayant Yadav Status: Pending_Supervisor</p>
		<p>Attempt 3</p> <p>CHECKER Status: Pending_Checker</p>
		<p>PENDING FOR INSPECTOR</p> <p>CHECKER Jayant Yadav Status: Rejected_By_Checker 26-08-2025 07:26</p>
		<p>Attempt 2</p> <p>MAKER Devendra Verma 26-08-2025 07:37</p> <p>CHECKER Jayant Yadav Status: Pending_Supervisor</p>
		<p>Attempt 3</p> <p>CHECKER Status: Pending_Checker</p>

Checklist: Plumbing Checklists

QUESTION	STATUS	ATTEMPT DETAILS
All CP fitting installed and working properly	PENDING_FOR_INSPECTOR (2 attempts)	<p>CHECKER Jayant Yadav Status: Completed 26-08-2025 07:30</p> <p>Attempt 2</p> <p>CHECKER Status: Pending_Checker</p>
Shower mixer/diverter working properly	PENDING_FOR_INSPECTOR (2 attempts)	<p>CHECKER Jayant Yadav Status: Completed 26-08-2025 07:30</p> <p>Attempt 2</p> <p>CHECKER Status: Pending_Checker</p>
Is the Wash basin bottle trap fixed without any leakage	PENDING_FOR_INSPECTOR (2 attempts)	<p>CHECKER Jayant Yadav Status: Completed 26-08-2025 07:30</p>

QUESTION	STATUS	ATTEMPT DETAILS
All valves are Working properly without any leakage	PENDING_FOR_INSPECTOR (2 attempts)	<p>Attempt 2</p> <p>CHECKER Status: Pending_Checker</p>
		<p>PENDING_FOR_INSPECTOR</p> <p>CHECKER Jayant Yadav Status: Completed 26-08-2025 07:30</p>
		<p>Attempt 2</p> <p>CHECKER Status: Pending_Checker</p>

Checklist: Waterproofing Checklists

QUESTION	STATUS	ATTEMPT DETAILS
Any leakages observed in ceiling of toilet	PENDING_FOR_INSPECTOR (2 attempts)	<p>Attempt 2</p> <p>CHECKER Jayant Yadav Status: Completed 26-08-2025 07:26</p>
		<p>Attempt 2</p> <p>CHECKER Status: Pending_Checker</p>

Checklist: Waterproofing Checklists

QUESTION	STATUS	ATTEMPT DETAILS
Any leakages observed in ceiling of toilet	PENDING_FOR_INSPECTOR (2 attempts)	CHECKER Jayant Yadav Status: Completed 26-08-2025 07:29
		Attempt 2 CHECKER Status: Pending_Checker

Checklist: Service Window Checklists

QUESTION	STATUS	ATTEMPT DETAILS
the service duct window closes and locks properly.	PENDING_FOR_INSPECTOR (2 attempts)	CHECKER Jayant Yadav Status: Completed 26-08-2025 07:26
		Attempt 2
		CHECKER Status: Pending_Checker
No Sacrches are observed on froasted glass and windo frame	PENDING_FOR_INSPECTOR (2 attempts)	CHECKER Jayant Yadav Status: Completed 26-08-2025 07:26
		Attempt 2
		CHECKER Status: Pending_Checker
Service window sealant is applied from outside	PENDING_FOR_INSPECTOR (2 attempts)	CHECKER Jayant Yadav Status: Completed 26-08-2025 07:26

QUESTION	STATUS	ATTEMPT DETAILS
		<p>Attempt 2</p> <p>CHECKER</p> <p>Status: Pending_Checker</p>

Checklist: Service Window Checklists

QUESTION	STATUS	ATTEMPT DETAILS
the service duct window closes and locks properly.	PENDING_FOR_INSPECTOR (2 attempts)	CHECKER Jayant Yadav Status: Completed 26-08-2025 07:30
		Attempt 2
		CHECKER Status: Pending_Checker
No Sacrches are observed on froasted glass and windo frame	PENDING_FOR_INSPECTOR (2 attempts)	CHECKER Jayant Yadav Status: Completed 26-08-2025 07:30
		Attempt 2
		CHECKER Status: Pending_Checker
Service window sealant is applied from outside	PENDING_FOR_INSPECTOR (2 attempts)	CHECKER Jayant Yadav Status: Completed 26-08-2025 07:30

QUESTION	STATUS	ATTEMPT DETAILS
		<p>Attempt 2</p> <p>CHECKER Status: Pending_Checker</p>

Checklist: Painting Checklists

QUESTION	STATUS	ATTEMPT DETAILS
All drain pipes and water supply pipes painted as per color codes	PENDING_FOR_INSPECTOR (2 attempts)	<p>CHECKER Jayant Yadav Status: Completed 26-08-2025 07:27</p>
		<p>Attempt 2</p> <p>CHECKER Status: Pending_Checker</p>

Checklist: Painting Checklists

QUESTION	STATUS	ATTEMPT DETAILS
All drain pipes and water supply pipes painted as per color codes	PENDING_FOR_INSPECTOR (2 attempts)	<p>CHECKER Jayant Yadav Status: Completed 26-08-2025 07:29</p>
		<p>Attempt 2</p> <p>CHECKER Status: Pending_Checker</p>

Checklist: DUCT Checklists

QUESTION	STATUS	ATTEMPT DETAILS
All Plumbing brackets PVC caps are provided.	PENDING_FOR_INSPECTOR (2 attempts)	<p>CHECKER Jayant Yadav Status: Completed 26-08-2025 07:27</p>
		<p>Attempt 2</p> <p>CHECKER Status: Pending_Checker</p>

Checklist: DUCT Checklists

QUESTION	STATUS	ATTEMPT DETAILS
All Plumbing brackets PVC caps are provided.	PENDING_FOR_INSPECTOR (2 attempts)	<p>CHECKER Jayant Yadav Status: Completed 26-08-2025 07:30</p>
		<p>Attempt 2</p> <p>CHECKER Status: Pending_Checker</p>