YE SERVICE NEWS


Subject	Change of Material of Pro	No. :YEN-CP-23020-3 Date:2020/05/19	
Engine	6EY18(A)L(W), 6EY22(A)(L)W	Use	All uses
Model		Engine Nos.	All engines

The material of protection ring for 6EY18 and 6EY22 engine model has been changed for improving durability and fitness with cylinder liner as below table . This change will not affect to engine performance.

If you have plan to replace protection ring at maintenance, replacing to new type is recommended...

	6EY18		6EY22	
	Current Type	New Type	Current Type	New Type
Parts Number	146623-01121	146623-01230	150633-01121	150633-01110
Material	SUS304	FC250	SUS304	FC250
Assy. Number of Cylinder Liner	746623-01901-C	146623-01240-C	150633-01140-C	150633-01241-C

Table: Detail for Change of Protection Ring



YANMAR ENGINEERING CO.,LTD Market Service Division Approved Checked Prepared Approved Checked Prepared Approved Checked Prepared Approved Checked Prepared Approved Checked Prepared