

MARINE NOTICE

Marine Notice 12/2016 Supercedes 2/2016

Asbestos on ships

Purpose

The purpose of this marine notice is to draw the attention of ship owners and operators to the ongoing prohibition of asbestos on ships, noting that Australian law requires operators to take all reasonable steps to protect the health and safety of employees and contractors while at work.

Ships to which the *Occupational Health and Safety (Maritime Industry) Act* 1993 applies

The Occupational Health and Safety (Maritime Industry) Act 1993 and the subordinate Occupational Health and Safety (Maritime Industry) (National Standards) Regulations 2003 (Regulation 2.08 and Schedule 2) require operators to ensure that hazardous substances such as asbestos are not used at a workplace under their control.

An exception has been made under the Regulations (2.08 and Schedule 2) for 'in situ' asbestos. This is asbestos that has been fixed or installed in a ship (or any other structure that forms a maritime workplace) or a plant (or any other thing that is used in a maritime workplace) before 31 December 2003 in such a way that it will not constitute a risk unless the asbestos is disturbed.

In situ asbestos on ships must be appropriately identified and managed to ensure that the risks posed by asbestos are assessed, controlled and mitigated as described in Part 2 of the Occupational Health and Safety (Maritime Industry) (National Standards) Regulations 2003. Additional guidance on the management of asbestos is provided in Part 8 of the Guidance on prohibition on the use of asbestos in workplaces in the Seacare jurisdiction and Safe Work Australia's Code of Practice – How to Manage and Control Asbestos in the Workplace.

Despite the above, the best outcome is the complete removal of asbestos and asbestos containing materials from ships. Any work on the removal or disposal of asbestos should be carried out in accordance with the State or Territory legislation. Ship owners and operators should contact the relevant State or Territory Workplace Health and Safety (WHS) regulator to ensure that removal work is carried out as per the applicable legislation and relevant Code of Practice.

Australian ships

From 31 December 2003 the installation of asbestos on Australian ships has been prohibited. The same prohibition has been effective internationally from 1 January 2011, in accordance with SOLAS Chapter II-1 Reg. 3-5.2.

It is recommended that ship owners ensure that any asbestos or asbestos containing materials on Australian ships is identified by a competent person in accordance with:

- AS/NZS ISO/IEC 17020 Conformity assessment - Requirements for the operation of various types of bodies performing inspection; or the
- Code of Practice How to Manage and Control Asbestos in the Workplace.

The presence of documentation confirming that no asbestos is present is considered best practice, as is the inclusion of a certificate or report verifying that the samples have been analysed by a body holding National Association of Testing Authorities, Australia (NATA) accreditation for the relevant test method or other equivalent accreditation to internationally recognised standards to conduct independent asbestos inspections and testing on ships.

NATA has published an Industry User Guide titled *Working with NATA Accredited Asbestos Facilities*, to assist the industry to determine if a body has the accreditation to carry out specific inspections or tests.

Ship survey data indicates that most asbestos detection occurs in the following areas:

- insulation and sealing materials in machinery spaces;
- sealing materials used in construction (e.g. gaskets and doorway/window sealants);
- electric and electronic components (e.g. cables and fuses); and
- insulation materials used in construction (e.g. deck coverings deckheads and bulkheads).

Asbestos containing components may also find their way into a ship during operational maintenance. This highlights the need for vigilance and periodic re-inspection following maintenance and refit works.

Other legislation

For ships entering or intending to enter Australian waters, including foreign registered ships, any import of asbestos or asbestos containing materials is prohibited under the *Customs (Prohibited Imports) Regulations* 1956 (s.4C).

Ship owners and operators should contact the Department of Immigration and Border Protection to ensure that appropriate inspection and certification measures are in place prior to a ship entering Australia.

Further guidance relating to asbestos can be accessed from:

Department of Immigration and Border Protection

Prohibited and restricted imports - Asbestos

https://www.border.gov.au/Busi/Impo/Proh/Asbestos

National Association of Testing Authorities, Australia (NATA)

Industry User Guide 7 – Working with NATA Accredited Asbestos Facilities

http://www.nata.com.au/nata/aboutnata/information-for-industry

Seacare Authority

Guidance on prohibition on the use of asbestos in workplaces in the Seacare jurisdiction

http://www.seacare.gov.au/forms and public ations/published information/our_services/Occupational Health and Safety/occupationa I health and safety/guid on prohib on use of asbestos in work in seacare justis

Safe Work Australia

Code of Practice – How to Manage and Control Asbestos in the Workplace

http://www.safeworkaustralia.gov.au/sites/sw a/about/publications/pages/manage-controlasbestos-cop

Code of Practice – How to Safely Remove Asbestos

http://www.safeworkaustralia.gov.au/sites/sw a/about/publications/pages/safely-removeasbestos-cop

Gary Prosser Deputy Chief Executive Officer June 2016

Australian Maritime Safety Authority GPO Box 2181 CANBERRA ACT 2601 File No. D16/163523