TAI CHONG CHEANG STEAMSHIP CO (SINGAPORE) PTE LTD

Safety Management System

Mooring System Management Plan and Line Management Plan – Section 2

Part B4 - Mooring line running hours record

Issue No: 000 Revised

15-Oct-20

GM (MSD)

Issue Date:

Issued By:

SECTION 2 - PART B

B4 - MOORING LINE RUNNING HOURS RECORD

- a) Use SMS Form MA041B for record of running hours of Mooring Wires, Ropes & Rope Tails.
- b) This record must be updated after each port call.
- c) The record of running hours must be adjusted by a factor of 1.25 when ropes have been used over fittings with D/d ration less than 12. This will automatically ensure that lines are inspected at reduced intervals.

Note: Completed SMS Form MA041B is to be filed here and up to date records are to be maintained.