Material Testing Module –RFI request Process for Contractor using Jal Rekha mobile App.


1. **Login into Jal Rekha app and click on Material Testing Module.**
2. **Sync Material Testing Module – Click on Sync Data.**
3. **Once synced, click on Inspection Request.**
4. **Select Components & material for which Inspection to be scheduled.**
5. **Fill all require detail and upload Photo & mention remarks.**
6. **Click on Submit.**
7. **Once RFI submitted, It will go to GM PIU for further action.**
8. **In case of Network issue, Save RFI and upload later. It will visible in Upload Office Data. When you are back in network, then upload.**
9. **Go to Survey History. All the RFI uploaded will be listed here.**
10. **You can see accepeted and rejected RFI of Material test under Accepted Inspection & Rejected Inspection respectively.**
11. **In case of any material failed during test and RFI rejected by field Engineer, it will be visibled in Rejected Inspection. Check requlary and rectify the work as per observation. You need to raise Reinspection RFI from Rejected Inspection. Once contractor raised request for Re-Inspection it will go to Field Engineer for further test procedures.**


Key Points:

Always sync to raise Inspection or see inspection history.


Double-check details before final submission.


Do not create new RFI id for rejected inspection.





Ist click on Sync data, once synce successful message comes, then click on Inspection Request.







Fill all require detail correctly, take photo, schedule inspection date and then click on Submit. Once request submitted, it will go to GM PIU for further action. They will assign this RFI to engineer for further inspection.

All the raised Inspections, you can see in history tab. You can see accepted and rejected inspection in given tab respectively.

Re-Inspection Process- In case of any material failed in test and RFI rejected by field engineer and GM PIU. Rejected RFI will reflect in Rejected Inspection. Now as per observation given, you need to replace material and once the material reached at the site, then need to raise **Re-Inspection** request against failed RFI id. Do not create new RFI.

Take photo of material, upload document (supporting document related to material), schedule inspection date and submit.





Once the Re-Inspection raised, it will reflect to GM PIU & Field Engineer for further inspection.