## 2020 PC/CP320 Integration Project Checklist (Fall)

## • Basic requirements

A. Sensor 1. 2.	s and Actuators gets input from environment makes changes in environ- ment based on inputs	Alcohol / Ethanol
3.	distance sensor (ultrasonic)	
4.	other input device (i.e. multivalued)	MQ3
5.	one motor (stepper or servo)	
6.	User output (i.e. proportional operation)	
B. Software		
1.	interacts with operator (on	
2.	computer) modular	
	(explicit functions for each device)	
3.	no magic numbers	
4.	self-explanatory variable and function names	
C. Documentation		
1.	circuit overview	
2.	clear block diagram	
	(identifying signal types)	
3.	explanation of each block	
	$(3 \times weight)$	

Note: All interactions with the operator and the environment must be related; environment input should affect output to operator and input from operator should affect output to environment.