

## **Eight Discipline Report (8D Report)**

То:	8D report No.:
From: : Chicony Power Technology	RMA claim No.:
CC:	Chicony Power P/N: A24-150P1A
	Customer P/N:
Submit date: 6/18	Product description: 150W
Receive date: 6/18	Defect D/C or Lot No.:

Subject: 264Vac 切換 90Vac PSU 輸出電壓會掉電

(Regulation, FW 韌體)

D1.) 問題解決成員:Use Team Approach

主持者 (Team Leader):

內部成員 (Internal Team Members):


外部成員 (External Team Member):

**D2**.)問題說明:Problem Description:

(Note: Use who, what, when, where, why, how, how many to specify the Customer's problem.)

在滿載條件下,當輸入電壓由 264Vac 切至 90Vac 時,大電容電壓會掉至 308V,此時

## LLC 輸出電流太大觸發 OCP 保護。



**D3**.)內部或客戶的暫時解決辦法及實施日期:Implement and Verify Containment Action:

(Note: Internal / external containment action effectiveness and date.)

1. 從客戶端取得樣機並做進一步分析

Date:2024/6/15

Form No.SMQA061 2.0 版 保存期限: 5 年



**D4**.)不良原因確認: Define and Verify Root Causes:

(Note: Identify and verify all suspect causes, which needs explain why the problem occurred.)

滿載條件下,當輸入電壓由264Vac切至90Vac時,大電容電壓掉至350V,此時LLC頻率降低進DCM,過程因觸

發CMR開關強制停打且轉態,導致正負半周切換時序異常。



當大電容電壓掉至310V,此時LLC上下臂開關不對稱導致電流大小波,有機會觸發到LLC的OCP保護。



## 改善對策:

1. 將CMR Level由100mV改為60mV避免誤觸發。

Form No.SMQA061 2.0 版 保存期限: 5 年



- 2. AC電壓急遽變動下,調整回授電容容值以及調低IC偵測輸入電壓取樣數以提升PFC響應速度
  - a. 修改C9容值由4.7n改為3.3n
  - b. IC取樣數由8個cycles改為2個cycles

## 改善對策驗證:

滿載條件下,當輸入電壓由264Vac切至90Vac時,大電容電壓掉至319V,此時LLC頻率降低進DCM,無電流大

小波,動作正常。



**D5.)**改善措施:Corrective Action Verification:

(**Note**: Be make sure the corrective actions is effective in process as well as able to fix the customer complaint problem)

- 1. 將CMR Level由100mV改為60mV避免誤觸發。
- 2. AC電壓急遽變動下,調整回授電容容值以及調低 IC偵測輸入電壓取樣數以提升PFC響應速度
  - a. 修改C9容值由4.7n改為3.3n
  - b. IC取樣數由8個cycles改為2個cycles

Date:2024/6/18

**D6.)**改善措施實施日期:Implement Permanent Corrective Actions:

(Note: Be provide the phase-in date or lot# of corrective actions implementation in process)

**Immediately** 

Form No.SMQA061 2.0 版

保存期限:5年



D7.)預防再發生措施:Prevent Recurrence:

(Note: Modified the management, operating systems, practices, and procedures to prevent recurrence for the problems as well as lessons learned cases.)

Same as D5

**D8.)**確認並感謝問題解決成員:Check and Congratulate the Team:

(Note: Recognize the collective efforts of the team.)

Thanks to you all!!!

Signature	Arthur Wu
Team Leader:	
	Name – Title
Signature by Approver:	Mark Meng
	Name-Title