P.T. CORINTHIAN INDUSTRIES INDONESIA

Part of the JELD-WEN* family

8994403

Jl. Mercedes, Desa Cicadas Kec. Gunung Putri, Kab. Bogor - Jawa Barat, Indonesia Tel: 62-21 - 867 0314 (Hunting), Fax: 62-21-867 0992

CREDIT NOTE

: CN/C/CI.109/259/V/17

DATE

: 26 May 2017

ISSUED TO

: SKAN BENELUX BV

ATTN

: DOETIE OLIJNSMA

CREDIT NOTE

PARTICULARS

AMOUNT



BEING CREDIT FOR JAN - MAY 2017 CLAIM

4,872.98

4,872.98

US DOLLARS

: FOUR THOUSAND EIGHT HUNDRED AND SEVENTY TWO AND CENTS NINETY EIGHT ONLY

For and on behalf of Corinthian Ind. Indonesia

N.

26/5/17

Transport No. PO no. Article no. Dirab Rice: Cirrency Quantity Empiricaci description Total value.	73.29	1 Other damages	73.29 USD	4500020341 221783211S	78685	13/04/2017
	61.1	1 Other damages	61.1 USD		78209	10/04/2017
Transport foc. PO no. Article no.	57.08	1 Other damages			78209	10/04/2017
Transport fro. PO no. Article no. Total va Tot	66.95	1 Damage to rebate edge			78209	10/04/2017
Transport inc. PO 10. Article inc. Unithprice: Currency Currency	59.74	1 Other damages		4500020171 LUCC83201S	78209	10/04/2017
Transporting PO 10: Article no. Unitiprice: Currency Cuantity Error code description Total va 500018647 1217932315 75819 4500018647 1217932315 63.3 UsD 1 Other damages 76047 4500018647 345882315 73.56 USD 1 Other damages 76047 4500018647 1217932315 46.17 USD 1 Other damages 76047 4500018699 1227832011 45.17 USD 1 Other damages 76526 4500018990 1237832011 60.3 USD 1 Other damages 76527 4500018970 1217832015 60.3 USD 1 Other damages 76527 4500018913 UCC782015 60.17 USD 1 Other damages 76769 4500018913 UCC782015 83.1 USD 1 Other damages 76770 4500018970 1247982315 83.1 USD 1 Other damages 76789 4500018913 UCC782011 10.3 USD 1 Other damages 77280 450001931 324322101 63.1 USD 1 Other damages 77281 450001931 3243822110 63.1 USD 1 Other damages 1 77282 450001931 345882311 71.3 USD 1 Other damages	73.55	1 Other damages			78209	10/04/2017
Transport no. PO no. Article jos. Unitiprice: Currency Quantity Error code description Total very 10 februs 75819 4500018647 121793231S 43.3 USD 1 Other damages 76474 4500018647 890378201S 73.56 USD 1 Other damages 76647 4500018809 122783201S 73.56 USD 1 Other damages 767647 4500018809 12783201S 46.17 USD 1 Lock hole fitting incorrect 767647 4500018809 12783201S 52.56 USD 1 Lock hole fitting incorrect 66 76527 4500018970 12783201S 54.11 USD 1 Other damages 66 76769 4500019371 UCC78201S 54.11 USD 1 Other damages 66 76769 4500019372 UcC78201S 54.11 USD 1 Other damages 66 76769 4500019372 UcC78201S 87.49 USD 1 Other damages 1 Usb 1 Damage on topdoor by stacked transport 76769 4500019313 UCC78201S 87.49 USD 1 Other damages 1 Usb 1 Usb 1 Other damages 1 Usb 1 Usb 1 Usb 1 Usb 2 Damage to rebate edge	139.3	2 Other damages			78209	10/04/2017
Transport no. PO no. Article no. Unitprice: Currency Quantity Error code description Total vs. 75819 4500018647 1217932315 63.3 USD 1 Other damages 76047 4500018647 3461882315 73.56 USD 1 Other damages 76047 4500018447 127932315 46.17 USD 1 Lock hole fitting incorrect 676226 4500018809 1227832011 52.56 USD 1 Lock hole fitting incorrect 66.3 USD 1 Lock hole fitting incorrect 66.3 USD 1 Lock hole fitting incorrect 66.3 USD 1 Dother damages 66.3 USD 1 Other damages 66.3 USD 1 Dother damages 1 Dother damages <td>72.6</td> <td>1 Other damages</td> <td></td> <td></td> <td>78209</td> <td>10/04/2017</td>	72.6	1 Other damages			78209	10/04/2017
Transport no. PO no. Article no. Unitiprice: Gurrency Quantity Error code description Total value 75819 4500018647 1217932315 63.3 USD 1 Other damages 76047 4500018647 34518832315 73.56 USD 1 Lock hole fitting incorrect 76047 4500018847 8902932315 65.3 USD 1 Lock hole fitting incorrect 76526 4500018897 01217832015 54.11 USD 1 Lock hole fitting incorrect 76527 4500018897 01217832015 54.11 USD 1 Lock hole fitting incorrect 76527 450001897 01217832015 54.11 USD 1 Lock hole fitting incorrect 76728 450001897 0127832015 54.11 USD 1 Lock hole fitting incorrect 76729 450001897 0247932315 58.31 USD 1 Dother damages 76729 450001897 0247932315 57.25 USD 1 Other damages 76729 450001897 0247932315 57.25 USD 1 Other damages 77263 4500019133 TU0393211NEVO 106.37 USD 1 Other damages 1 77268 450001913 SP04382315 72.36 USD 1 Damage to rebate edge 1<	65.97	1 Damage to rebate edge			78472	10/04/2017
Transport no. PO no. Article no. Unitiprice: Currency Countity Quantity Error code description Total vs 75819 4500018647 121793231S 63.3 USD 1 Other damages 1 Other damages 76047 4500018428 802093231S 46.17 USD 1 Other damages 6 76226 4500018428 802093231S 46.17 USD 1 Lock hole fitting incorrect 6 76527 4500018970 123783201S 52.56 USD 1 Other damages 6 76527 4500018970 12378321IS 60.3 USD 1 Other damages 6 76527 4500018970 12378321IS 60.1 USD 1 Other damages 6 76527 4500018970 12378321IS 60.1 USD 1 Lock hole fitting incorrect 6 76760 4500018970 278201I 58.31 USD 1 Damage on topdoor by stacked transport 1 76770 4500018970 278201I 50.25 USD 1 Other damages 77123 4500019313 34618321IO 50.25 USD 1 Other damages 1 77268 4500019313 346183221IO 63.1 USD 1 Other damages 1	126.9	2 Damage to rebate edge			78472	10/04/2017
Transport no. PD. no. Article no. Unitiprice: Currency Quantity Error code description. Total variance 75819 4500018647 1217932315 63.3 USD 1 Other damages 60.3 USD 1 Other damages 1 Other damages 60.3 USD 1 Other damages 1 Other damages 60.3 USD 1 Other damages 1	79.15	1 Damage to rebate edge			78472	10/04/2017
Transport no. PO no. Article no. Unitiprice. Currency Quantity Error code description Total value 75819 4500018647 121793231S 63.3 USD 1 Other damages 6 0.3 USD 1 Other damages 1 0 USD 1 Other damages 6 0.3 USD 1 Other damages 1 0 USD 1 Other damages 1 0 USD 1 Other damages 1 0 USD 1 Other damages 1 Other damages 1 0 USD 1 Other damages 1 0 USD 1 Other damages 1 Other damages 1 Other damages	60.3	1 Other damages			78472	10/04/2017
Transport no. PO no. Article no. Unithrice: Currency Quantity Error code description Total very 75819 75819 4500018647 1217932315 63.3 USD 1 Other damages 76047 4500018647 3461882315 73.56 USD 1 Other damages 76226 4500018893 1227832011 52.56 USD 1 Other damages 76526 45000188970 1217832015 60.3 USD 1 Other damages 76527 4500018970 1237832115 60.3 USD 1 Other damages 76527 4500018970 1237832115 60.1 USD 1 Other damages 76527 4500018970 1237832115 60.1 USD 1 Ucck hole fitting incorrect 76527 4500018970 1237832115 60.1 USD 1 Ucck hole fitting incorrect 76766 4500018473 E66093231MATR 113.55 USD 1 Damage on topdoor by stacked transport 76769 4500018897 P03782011 50.25 USD 1 Other damages 77268 450001913 T00393211 50.25 USD 1 Other damages 77268 450001931 3461832110 71.3 USD 1 Damage to rebate edge 77268 4500019478 W176593231	76.29	1 Damage to rebate edge			78472	10/04/2017
Transport no. PO no. Article no. Unitiprice: Currency Quantity Error code description Total vs 75819 4500018647 1217932315 63.3 USD 1 Other damages 76047 4500018647 3461882315 63.3 USD 1 Other damages 76047 4500018647 3461882315 73.56 USD 1 Other damages 76226 4500018809 127832011 52.56 USD 1 Other damages 76527 4500018809 127832015 60.3 USD 1 Other damages 76527 4500018970 121383211S 60.17 USD 1 Other damages 76527 4500018970 123583211S 60.17 USD 1 Other damages 76752 4500018970 123583211S 58.31 USD 1 Other damages 76754 4500018970 124793231S 58.31 USD 1 Other damages 76759 4500018970 124793231S 87.49 USD 1 Other damages 76769 4500018970 124793231S 87.49 USD 1 Other damages 76769 450001913 TU0393211NEVO 106.37 USD 1 Other damages 77268 450001931 3254832010 50.31 USD 1 Other damages	60.96	1 Other damages			78472	10/04/2017
Transport no. PO no. Article no. Unitiprice: Currency Quantity Quantity Error code description Total value 75819 4500018647 121793231S 63.3 USD 1 Other damages 1 Other damages 76047 4500018647 346188231S 73.56 USD 1 Other damages 6 76024 76226 45000188647 SP03782011 52.56 USD 1 Other damages 6 76024 76527 4500018970 121783201S 54.11 USD 1 Other damages 6 76527 76527 4500018970 121783201S 60.3 USD 1 Other damages 6 76527 76756 4500018970 123583211S 60.17 USD 1 Lock hole fitting incorrect 6 76527 76757 4500018970 123583211S 58.31 USD 1 Other damages 76758 4500018970 224793231S 58.31 USD 1 Damage on topdoor by stacked transport 76769 4500018809 SP0378201I 50.25 USD 1 Other damages 77268 450001931 3254832010 50.25 USD 1 Other damages 77268 450001931 3461832110 10.4 USD 1 Other damages 77268 450001933 3	63.24	1 Damage to rebate edge		4500020010 LUCC832110	78208	7/04/2017
Transport no. PO no. Article no. Unithprice: Ourrency Ouantity Cuantity Error code description 75819 4500018647 121793231S 63.3 USD 1 Other damages 76047 4500018647 346188231S 73.56 USD 1 Other damages 76226 4500018647 SP0378201S 46.17 USD 1 Lock hole fitting incorrect 76527 4500018970 121783201S 52.56 USD 1 Wrong position hinge drillings 76527 4500018970 121783201S 54.11 USD 1 Other damages 76527 4500018970 123583211S 60.31 USD 1 Other damages 76752 4500018970 123583211S 60.17 USD 1 Lock hole fitting incorrect 76754 4500018970 123583211S 60.17 USD 1 Lock hole fitting incorrect 76756 4500018970 224793231S 87.49 USD 1 Damage on topdoor by stacked transport 76769 4500018809 SP03782011 50.25 USD 1 Other damages 77123 450001931 3TU0393211NEVO 106.37 USD 1 Other damages 77268 450001931 346183211O 50.31 USD 1 Other damages to rebate edge 77268	73.58	1 Other damages			77268	1/03/2017
Transport no. PO no. Article no. Unitiprice: Currency Currency Quantity Error code description 75819 4500018647 121793231S 63.3 USD 1 Other damages 76047 4500018647 346188231S 73.56 USD 1 Other damages 76047 4500018847 SP0378201S 46.17 USD 1 Lock hole fitting incorrect 76526 4500018428 BD2093231S 60.3 USD 1 Other damages 76527 4500018970 123583211S 60.3 USD 1 Other damages 76527 4500018970 123583211S 60.17 USD 1 Other damages 76527 4500018970 123583211S 60.17 USD 1 Lock hole fitting incorrect 76752 450001813 LUCC78201S 58.31 USD 1 Other damages 76769 4500018270 224793231S 58.31 USD 1 Damage on topdoor by stacked transport 76769 45000188970 224793231S 87.49 USD 1 Other damages 77123 450001933 TU0393211NEVO 106.37 USD 1 Other damages 77268 450001933 3461832210 106.37 USD 1 Other damages 77268 450001933 346183231S </td <td>57.08</td> <td>1 Other damages</td> <td></td> <td></td> <td>77268</td> <td>1/03/2017</td>	57.08	1 Other damages			77268	1/03/2017
Transport no. PO no. Article no. Unitiprice: Currency Quantity Currency Quantity Error code description 75819 4500018647 121793231S 6.3.3 USD 1 Other damages 76047 4500018647 SP0378201S 46.17 USD 1 Other damages 76226 4500018809 122783201L 52.56 USD 1 Lock hole fitting incorrect 76527 4500018428 BD2093231S 60.3 USD 1 Other damages 76527 4500018970 121783201S 54.11 USD 1 Other damages 76527 4500018970 12383211S 60.17 USD 1 Other damages 76527 4500019133 LUCC78201S 54.11 USD 1 Other damages 76770 4500019133 LUCC78201S 58.31 USD 1 Damage on topdoor by stacked transport 76769 4500018970 224793231S 58.31 USD 1 Other damages 76769 4500018809 SP0378201L 50.25 USD 1 Other damages 77123 450001931 TU039321NEVO 106.37 USD 1 Other damages 77268 450001931 3461832010 63.14 USD 1 Damage to rebate edge 77268 450001931 3461832110 <td< td=""><td>72.36</td><td>1 Other damages</td><td></td><td></td><td>77268</td><td>1/03/2017</td></td<>	72.36	1 Other damages			77268	1/03/2017
Transport no. PO no. Article no. Unitiprice: Currency Quantity Error code description 75819 4500018647 121793231S 63.3 USD 1 Other damages 76047 4500018647 346188231S 73.56 USD 1 Other damages 76047 4500018809 122783201L 46.17 USD 1 Other damages 76526 4500018428 BD2093231S 52.56 USD 1 Wrong position hinge drillings 76527 4500018970 121783201S 54.11 USD 1 Other damages 76527 4500018970 123583211S 60.17 USD 1 Other damages 76756 4500019133 LUCC78201S 54.11 USD 1 Lock hole fitting incorrect 76770 4500018970 224793231S 58.31 USD 1 Damage on topdoor by stacked transport 76769 4500018970 224793231S 87.49 USD 1 Other damages 77123 450001913 TU0393211NEVO 106.37 USD 1 Other damages 77128 450001913 TU0393211NEVO 106.37 USD 1 Other damages 7 100 450001913 TU0393211NEVO 106.31 USD 1 Other damages 7 100 450001913 TU0393211N	142.6	2 Damage to rebate edge			77268	1/03/2017
Transport no. PO no. Article no. Unittprice: Currency Quantity Error code description 75819 4500018647 121793231S 63.3 USD 1 Other damages 76047 4500018647 346188231S 73.56 USD 1 Other damages 76226 4500018809 122783201L 52.56 USD 1 Lock hole fitting incorrect 76526 4500018428 BD2093231S 50.3 USD 1 Wrong position hinge drillings 76527 4500018970 121783201S 54.11 USD 1 Other damages 76527 4500018970 123583211S 60.17 USD 1 Ucck hole fitting incorrect 76527 4500018970 123583211S 60.17 USD 1 Ucck hole fitting incorrect 76766 4500019133 LUCC78201S 58.31 USD 1 Damage on topdoor by stacked transport 76769 4500018970 224793231S 87.49 USD 1 Other damages 76769 4500018809 SP0378201L 50.25 USD 1 Other damages 76769 450001833 TU03993211NEVO 50.25 USD 1 Other damages 767123 4500019133 TU03993211NEVO 50.37 USD 1 Other damages 767124	63.14	1 Damage to rebate edge	63.14 USD		77268	1/03/2017
Transport no. PO no. Article no. Unitiprice: Currency Quantity Error code description 75819 4500018647 121793231S 63.3 USD 1 Other damages 76047 4500018647 346188231S 73.56 USD 1 Other damages 76047 4500018647 SP0378201S 46.17 USD 1 Lock hole fitting incorrect 76226 4500018809 122783201L 52.56 USD 1 Wrong position hinge drillings 76526 4500018970 121783201S 60.3 USD 1 Other damages 76527 4500018970 123583211S 60.1 USD 1 Other damages 76528 4500019133 LUCC78201S 54.11 USD 1 Lock hole fitting incorrect 76750 4500018970 123583211MATR 58.31 USD 1 Damage on topdoor by stacked transport 76769 4500018970 224793231S 58.31 USD 1 Other damages 76769 4500018970 224793231S 87.49 USD 1 Other damages 76769 4500018980 SP0378201L 50.25 USD 1 Other damages 76769 4500018990 SP0378201L 50.25 USD 1 Other damages	106.37	1 Other damages	106.37 USD		77123	28/02/2017
Transport no. PO no. Article no. Unitprice: Currency Quantity Error code description 75819 4500018647 121793231S 63.3 USD 1 Other damages 76047 4500018647 346188231S 73.56 USD 1 Other damages 76047 4500018647 5P0378201L 46.17 USD 1 Lock hole fitting incorrect 76226 4500018809 122783201L 52.56 USD 1 Wrong position hinge drillings 76526 4500018428 BD2093231S 60.3 USD 1 Other damages 76527 4500018970 121783201S 54.11 USD 1 Other damages 76527 4500018970 123583211S 60.17 USD 1 Lock hole fitting incorrect 76766 4500019133 LUCC78201S 58.31 USD 1 Lock hole fitting incorrect 76770 4500016426 EG0693231MATR 113.55 USD 1 Damage on topdoor by stacked transport 76769 4500018970 224793231S 87.49 USD 1 Other damages	50.25	1 Other damages			76769	14/02/2017
Transport no. PO no. Article no. Unitiprice: Currency Quantity Error code description 75819 4500018647 121793231S 63.3 USD 1 Other damages 76047 4500018647 346188231S 73.56 USD 1 Other damages 76047 4500018647 SP0378201S 46.17 USD 1 Lock hole fitting incorrect 76226 4500018899 122783201L 52.56 USD 1 Wrong position hinge drillings 76526 4500018428 BD2093231S 60.3 USD 1 Other damages 76527 4500018970 121783201S 54.11 USD 1 Other damages 76527 4500018970 123583211S 60.17 USD 1 Lock hole fitting incorrect 76766 4500019133 LUCC78201S 58.31 USD 1 Lock hole fitting incorrect 76770 4500016426 EG0693231MATR 113.55 USD 1 Other damages	87.49	1 Other damages			76769	14/02/2017
Transport no. PO no. Article no. Unitprice: Currency Quantity Error code: description 75819 4500018647 121793231S 63.3 USD 1 Other damages 76047 4500018647 346188231S 73.56 USD 1 Other damages 76047 4500018647 SP0378201S 46.17 USD 1 Lock hole fitting incorrect 76226 4500018809 122783201L 52.56 USD 13 Wrong position hinge drillings 76526 4500018428 BD2093231S 60.3 USD 1 Other damages 76527 4500018970 123583211S 54.11 USD 1 Other damages 76527 4500018970 123583211S 60.17 USD 1 Lock hole fitting incorrect 76527 4500018970 123583211S 54.11 USD 1 Lock hole fitting incorrect 76527 450001893 LUCC78201S 58.31 USD 1 Damage on topdoor by stacked transport	113.55	1 Other damages			76770	13/02/2017
Transport no. PO no. Article no. Unitprice: Currency Quantity Error code: description 75819 4500018647 121793231S 63.3 USD 1 Other damages 76047 4500018647 346188231S 73.56 USD 1 Other damages 76047 4500018647 SP0378201S 46.17 USD 1 Lock hole fitting incorrect 76226 4500018809 122783201L 52.56 USD 13 Wrong position hinge drillings 76527 4500018970 121783201S 60.3 USD 1 Other damages 76527 4500018970 123583211S 54.11 USD 1 Other damages 76527 4500018970 123583211S 60.17 USD 1 Lock hole fitting incorrect	58.31	 Damage on topdoor by stacked transport 			76766	14/02/2017
Transport no. PO no. Article no. Unitiprice: Currency Currency Quantity Error code description 75819 4500018647 121793231S 63.3 USD 1 Other damages 76047 4500018647 346188231S 73.56 USD 1 Other damages 76047 4500018647 SP0378201S 46.17 USD 1 Lock hole fitting incorrect 76226 4500018809 122783201L 52.56 USD 13 Wrong position hinge drillings 76526 4500018428 BD2093231S 60.3 USD 1 Other damages 76527 4500018970 121783201S 54.11 USD 1 Other damages	60.17	1 Lock hole fitting incorrect			76527	3/02/2017
Transport no. PO no. Article no. Unitprice: Currency Quantity Error code description 75819 4500018647 121793231S 63.3 USD 1 Other damages 76047 4500018647 346188231S 73.56 USD 1 Other damages 76047 4500018647 SP0378201S 46.17 USD 1 Lock hole fitting incorrect 76226 4500018809 122783201L 52.56 USD 13 Wrong position hinge drillings 76526 4500018428 BD2093231S 60.3 USD 1 Other damages	54.11	1 Other damages			76527	3/02/2017
Transport no. PO no. Article no. Unitprice: Currency Quantity Quantity Error code description 75819 4500018647 121793231S 63.3 USD 1 Other damages 76047 4500018647 346188231S 73.56 USD 1 Other damages 76047 4500018647 SP0378201S 46.17 USD 1 Lock hole fitting incorrect 76226 4500018809 122783201L 52.56 USD 13 Wrong position hinge drillings	60.3	1 Other damages			76526	1/02/2017
Transport no. PO no. Article no. Unitprice: Currency Quantity Quantity Error code description 75819 4500018647 121793231S 63.3 USD 1 Other damages 76047 4500018647 346188231S 73.56 USD 1 Other damages 76047 4500018647 SP0378201S 46.17 USD 1 Lock hole fitting incorrect	683.28				76226	30/01/2017
Transport no. PO no. Article no. Unitorice: Currency Quantity Quantity Error code description 75819 4500018647 121793231S 63.3 USD 1 Other damages 76047 4500018647 346188231S 73.56 USD 1 Other damages	46.17	1 Lock hole fitting incorrect	46.17 USD		76047	19/01/2017
Transport no. PO no. Article no. Unitprice: Currency Quantity Error code description 75819 4500018647 121793231S 63.3 USD 1 Other damages	73.56	1 Other damages	73.56 USD		76047	19/01/2017
PO no. Article no. Unitorice: Currency Quantity Error code description	63.3	1 Other damages			75819	13/01/2017
	Total value:	Error code description	Currency			Date Tran
						*

348.55	5 Damage to rebate edge	69.71 USD	4500021531 SOFI932110	79913	16/05/2017
61.67	1 Other damages	61.67 USD	4500021203 2310882115	79753	8/05/2017
	15 Postition label incorrect		4500021203 2470832115	79475	4/05/2017
68.1	1 Other damages	68.1 USD	4500020994 124483201R	79475	4/05/2017
62.65	1 Forklift fork damage	62.65 USD	4500020994 CARL88231S	79474	3/05/2017
	4 Wrong information on label		4500020859 TR07732110	79226	1/05/2017
. 0	15 Postition label incorrect		4500020694 326183201R	79226	1/05/2017
157.74	2 Other damages	78.87 USD	4500020857 2470882315	79222	25/04/2017
73.4	1 Other damages	73.4 USD	4500020696 WIJ0293231S	79221	25/04/2017
	1 Damage to rebate edge	66.31 USD	4500020342 WLG02932310	78926	14/04/2017
	1 Damage to rebate edge	57.94 USD	4500020012 BD20832110	78473	14/04/2017
133.86	2 Other damages	66.93 USD	4500020011 3461782015	78473	14/04/2017
	3 Damage to rebate edge	95.39 USD	4500020342 TU0383201NEVO	78686	14/04/2017
47.53	1 Other damages	47.53 USD	4500020340 SP0383201S	78686	14/04/2017
	1 Damage to rebate edge	49.8 USD	4500020340 SP01782010	78686	14/04/2017
68.3	1 Other damages	68.3 USD	4500020492 PAOL83201S	78686	14/04/2017
4	 Damage to rebate edge 	49.43 USD	4500020340 SP01732010	78698	14/04/2017
	1 Damage to rebate edge	73.54 USD	4500020173 3463782010	78698	14/04/2017
61.26	1 Other damages	61.26 USD	4500020173 3261932115	78698	14/04/2017
64.31	1 Other damages	64.31 USD	4500020173 325388211S	78698	14/04/2017
72.33	1 Other damages	72.33 USD	4500020340 1247882315	78698	14/04/2017
	1 Damage to rebate edge	68.05 USD	4500020174 WLG01932310	78685	13/04/2017
Total value:	Unitprice: Currency Quantity Error code description	Unitprice: Currency	PO no. Article no.	Transport no. P	Date Tr