## IC Test – GUI Program

- It was designed and tested successfully.
- Imaging/HIFU button: reset the current supply voltage to zero sequentially and set the voltage for the imaging\HIFU mode sequentially.
- Read: read the current voltage and current.
- Save data: Save the scope waveform for different CMUT bias voltage.

