Reliability Report 2025. Page 1: Fleet. At the end of 2025 there were 48,000 active Nimbus stations in 31 countries. Average reporting uptime was 99.2 percent.

Reliability Report 2025. Page 2: Failures. The most common hardware issue was humidity sensor drift, affecting 1.8 percent of stations per year. Anemometer bearing wear affected 0.9 percent.

Reliability Report 2025. Page 3: Actions. Firmware 3.2 improved humidity accuracy near saturation. In 2026 we will ship a field recalibration kit with every Pro station.