



WorkSafety

SMART SAFETY





Work Safety

Welcome Back

Secure access for authorized
inspectors & managers

Email or Username



user@worksafety.gov

Password

[Forgot password?](#)



.....



Keep me signed in

Sign In



SECURE ENVIRONMENT

WorkSafety v2.1 • Official Gov Release



WorkSafety



OFFLINE



New Inspection

Start an AI risk analysis in seconds.

Start Now >

Pending Analysis

3 PENDING



Setor Norte - Fundação



10/01

● Not synced



Linha de Montagem A



09/01

● Not synced



Manutenção Externa



08/01



New Inspection

STEP 1: ENVIRONMENT

Mandatory



Construction

Tap to select



Industry

Tap to select



Other

Tap to select



STEP 2: CATEGORY

Standard

General Safety




Continue >



PRIVACY MODE ON

Identified faces will be automatically blurred (GDPR).



AI: Object Detection (Perseu) Enabled




PRIVACY MODE ON

Identified faces will be automatically blurred (GDPR).



Tap to Review



1

AI: Object Detection (Perseu) Enabled



Review Photos (3)

+ Add



Submit for Analysis 



Syncing...



Visual Analysis (Perseu AI)

Detecting PPE & Risks...



Regulatory Check (Sofia NLP)

Mapping Bau-Wegweiser...

Processando...



Syncing...



Visual Analysis (Perseu AI)

Detecting PPE & Risks...



Regulatory Check (Sofia NLP)

Mapping Bau-Wegweiser...



Risks Detected

Case #12345 • Validation



TOTAL
RISKS

05



COMPLIANCE

82%



Action Checklist

JAN 10, 2026



Missing Guardrail

📍 Platform L2

CRITICAL

Immediate Install



PPE Violation

📍 Zone A

HIGH

Warning Issued



Blocked Exit

📍 Corridor B

MEDIUM

Clear Area



Reject

Confirm





Review

Case

#12345



ANALYSIS RESULT



View Risks



Save Validation