Function Keys

Control Q	Quit program
Control TAB, Control shift TAB	Mode selection operate/coordinates/Program ..etc
Alt+O	mode operate

Control V, Control shift V	Status tab next, previous
Control W	Toggle Work/Machine coordinates
Control F6	toggle MDI

Alt F1	Main menu
Alt F2	Home menu
Alt F3	Zero menu
Alt F4	Auto menu
Alt F7	Machine IO menu
Alt F8	Graphics menu
Alt F9	Jog menu Alt F10 Jog Pad
Alt F11	User 1 menu
Alt F12	User 2 menu
Alt 1,2,3 .. 0, Ctrl+Alt 1,2,3 .. 0	User macro 1 – User Macro 20

Control R	Reset
Control H	Home all
Control 1	Zero x
Control 2	Zero y
Control 3	Zero z
Control 4	Zero a
Control 5	Zero b
Control 6	Zero c

Control + shift + A	Handwheel on A
Control + shift + B	Handwheel on B
Control + shift + C	Handwheel on C
Control + shift + X	Handwheel on X
Control + shift + Y	Handwheel on Y
Control + shift + Z	Handwheel on Z
Control + Alt + N	Handwheel X0.1
Control + N	Handwheel X1
Control + O	Handwheel X10
Control + P	Handwheel X100
Control + shift + N	Jog continue (Handwheel mode off)
Control J, + shift J	Jog mode up, jog mode down

Alt + shift + A	Select JOG A
Alt + shift + B	Select JOG B
Alt + shift + C	Select JOG C
Alt + shift + X	Select JOG X
Alt + shift + Y	Select JOG Y
Alt + shift + Z	Select JOG Z
Control+Alt+Shift+O	Select JOG Speed Low
Control+Alt+Shift+P	Select JOG Speed Med
Control+Alt+Shift+Q	Select JOG Speed High
Control+Alt+Shift+R	Select JOG Step 0.01
Control+Alt+Shift+S	Select JOG Step 0.1
Control+Alt+Shift+T	Select JOG Step 1
Alt+Shift+P	Start Jog+ selected axis
Alt+Shift+N S	tart Jog- selected axis
Alt+Shift+S	Stop Jog
Control I	Load g-code file
Control G, +shift	Run, Pause
Control T	Toggle Single line
Control + B	Toggle Blockdelete
Control F, +shift	+Feed, -Feed
Control S, Control + shift + S	+Speed, -Speed
Control+Alt+S	Speed override 100%

Control+Alt+F	Feed override 100%
Alt+Shift+O	Open Teach
Control+Alt+Shift+A	Add Point
Control+Alt+Shift+E	Edit

Control D, Control + shift D	Spindle On right, Spindle Off
Control E, Control + shift D	Spindle On left, Spindle Off
Control K	Toggle Flood
Control L	Toggle Mist
Control M	Toggle Aux1
Control+Alt+Shift+1	Toggle Aux1 out
Control+Alt+Shift+2	Toggle Aux2 out
Control+Alt+Shift+3	Toggle Aux3 out
Control+Alt+Shift+4	Toggle Aux4 out
Control+Alt+Shift+5	Toggle Aux5 out
Control+Alt+Shift+6	Toggle Aux6 out
Control+Alt+Shift+7	Toggle Aux7 out
Control+Alt+Shift+8	Toggle Aux8 out
Control+Alt+Shift+9	Toggle Aux9 out
Control F1 - control F12	reserved