

## **Service/ Complaint Report**

BBCPL-SER-F-03 (00/01.04.2021)

Engineer Name:	Mr. Suryakant R. Nehatrao	Visit Date/s:	01-Apr-2022
<b>Customer Name:</b>	Rede Scalable Energy Management Pvt. Ltd.	Part No.	IFT-802TS15
Contact Person:	Mr.Basudeb Dhar (913340630276)	Make	Planet
Site Contact Person:		<b>Under Warranty</b>	YES
<b>Site Contact Person:</b>		SO. No.	
Site Address:	Chakpara,Liluah,		
	Howrah - 711204		
	State Code : 19 State : West Bengal		
Serial Nos.	AH101520A00023		

### **Problems Reported/ Service For:**

• IFT-802TS15 device not power on .

#### Findings/ Observation of BluBoxx Engineer:

IFT-802TS15 device not power on

#### Actions taken by BluBoxx Engineer:

- Visual checked of device for Physical Damage or damage due to incorrect/ improper handling or wrong connections.
- Visual checked for any water damage.
- Device sent to Customer site after testing in R&D all function working fine.

**Problem Solved: YES** 

Needs any modification for better results: NO

**If YES Details** 

Specific Remarks form Customer: NO

# Conclusion:

The IFT-802TS15 has power failure Due to PCB issue (Manufacturing Defect) it get resolved by OEM by PCB repairing.