Configuration of serial to Ethernet (KSH) Model no: E-p732-x with Autonics temperature sensor Model no: THD-DD2-T

Communication parameter for temperature sensor

Interface = RS485

Baudrate = 9600

Parity = none

Stop bit = 1

Data bit =8

Serial to Ethernet (KSH) Model no: E-p732-x

Port-2


RS-485/422


Х	R-		
Χ	R+		
D-	T-		
D+	T+		

Connect the RS485 wire with D+ and D- for communication

Default IP: 192.168.0.100 log into the device

No need to Enter Password





For the communication with Modscan utility

Device id which: six (6)

Modbus point type: 04: INPUT REGISTER

ADDRESS: 0001

LENGH: 2

